

# HARBOUR MASTER'S REPORT

# <u>2014</u>

### for the

# HUMBER HARBOUR AREA



Introduction	3
ABP Pilots	5
Pilotage Exemptions Certificate Holders	6
Acts of Pilotage	7
Shipping Movements	8
Navigational Incidents	8
Graph of Vessels Reporting Defects	9
Defect (Ship) Reported	10
Graph of Reported Pilot Ladder Defects	20
Defect (Pilot Ladder) Reported	21
Anchorage Problems	25
Graph of Close Quarter (Near Miss) Occurances	26
Close Quarters Reports	27
Graph of Vessels Grounding but Not Refloating on the Same Tide	29
Summary of Groundings	
Graph of Vessels Making Contact With Seamarks	33
Contact with Sea Marks	
Graph of Vessels Making Contact With Structures	
Contact with Structures	
Graph of Vessels Making Contact With Other Vessels	39
Contact with Vessels	
Graph of Collision with Vessels	
Collisions with Vessels	
Summary of Bunker Operations at	43
Whitebooth Roads, Holme Ridge and Tetney Mono Buoy	
Debris etc. reported in River	
Distress and other flare Reports	
Failure to report to VTS	46
Summary of Fires Reported	
Fishing V/L Incidents	48
Graph of Vessels Reported for Proceeding At High Speed	49
Reports of High Speed	50
Lost and Fouled Anchors	
Summary of Low Water Berthing and Sailing Requests	52
Navigation Marks Damaged or Unreliable	53
Pollution Reports	
Graph of Vessels in Contravention of the Traffic Separation Scheme	58
Traffic Separation Scheme Contravention	59
Barge Movements passing under the Humber Bridge	60
Report of Bridge Jumpers	
Conservancy Activities	
Sunk Dredged Channel 2014	
Least Available Depths 2014	
Humber Dredging Summary 2014	
Harbour Craft	
Statutory Harbour Consents	
Daily Weather at 07:03	



#### Introduction

This report is intended to give the reader an overview of how ABP manages the navigational safety and conservancy of the Humber Harbour Area, and in relation to its obligations as a Statutory Harbour Authority and Competent Authority for the promotion of safety. The Humber continues to be the busiest estuary in the United Kingdom, in terms of tonnage handled, with some 13,205 inward shipping movements in 2014, giving rise to 29,219 vessel movements in total. In addition, there were 2875 recorded Oil Barge movements moving over 900 thousand tonnes of product between Immingham, Hull and upriver destinations. Latest available statistical figures indicate that in excess of 83.06 million tonnes of cargo and over 1.038 million passengers were handled.

In general shipping numbers remained in line with 2013 with a small growth recorded on the number of inbound vessels.


A number of proposed major projects moved closer to realisation at Greenport, Hull and ABLE Marine Energy Park at Killingholme. Towards the end of 2014 preparatory works also began on the replacement of the P66 subsea pipeline at Tetney.

The area of the Whittons experienced significant shoaling with channel migration and dredging frequency increased in the Sunk Dredged Channel on the approaches to Immingham.

On the 1st January 2015 Capt. A Firman will replace Capt. P Cowing as Harbour Master Humber and assume the role of head of department of Humber Estuary Services, which will continue to retain an independent statutory function within a wider ABP Humber Marine Department headed by Capt. Cowing. In line with the changes within the Humber Marine Department, early in 2015 the management and administrative functions of HES will relocate to Grimsby Port Office. Stakeholders will continue to be kept informed of any changes which affect them moving forward. To assist with this, an organisational chart of the new Humber Marine Department is shown overleaf.

Capt. A Firman Harbour Master Humber






#### **ABP Pilots**

The pilot complement as at end of 2014 is as follows:


VLS	21½
First Class	341⁄2
Second Class	281⁄2
Third Class	21½
Training	3
Total	109





#### **Pilotage Exemptions Certificate Holders**

As of December 2014, 165 Pilotage Exemptions Certificates are valid. This figure includes 31 Class C PECs issued to barge skippers.






#### Acts of Pilotage

The total number of pilotage acts carried out in the year was 15,750. The equivalent number for the year 2014 was 16,604.

The total number of PEC passages, other than barge PEC holders, carried out in the year, was 8,565. The equivalent number in 2013 was 8,070.





#### **Shipping Movements**

The total number of inward shipping movements during 2014 was 13,205 This can be broken down as follows:


#### 2014

Tetney Monobuoy	142
Grimsby	1257
Immingham	5380
Hull	3008
Goole	662
Humber Wharves	1850
Ouse Wharves	99
River Trent	807
Total	13205

### **Navigational Incidents**

Incident	2013	2014
Contact with vessel	4	5
Near Misses	9	9
Contact with structures	79	70
Contact with floating marks	1	5
Groundings, off in same tide	27	49
Groundings, remain over tide	11	8
Sub total	131	146
Defect (Ship)	246	188
Total	377	334







Date	Reported By	Ships	General Location
01-Jan Vessels bo	VTS 15 w thruster is inoperative.	TIGRIS	Chequer
Destinatior	n: Immingham oil terminal be	erthing 0530 1st January.	
02-Jan	VTS 15	DANIO	Brough
	ts that starboard engine has ilst repairs are carried out.	a water leak in the Lube Oil cooling syst	tem. Vessel is proceeding on one
Next port D			
04-Jan	AHM	VOS WARRIOR	Spurn L/F
		is working, but they have use of an Aqua be repaired in Alexandra dock, Hull on th	
		Alex Dk, advised by vessel that bow thru	
04-Jan	VTS 14	IYSHA	Sea Reach
		ich developed engine problems, returnin	g to fish dock for repairs. Grimsby fish
dock advis		rst lock on AM tide 05/01/14	
)6-Jan	PILOT	3 OAK	Imm Dk
		vessel has major engine problem in lock	and is "dead ship". Tugs ordered to
	rn to layby berth in Immingh		
)7-Jan Pilot report	PILOT	RMS SAIMAA essel berthing Immingham dock 1800/7th	
101 Tepon	VTS 14	WILSON MERSIN	Spurn Point
Bow Thrus	ter inoperative. ETA King G	eorge Dock 0400 11/1/14. No outward o	
20-Jan	VTS 15	SCOT CARRIER	Chequer
Pilot report 22-Jan	ts that the bow thruster is inc MASTER / CAPTAIN	pperative. Vessel bound for Grove wharf FRISIUM	. Spurn L/F
		land Pier. Engineers will attend on arriva	
one operat		to NHP. Radar will be repaired along will	
24-Jan	PILOT	ELSA ESSBERGER	Imm Dk
3ow thrust 27-Jan	er inoperative PILOT	SORMOVSKIY 3051	NH Dock
	-	error. Engineer organised at next port (R	
28-Jan	PILOT		
1429 Pilot nformed. S dispatched 1500 engir	reports outbound vessel suf Svitzer Laura already standii I immediately. Vessel stemm nes stopped (repairs ongoing		e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit.
1429 Pilot nformed. S dispatched 1500 engir 1537 temp HMCG adv	reports outbound vessel suf Svitzer Laura already standii I immediately. Vessel stemm nes stopped (repairs ongoing orary fix completed, vessel vised. Duty Manager advised	fering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the ning with tugs fast in the deep water app g) proceeding out to 5' N to affect permane d.	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit.
1429 Pilot informed. S dispatched 1500 engir 1537 temp HMCG adv 2244 v/l ad 29-Jan	reports outbound vessel suf Svitzer Laura already standin I immediately. Vessel stemm nes stopped (repairs ongoing orary fix completed, vessel vised. Duty Manager advised dvises that all fixed and now VTS 14	fering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the ning with tugs fast in the deep water app g) proceeding out to 5' N to affect permane d. proceeding on passage. AMBER TRADER	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit.
1429 Pilot nformed. S dispatched 1500 engir 1537 temp HMCG adv 2244 v/l ad 29-Jan Vessel dep 0445 Powe 0320 Svitz 0440 Susa	reports outbound vessel suf Svitzer Laura already standin I immediately. Vessel stemm hes stopped (repairs ongoing orary fix completed, vessel vised. Duty Manager advised vises that all fixed and now VTS 14 parting IBT lost power to eng er regained but unreliable. T er Madeleine released. Sust in stood down. Vessel bound leparts VTS area.	fering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the ning with tugs fast in the deep water app proceeding out to 5' N to affect permane d. proceeding on passage. AMBER TRADER gine, Svitzer Madeleine standing by. ug made fast. Pilot request tug escort pa an remaining with the vessel.	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit. nt repair, engine will be disabled.
1429 Pilot nformed. \$ dispatched 1500 engir 1537 temp HMCG adv 2244 v/l ad 29-Jan /essel dep 0445 Powe 0320 Svitz 0440 Susa 0600 V/L d 29-Jan	reports outbound vessel suf Svitzer Laura already standin i immediately. Vessel stemm hes stopped (repairs ongoing orary fix completed, vessel vised. Duty Manager advised vises that all fixed and now VTS 14 oarting IBT lost power to eng er regained but unreliable. T er Madeleine released. Sust in stood down. Vessel bound leparts VTS area. MASTER / CAPTAIN	fering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the ning with tugs fast in the deep water app g) proceeding out to 5' N to affect permane d. proceeding on passage. AMBER TRADER jine, Svitzer Madeleine standing by. ug made fast. Pilot request tug escort pa an remaining with the vessel. d for Jelsa (Norway). THAMES FISHER	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit. nt repair, engine will be disabled. IBT ast IOT. Svitzer Susan also standing by Humber
1429 Pilot nformed. \$ dispatched 1500 engir 1537 temp HMCG adv 2244 v/l ad 29-Jan /essel dep 0445 Powe 0320 Svitz 0440 Susa 0600 V/L d 29-Jan Dn passing	reports outbound vessel suf Svitzer Laura already standin immediately. Vessel stemm hes stopped (repairs ongoing orary fix completed, vessel vised. Duty Manager advised vises that all fixed and now VTS 14 oarting IBT lost power to eng er regained but unreliable. T er Madeleine released. Sust in stood down. Vessel bound leparts VTS area. MASTER / CAPTAIN g North Binks buoy, experien	fering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the ning with tugs fast in the deep water app g) proceeding out to 5' N to affect permane d. proceeding on passage. AMBER TRADER jine, Svitzer Madeleine standing by. ug made fast. Pilot request tug escort pa an remaining with the vessel. d for Jelsa (Norway).	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit. nt repair, engine will be disabled. IBT ast IOT. Svitzer Susan also standing by Humber
1429 Pilot nformed. \$ dispatched 1500 engir 1537 temp 1MCG adv 2244 v/l ad 29-Jan /essel dep 0445 Powe 0320 Svitz 0440 Susa 0600 V/L d 29-Jan On passing OT advise	reports outbound vessel suf Svitzer Laura already standin immediately. Vessel stemm hes stopped (repairs ongoing orary fix completed, vessel vised. Duty Manager advised vises that all fixed and now VTS 14 oarting IBT lost power to eng er regained but unreliable. T er Madeleine released. Sust in stood down. Vessel bound leparts VTS area. MASTER / CAPTAIN g North Binks buoy, experien	fering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the ning with tugs fast in the deep water app g) proceeding out to 5' N to affect permane d. proceeding on passage. AMBER TRADER jine, Svitzer Madeleine standing by. ug made fast. Pilot request tug escort pa an remaining with the vessel. d for Jelsa (Norway). THAMES FISHER need engine problems and aborted pass	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit. nt repair, engine will be disabled. IBT ast IOT. Svitzer Susan also standing by Humber
429 Pilot formed. \$ lispatched 500 engir 537 temp IMCG adv 2244 v/l ad 29-Jan Vessel dep 0445 Powe 0320 Svitz 0440 Susa 0600 V/L d 29-Jan On passing OT advise 815 vesse 2015 V/L a	reports outbound vessel suf Svitzer Laura already standin immediately. Vessel stemm hes stopped (repairs ongoing orary fix completed, vessel vised. Duty Manager advised vised. Duty Manager advised vises that all fixed and now VTS 14 Darting IBT lost power to eng er regained but unreliable. T er Madeleine released. Sust in stood down. Vessel bound leparts VTS area. MASTER / CAPTAIN g North Binks buoy, experier ad. el underway proceeding to the anchored in Bull anchorage (	fering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the ning with tugs fast in the deep water app g) proceeding out to 5' N to affect permane d. proceeding on passage. AMBER TRADER jine, Svitzer Madeleine standing by. ug made fast. Pilot request tug escort pa an remaining with the vessel. d for Jelsa (Norway). THAMES FISHER need engine problems and aborted pass he Bull anchorage. EX2) awaiting shore side engineers to a	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit. nt repair, engine will be disabled. IBT ast IOT. Svitzer Susan also standing by Humber age to Humber Deep Water anchorage ttend.
429 Pilot nformed. \$ dispatched 500 engir 537 temp HMCG adv 2244 v/l ad 29-Jan /essel dep 0445 Powe 0320 Svitz 0320 Svitz 0320 Svitz 0440 Susa 6000 V/L d 29-Jan On passing OT advise 815 vesse 2015 V/L a 30-Jan	reports outbound vessel suf Svitzer Laura already standin immediately. Vessel stemm hes stopped (repairs ongoing orary fix completed, vessel vised. Duty Manager advised vises that all fixed and now VTS 14 vTS 14 Darting IBT lost power to eng er regained but unreliable. T er Madeleine released. Sust in stood down. Vessel bound leparts VTS area. MASTER / CAPTAIN g North Binks buoy, experier ed. el underway proceeding to to anchored in Bull anchorage ( PILOT	fering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the ning with tugs fast in the deep water app g) proceeding out to 5' N to affect permane d. proceeding on passage. AMBER TRADER gine, Svitzer Madeleine standing by. ug made fast. Pilot request tug escort pa an remaining with the vessel. d for Jelsa (Norway). THAMES FISHER need engine problems and aborted pass he Bull anchorage. EX2) awaiting shore side engineers to a KARINA G	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit. nt repair, engine will be disabled. IBT ast IOT. Svitzer Susan also standing by Humber age to Humber Deep Water anchorage
429 Pilot nformed. \$ dispatched 500 engir 537 temp HMCG adv 2244 v/l ad 29-Jan /essel dep 0445 Powe 0320 Svitz/ 0440 Susa 0600 V/L d 29-Jan On passing OT advise 815 vesse 2015 V/L a 30-Jan Bow thrust	reports outbound vessel suf Svitzer Laura already standin immediately. Vessel stemm hes stopped (repairs ongoing orary fix completed, vessel vised. Duty Manager advised vises that all fixed and now VTS 14 vorting IBT lost power to eng er regained but unreliable. T er Madeleine released. Sust in stood down. Vessel bound leparts VTS area. MASTER / CAPTAIN g North Binks buoy, experier ed. el underway proceeding to the anchored in Bull anchorage ( PILOT er not working. KGD advise	fering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the ning with tugs fast in the deep water app g) proceeding out to 5' N to affect permane d. proceeding on passage. AMBER TRADER gine, Svitzer Madeleine standing by. ug made fast. Pilot request tug escort pa an remaining with the vessel. d for Jelsa (Norway). THAMES FISHER need engine problems and aborted pass he Bull anchorage. EX2) awaiting shore side engineers to a KARINA G	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit. nt repair, engine will be disabled. IBT ast IOT. Svitzer Susan also standing by Humber age to Humber Deep Water anchorage ttend.
429 Pilot nformed. § lispatched 500 engir 537 temp IMCG adv 2244 v/l ad 29-Jan /essel dep 0445 Powe 0320 Svitza 0440 Susa 0320 Svitza 0440 Susa 050 V/L d 29-Jan On passing OT advise 815 vesse 815 vesse 815 vesse 80-Jan 30-Jan 30-Jan 30-Jan 30-Jan	reports outbound vessel suf Svitzer Laura already standin immediately. Vessel stemm hes stopped (repairs ongoing orary fix completed, vessel vised. Duty Manager advised vises that all fixed and now VTS 14 vot 14 vot 15 14 vot 16 power to eng er regained but unreliable. T er Madeleine released. Sust in stood down. Vessel bound leparts VTS area. MASTER / CAPTAIN g North Binks buoy, experier ad. el underway proceeding to the anchored in Bull anchorage ( PILOT er not working. KGD advise ADM IMM ered lock ready for departur	tering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the ning with tugs fast in the deep water app g) proceeding out to 5' N to affect permane d. proceeding on passage. AMBER TRADER gine, Svitzer Madeleine standing by. ug made fast. Pilot request tug escort pa an remaining with the vessel. d for Jelsa (Norway). THAMES FISHER need engine problems and aborted pass he Bull anchorage. EX2) awaiting shore side engineers to a KARINA G d SWIFT e and was denied clearance due traffic o	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit. nt repair, engine will be disabled. IBT ast IOT. Svitzer Susan also standing by Humber age to Humber Deep Water anchorage ttend. Spurn Point Imm Dk off Immingham. The ADM telephoned
429 Pilot formed. S lispatched 500 engir 537 temp IMCG adv 2244 v/l ad 29-Jan 2045 Powe 320 Svitz 320 Svitz 32	reports outbound vessel suf Svitzer Laura already standin I immediately. Vessel stemm hes stopped (repairs ongoing orary fix completed, vessel vised. Duty Manager advised dvises that all fixed and now VTS 14 Dearting IBT lost power to eng er regained but unreliable. T er Madeleine released. Suss in stood down. Vessel bound leparts VTS area. MASTER / CAPTAIN g North Binks buoy, experier ed. el underway proceeding to the anchored in Bull anchorage ( PILOT er not working. KGD advise ADM IMM ered lock ready for departur vise that the vessel was retu	fering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the ning with tugs fast in the deep water app g) proceeding out to 5' N to affect permane d. proceeding on passage. AMBER TRADER gine, Svitzer Madeleine standing by. ug made fast. Pilot request tug escort pa an remaining with the vessel. d for Jelsa (Norway). THAMES FISHER need engine problems and aborted pass he Bull anchorage. EX2) awaiting shore side engineers to a KARINA G d	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit. nt repair, engine will be disabled. IBT ast IOT. Svitzer Susan also standing by Humber age to Humber Deep Water anchorage ttend. Spurn Point Imm Dk off Immingham. The ADM telephoned
429 Pilot nformed. S dispatched 500 engir 537 temp HMCG adv 2244 v/l ad 29-Jan /445 Powe 320 Svitz 0440 Susa 0600 V/L d 29-Jan Dn passing OT advise 815 vesse 815 vesse 015 V/L a 30-Jan 30-Jan 30-Jan 30-Feb /essel entr /TS to adv pefore dep	reports outbound vessel suf Svitzer Laura already standin immediately. Vessel stemm hes stopped (repairs ongoing orary fix completed, vessel vised. Duty Manager advised vises that all fixed and now VTS 14 Darting IBT lost power to eng er regained but unreliable. T er Madeleine released. Sust in stood down. Vessel bound leparts VTS area. MASTER / CAPTAIN g North Binks buoy, experier ad. el underway proceeding to the anchored in Bull anchorage ( PILOT er not working. KGD advise ADM IMM ered lock ready for departur vise that the vessel was reture.	fering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the ning with tugs fast in the deep water appi- g) proceeding out to 5' N to affect permane d. proceeding on passage. AMBER TRADER jine, Svitzer Madeleine standing by. ug made fast. Pilot request tug escort pa an remaining with the vessel. d for Jelsa (Norway). THAMES FISHER need engine problems and aborted pass he Bull anchorage. EX2) awaiting shore side engineers to a KARINA G SWIFT e and was denied clearance due traffic or rning to her berth as she had engine pro	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit. nt repair, engine will be disabled. IBT ast IOT. Svitzer Susan also standing by Humber age to Humber Deep Water anchorage ttend. Spurn Point Imm Dk off Immingham. The ADM telephoned oblems. Vessel had repairs carried out
429 Pilot formed. S lispatched 500 engir 537 temp HMCG adv 2244 v/l ad 29-Jan 2045 Powe 320 Svitz 320 Svitz 32	reports outbound vessel suf Svitzer Laura already standin immediately. Vessel stemm hes stopped (repairs ongoing orary fix completed, vessel vised. Duty Manager advised dvises that all fixed and now VTS 14 Dearting IBT lost power to eng er regained but unreliable. T er Madeleine released. Suss in stood down. Vessel bound leparts VTS area. MASTER / CAPTAIN g North Binks buoy, experier anchored in Bull anchorage ( PILOT er not working. KGD advise ADM IMM ered lock ready for departur vise that the vessel was reture anture. MASTER / CAPTAIN	tering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the ning with tugs fast in the deep water app g) proceeding out to 5' N to affect permane d. proceeding on passage. AMBER TRADER gine, Svitzer Madeleine standing by. ug made fast. Pilot request tug escort pa an remaining with the vessel. d for Jelsa (Norway). THAMES FISHER need engine problems and aborted pass he Bull anchorage. EX2) awaiting shore side engineers to a KARINA G d SWIFT e and was denied clearance due traffic o	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit. nt repair, engine will be disabled. IBT ast IOT. Svitzer Susan also standing by Humber age to Humber Deep Water anchorage ttend. Spurn Point Imm Dk off Immingham. The ADM telephoned blems. Vessel had repairs carried out
1429 Pilot Informed. S dispatched 1500 engir 1537 temp HMCG adv 2244 v/l ad 29-Jan /essel dep 0445 Powe 0320 Svitz 1440 Susa 0600 V/L d 29-Jan On passing OT advise 815 vesse 2015 V/L a 20-Jan On passing OT advise 815 vessel 2015 V/L a 20-Jan 30-Jan 30-Jan 30-Jan 30-Jan 10-Jan 30-Jan 10-Jan 30-Jan 10-J	reports outbound vessel suf Svitzer Laura already standin immediately. Vessel stemm hes stopped (repairs ongoing orary fix completed, vessel vised. Duty Manager advised vises that all fixed and now VTS 14 oarting IBT lost power to eng er regained but unreliable. T er Madeleine released. Sus: in stood down. Vessel bound leparts VTS area. MASTER / CAPTAIN g North Binks buoy, experier ed. el underway proceeding to the anchored in Bull anchorage ( PILOT er not working. KGD advise ADM IMM ered lock ready for departur vise that the vessel was retu- narture. MASTER / CAPTAIN ports engine problems, vesse ares engine problem rectifier- el suffers further mechanica- ning cancelled for this tide.	tering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the hing with tugs fast in the deep water app proceeding out to 5' N to affect permane d. proceeding on passage. AMBER TRADER gine, Svitzer Madeleine standing by. ug made fast. Pilot request tug escort pa an remaining with the vessel. d for Jelsa (Norway). THAMES FISHER need engine problems and aborted pass he Bull anchorage. EX2) awaiting shore side engineers to a KARINA G d SWIFT e and was denied clearance due traffic of rning to her berth as she had engine pro NAJADE sel anchors in position in DWA position J d proceeding to pilot boarding station. I problems and anchors 8 cables SSE of	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit. nt repair, engine will be disabled. IBT ast IOT. Svitzer Susan also standing by Humber age to Humber Deep Water anchorage ttend. Spurn Point Imm Dk off Immingham. The ADM telephoned oblems. Vessel had repairs carried out DWA f South Sand buoy.
1429 Pilot nformed. § dispatched 1500 engir 1537 temp HMCG adv 2244 v/l ad 29-Jan Vessel dep 0445 Powe 0320 Svitz 0440 Susa 0600 V/L d 29-Jan On passing OT advise 1815 vesse 2015 V/L a 30-Jan Bow thrust 03-Feb Vessel entiv VFS to adv pefore dep 03-Feb Captain rep 1700 Decla 1720 Vess 1745 Berth 1758 Capta	reports outbound vessel suf Svitzer Laura already standin immediately. Vessel stemm hes stopped (repairs ongoing orary fix completed, vessel vised. Duty Manager advised vised. Duty Manager advised vises that all fixed and now VTS 14 or regained but unreliable. T er Madeleine released. Sust in stood down. Vessel bound leparts VTS area. MASTER / CAPTAIN g North Binks buoy, experier ed. el underway proceeding to the unchored in Bull anchorage ( PILOT er not working. KGD advise ADM IMM ered lock ready for departur vise that the vessel was retu- varture. MASTER / CAPTAIN ports engine problems, vess ares engine problem rectifier- el suffers further mechanica- ning cancelled for this tide. ain informs problem with fue	tering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the hing with tugs fast in the deep water app proceeding out to 5' N to affect permane d. proceeding on passage. AMBER TRADER gine, Svitzer Madeleine standing by. ug made fast. Pilot request tug escort pa an remaining with the vessel. d for Jelsa (Norway). THAMES FISHER need engine problems and aborted pass he Bull anchorage. EX2) awaiting shore side engineers to a KARINA G d SWIFT e and was denied clearance due traffic of rning to her berth as she had engine pro- lef anchors in position in DWA position J d proceeding to pilot boarding station. I problems and anchors 8 cables SSE of el pump, repair will take approximately 2	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit. nt repair, engine will be disabled. IBT ast IOT. Svitzer Susan also standing by Humber age to Humber Deep Water anchorage ttend. Spurn Point Imm Dk off Immingham. The ADM telephoned oblems. Vessel had repairs carried out DWA f South Sand buoy. hours.
1429 Pilot nformed. § dispatched 1500 engir 1537 temp HMCG adv 2244 v/l ad 29-Jan Vessel dep 0445 Powe 0320 Svitz 0440 Susa 0600 V/L d 29-Jan On passing OT advise 1815 vesse 2015 V/L a 30-Jan Bow thrust 03-Feb Vessel ent VTS to adv before dep 03-Feb Captain rep 1700 Decla 1720 Vess 1745 Berth 1758 Capta	reports outbound vessel suf Svitzer Laura already standin immediately. Vessel stemm hes stopped (repairs ongoing orary fix completed, vessel vised. Duty Manager advised vised. Duty Manager advised vises that all fixed and now VTS 14 or regained but unreliable. T er Madeleine released. Sust in stood down. Vessel bound leparts VTS area. MASTER / CAPTAIN g North Binks buoy, experier ed. el underway proceeding to the unchored in Bull anchorage ( PILOT er not working. KGD advise ADM IMM ered lock ready for departur vise that the vessel was retu- varture. MASTER / CAPTAIN ports engine problems, vess ares engine problem rectifier- el suffers further mechanica- ning cancelled for this tide. ain informs problem with fue	tering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the hing with tugs fast in the deep water app proceeding out to 5' N to affect permane d. proceeding on passage. AMBER TRADER gine, Svitzer Madeleine standing by. ug made fast. Pilot request tug escort pa an remaining with the vessel. d for Jelsa (Norway). THAMES FISHER need engine problems and aborted pass he Bull anchorage. EX2) awaiting shore side engineers to a KARINA G d SWIFT e and was denied clearance due traffic of rning to her berth as she had engine pro NAJADE sel anchors in position in DWA position J d proceeding to pilot boarding station. I problems and anchors 8 cables SSE of	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit. nt repair, engine will be disabled. IBT ast IOT. Svitzer Susan also standing by Humber age to Humber Deep Water anchorage ttend. Spurn Point Imm Dk off Immingham. The ADM telephoned oblems. Vessel had repairs carried out DWA f South Sand buoy. hours. ck.
1429 Pilot Informed. § dispatched 1500 engir 1537 temp HMCG adv 2244 v/l ad 29-Jan /essel dep 0445 Powe 0445 Powe 045	reports outbound vessel suf Svitzer Laura already standin immediately. Vessel stemm hes stopped (repairs ongoing orary fix completed, vessel vised. Duty Manager advised vised. Duty Manager advised vises that all fixed and now VTS 14 Darting IBT lost power to eng- er regained but unreliable. T er Madeleine released. Sust in stood down. Vessel bound eparts VTS area. MASTER / CAPTAIN g North Binks buoy, experier ed. el underway proceeding to the anchored in Bull anchorage ( PILOT ter not working. KGD advise ADM IMM ered lock ready for departur vise that the vessel was retu- nature. MASTER / CAPTAIN ports engine problem s, vess ares engine problems, vess ares engine problems, vess ares engine problem vectifier el suffers further mechanica ing cancelled for this tide. ain informs problem with fue ain informs problem with fue ain informs repairs complete PILOT following bridge equipment	fering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the hing with tugs fast in the deep water apping)         proceeding out to 5' N to affect permane d.         proceeding on passage.         AMBER TRADER         gine, Svitzer Madeleine standing by.         ug made fast. Pilot request tug escort paran remaining with the vessel.         d for Jelsa (Norway).         THAMES FISHER         nced engine problems and aborted pass         he Bull anchorage.         EX2) awaiting shore side engineers to a         KARINA G         d         g roceeding to pilot boarding station.         l proceeding to pilot boarding station.         l problems and anchors 8 cables SSE of         e and was denied clearance due traffic or         ring to her berth as she had engine pro         Lee anchors in position in DWA position J         d proceeding to pilot boarding station.         l problems and anchors 8 cables SSE of         et pump, repair will take approximately 2         e. Vessel berthing 0915 New Holland Do         CASABLANCA         defects, the pilot has declared that it is u	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit. nt repair, engine will be disabled. IBT ast IOT. Svitzer Susan also standing by Humber age to Humber Deep Water anchorage ttend. Spurn Point Imm Dk off Immingham. The ADM telephoned blems. Vessel had repairs carried out DWA f South Sand buoy. hours. ck. Spurn Point unsafe to proceed to Goole on this nigh
1429 Pilot nformed. S dispatched 1500 engir 1537 temp HMCG adv 2244 v/l ad 29-Jan Vessel dep 0445 Powe 0320 Svitz 0440 Susa 0600 V/L d 29-Jan On passing OT advise 1815 vesse 2015 V/L a 30-Jan Bow thrust 03-Feb Vessel entr VTS to adv pefore dep 03-Feb Captain rep 1745 Berth Captain rep 1758 Capta 2225 Capta 05-Feb Due to the ide and re range; GPS	reports outbound vessel suf Svitzer Laura already standin immediately. Vessel stemm hes stopped (repairs ongoing orary fix completed, vessel j vised. Duty Manager advised dvises that all fixed and now VTS 14 Dearting IBT lost power to eng er regained but unreliable. T er Madeleine released. Suss in stood down. Vessel bound leparts VTS area. MASTER / CAPTAIN g North Binks buoy, experier anchored in Bull anchorage ( PILOT er not working. KGD advise ADM IMM ered lock ready for departur vise that the vessel was reture. MASTER / CAPTAIN ports engine problem s, vess ares engine problem s, vess ares engine problem s, vess ares engine problem with fue ain informs repairs complete PILOT following bridge equipment commends a daylight passa	fering engine problems whilst abeam of ng by and Svitzer Trimley recalled by the ning with tugs fast in the deep water apping)         proceeding out to 5' N to affect permane d.         proceeding on passage.         AMBER TRADER         jine, Svitzer Madeleine standing by.         ug made fast. Pilot request tug escort paran remaining with the vessel.         d for Jelsa (Norway).         THAMES FISHER         nccd engine problems and aborted pass         he Bull anchorage.         EX2) awaiting shore side engineers to a         KARINA G         d         SWIFT         e and was denied Clearance due traffic c         rning to her berth as she had engine pro         I NAJADE         sel anchors in position in DWA position J         d proceeding to pilot boarding station.         l problems and anchors 8 cables SSE of         e pump, repair will take approximately 2         e. Vessel berthing 0915 New Holland Door         CASABLANCA         defects, the pilot has declared that it is u         uge only. Defects: Poor radar picture - un         es; sizable difference between magnetic	IOT 1. IOT and Immingham Dock e ship. Fire Tug Svitzer Susan rox. 1nm due west of Sunk Spit. nt repair, engine will be disabled. IBT ast IOT. Svitzer Susan also standing by Humber age to Humber Deep Water anchorage ttend. Spurn Point Imm Dk off Immingham. The ADM telephoned blems. Vessel had repairs carried out DWA f South Sand buoy. hours. ck. Spurn Point Insafe to proceed to Goole on this nigh hable to pick out buoys at adequate



Γ

Date	Reported By	Ships	General Location
lock aware	e. River boadcast made.		
	anchor 0725 Svitzer Josep		
		der to proceed to Immingham dock.	
	er Bristol proceeding. Ancho nd tug in attendance and v/l		
	ecure in Imm lock.	continuing to the look.	
7-Feb	PILOT	DANIO	Chequer
		ngine stopped due to unknown defect. Ve	ssel proceeding on one engine. Pilot
	essel still manoeuvrable and		-
330 vesse 5/02/15 A		eports defect will be rectified before sailing	g.
8-Feb	PILOT	OSTEREMS	Spurn Point
ilot report	s automatic pilot not working	g. Vessels destination Delfzl.	
9-Feb	PILOT	DANIO	Brough
		d. Cargo steel products. KGD offered as a	
		be which has now been repaired. Vessel b	back on 2 engines.
iext port F 0-Feb	Rotterdam	MARCHICORA	KGD
		<ul> <li>Pilot reports stbd anchor windlass defection</li> </ul>	-
0-Feb	VTS 15	HARM JOHANNES	New Sand Hole
		TS area. AIS defective. (MMSI 235003424	
onstraine	d by draught in a TSS by pa	ssing close ahead of her and had to be di	
	on two occasions.		
0-Feb	VTS 14	FREJ	Sea Reach
	orts a problem with fuel inje	ction pump approximately 3 miles SE of C	Nor and intends to drift while
		has now been resolved and is proceeding	on passage. Next port Velsen.
3-Feb	VTS 15	RMS RUHRORT	Upper Humber
IS not tra	nsmitting but pilot reports th	at the unit is receiving correctly. Vessel or	utbound, next port Rotterdam.
4-Feb	MASTER / CAPTAIN	BIRCH 5	Humber
		dar. Master states technicians arranged fo	or arrival King George Dock.
0	GD at 0500. 25/02/14 Rada		L humahan
16-Feb	VTS 14	and awaiting berth availability at Immingh	Humber Nam Oil Terminal
	orts AIS is to be repaired w		iam on reminal.
7-Feb	PILOT	ARESSA	Imm Dk Bellmouth
One radar	inoperative, second radar po	oor performance -difficulty displaying navi	gation marks. Bow thruster
		nths' notice to resolve defects after PSC	
7-Feb	PILOT	FRI PORSGRUNN	Spurn L/F
7-Feb	er inoperative VTS 14	КІТТҮ С	Humbor
		am 2359 17/02/014. No outward orders a	Humber
8-Feb		AVALON	Spurn Point
	-	t not retrieve. This defect was first reported	
hat the wi		me in Goole. This is the vessels first visit	since 12/01/13.
9-Feb	SMS TUGS	TRADESMAN	WBR
		er. Tug Norman proceeding from KGD an	d tug Englishman from E/J to assist.
	Norman in attendance in the r tow by tug Norman, proce		
	ed KGD Hull.		
0-Feb	PILOT	ELYTIS	Imm Dk
	s inoperative bow thruster.		
		now operational while passing the Upper I	
3-Feb	VTS 15	SHANNON STAR	Spurn L/F
		er buoy, the auto lube oil alarm for the ma deep water anchorage to investigate.	iin engine keeps sounding. Vessel
		is engines will not be immobilised expects	repairs to take two hours.
		stination. Destination: Le Harve	
4-Feb	PILOT	REMORA	Chequer
		perative and that the river radar is fully ope	erational.
	h: Flixborough berthing 0145		
6-Feb	PILOT	MARE BALTIC	Spurn L/F
vhile along		ng. Vessel berthing IOT 2 at 1545. Captai	IT declares defect will not de fixed
1-Mar	VTS 15	MARGARETHA	Goole
		orts complete loss of engine power off Oc	
735 Vess	el anchored. Tug 'Little Shu	va' being mobilised to assist.	
		an an a bha an	
	ne power restored recovering. Shuva' assisting.	g anchor.	

Date	Reported By	Ships	General Location
	st in Ocean Lock, Goole	•	
01-Mar	PILOT	FAST SUS s and is reducing to slow ahead. Due to proxin	Foul Holme
standby. 2000 Vess 2010 - Ves	el reports the defect as high sel clears IOT, Fire tug stoo	exhaust gas temperatures. ad down. 2020 Pilot reports that the problem w	
Exhaust te 01-Mar	mperatures normal. PILOT	WILSON LUBECK	Bull
Pilot report ETA H'Dyk		nician to attend on arrival Howdendyke.	
05-Mar	PILOT	REYKJAFOSS	Imm Dk
		t water is coming from the bulbous bow approx	
Vessel due	nanager advised & duty MC to sail from Immingham DF have cleared the vessel to		ng.
05-Mar	MASTER / CAPTAIN	CHEMBULK SHANGHI	Humber
Outer Sand Vessel ber			ns. Vessel anchored 2nm north of
07-Mar	PILOT	FLINTERHAVEN	Spurn Bight
	s bow thruster defective. Ve MASTER / CAPTAIN	essel taking tug for berthing.	Roose Roose
09-Mar		approaching the TSS developed pitch propell	Rosse Reach
Agent advi Berthing tir 0730 Mast 11-Mar Master rep	sed and vessel re-ordered f ne 1315. er declares defects rectified VTS 15 orts that the Gyro compass	STOLT RAZORBILL is inoperative. The problem is due to be rectif	
14-Mar	PILOT E problems (blocked fuel lin		Ridge
0345 Anch 0445 Repa	ored between buoys 7A & S irs complete rway and resuming outward PILOT	to effect repairs	Spurn L/F
		nation: King George dock 10 quay berthing 17	
Master adv	vises will be repaired alongs	ide.	
18-Mar Master rep	VTS 15	COPERNICUS steering gear pumps is inoperative.	Humber
		vessel from the IOT to KGD, as a precaution.	KGD ADM advised.
18-Mar	PILOT	HENG SHAN	HIT
five other n 2050 Duty 2100 Three replacemend dismissed.	nooring lines have recently manager informed e tugs to remain in attendan nt mooring lines. Vessel has	erth on HIT2, one of the vessel's spring lines been spliced and are in a poor condition. ce until at least low water, pilots to remain on- s only three lines ashore and is unable to discl	board. Agent is trying to arrange harge cargo until the tugs are
19-Mar	PILOT	SNOWLARK	Goole
0830 Áll fa repair. ETE 1400 Maste	st Blacktoft. The problem ap D Blacktoft 1800 19/03/14 to er cancels sailing order awa	hat the ship has engine problems and is proce opears to be damage to the cylinder valves, wi o Great Yarmouth, subject to repairs. hiting MCA inspection. a pilot has been ordered for 1900 20th and tw	ill take at least three hours to
21-Mar	PILOT	PETR VELIKIY	Spurn L/F
Berthing K	GD 21st 2000. No ETD	icking up targets with any clarity. In particular	the buoys are hard to detect.
24-Mar	VTS 15	STEENBANK	GY Royal
Pilot report 25-Mar	s that the Bow thruster is in VTS 14	operative. V/L bound for Rotterdam. B GAS ETTRICK	Spurn Point
Pilot report failure on n 0851Vesse 0850 Agen 0909 Vess	s serious engine failure out nain engine. Vessel expecte el drifting into Bull anchorag t contacted to arrange stan el anchored position Kilo.	bound in the vicinity of the Hobo buoy. Autome ed to be dead ship for several hours. e to anchor. All ships securite broadcast made	atic stop activated by cylinder e Ch 12 and 14.
	Nap departs Grimsby to star		



Date	Reported By	Ships	General Location
	or aweigh proceeding to sea for		Ceneral Ecolution
25-Mar	PILOT	NOR FEEDER	Imm Dk
Gyro comp	ass not feeding into autopilot.	Destination: Felixstowe	
27-Mar	VTS 15	SPLITTNES	Spurn L/F
		ts that one of two radars is inoperative.	
01-Apr Bowy thrust	PILOT	HELAS	Spurn L/F
02-Apr	er inoperative. Vessel bound N	TERA	Hawke
		s that the vessel has lost all engine and elec	
1912 Powe	er restored.	-	
		o New Holland due to dense fog, poor rada	video display, inaccurate gyro
and magne 03-Apr	etic compasses. PILOT	MOSELDIJK	Imm Dk
	s gyro faulty intention to repair		
		el will now have its gyro repaired in Rotterd	am. ETD Imm PM 05/04/14
04-Apr	VTS 15	STOLT SHEARWATER	Sea Reach
		problems in the inward lane of the Sea Re	ach TSS and is not under
command. 1227 Pilot	All ships broadcast made.		
		m. Master/pilot happy to proceed to Salt en	d jetty. Pier master advised
	500 SEJ 1. No sailing orders a	t present	, , ,
04-Apr	VTS 15	ORIENT SUN	Sunk Spit
		een showing an increasing error during the	passage from the Humber light
	now 25 degrees from true. Cre reports that crew have switche	ew attempting to rectify. d to secondary gyro and that gyro headings	are now satisfactory
06-Apr	VTS 15	RYSTRAUM	Humber
	orts losing his port anchor in D	eep water anchorage position 'C'. Vessel b	ound to Salt End Jetty.
12-Apr	MASTER / CAPTAIN	SEA MELODY	Humber
	ports defective gyro, vessel du		
12-Apr	VTS 12	BF FORTALEZA	Imm Dk
		ost all power in Immingham Dock. nd tug to berth. No damage reported. 2340	All fast
13-Apr	VTS15	SEA MELODY	Chequer
	s that the gyro compass is ino		eneque:
13-Apr	VTS 15	PEAK BERGEN	Chequer
	s that the bow thruster is inope		
16-Apr		EBROBORG	Spurn L/F
Bow thrust 17-Apr	er inoperative - one tug ordere VTS 15		Spurn L/F
		bound for KGD. ETA PM/17th.	opun En
19-Apr	PILOT	CRISTINA	Upper Humber
Vessel out	bound to Figueira da Foz. Pilo	t reports main engine cooling problems.	
	el has isolated problem and co	<u> </u>	
19-Apr	MASTER / CAPTAIN		Humber
	before proceeding up river.	ports steering pump problems. Vessel to an	ichor in deep water anchorage to
		/essel to berth Grove LE1 19/04/14 2200.	
22-Apr	PILOT	WARNOW STAR	IOT
		orts that the Gyro compass has a large erro	r
	reports that the gyro error has	now been rectified. CELTIC VENTURE	Spurn L/F
20_0nr			
	w thruster is inonerative liet		
Vessels bo	w thruster is inoperative. Desti VTS 15	OPALINE	IOT
/essels bo 30-Apr	VTS 15		-
30-Apr Vessel in p but that the	VTS 15 vosition between 9A buoy and l by were now resolved. He was	<b>OPALINE</b> OT no.3: Master (PEC No.1129): reports th however making his two tugs fast for passir	at he was having engine problem ng IOT. From Master: This is a
Vessels bo 30-Apr Vessel in p out that the recurrence	VTS 15 osition between 9A buoy and I ey were now resolved. He was of a problem with the cranksh	<b>OPALINE</b> OT no.3: Master (PEC No.1129): reports th however making his two tugs fast for passin aft that was thought to have been resolved	at he was having engine problem ng IOT. From Master: This is a before leaving the last port.
Vessels bo 30-Apr Vessel in p but that the recurrence Master has	VTS 15 osition between 9A buoy and l ey were now resolved. He was of a problem with the cranksh s been advised that he will be r	<b>OPALINE</b> OT no.3: Master (PEC No.1129): reports th however making his two tugs fast for passir	at he was having engine problem ng IOT. From Master: This is a before leaving the last port.
Vessels bo 30-Apr Vessel in p but that the ecurrence Master has been fully r	VTS 15 osition between 9A buoy and l ey were now resolved. He was of a problem with the cranksh s been advised that he will be r	<b>OPALINE</b> OT no.3: Master (PEC No.1129): reports th however making his two tugs fast for passin aft that was thought to have been resolved	at he was having engine problem ng IOT. From Master: This is a before leaving the last port.
Vessels bo 30-Apr Vessel in p but that the recurrence Master has been fully r 30-Apr	VTS 15 osition between 9A buoy and l ey were now resolved. He was of a problem with the cranksh been advised that he will be r resolved. VTS 14	<b>OPALINE</b> OT no.3: Master (PEC No.1129): reports th however making his two tugs fast for passin aft that was thought to have been resolved equired to have a two tug escort when pass	at he was having engine problem ng IOT. From Master: This is a before leaving the last port. sing IOT until the problem has Spurn Point
Vessels bo 30-Apr Vessel in p but that the recurrence Master has been fully r 30-Apr 2230 Tug i 2309 Vess	VTS 15 osition between 9A buoy and l ey were now resolved. He was of a problem with the cranksh been advised that he will be r resolved. VTS 14 nward for RSQ reports engine el observed to be tracking to th	OPALINE OT no.3: Master (PEC No.1129): reports th however making his two tugs fast for passin aft that was thought to have been resolved equired to have a two tug escort when pass SARAH D overheating when entering channel from th he north and into shallow water.	at he was having engine problem ng IOT. From Master: This is a before leaving the last port. sing IOT until the problem has Spurn Point e North at 3A Binks.
Vessels bo 30-Apr Vessel in p but that the recurrence Master has been fully r 30-Apr 2230 Tug i 2309 Vess 2316 Vess	VTS 15 osition between 9A buoy and l ey were now resolved. He was of a problem with the cranksh been advised that he will be r resolved. VTS 14 nward for RSQ reports engine el observed to be tracking to th el alters back to the south and	OPALINE OT no.3: Master (PEC No.1129): reports th however making his two tugs fast for passin aft that was thought to have been resolved equired to have a two tug escort when pass SARAH D overheating when entering channel from th he north and into shallow water. advises she is attempting to cool the engin	at he was having engine problem ng IOT. From Master: This is a before leaving the last port. sing IOT until the problem has Spurn Point e North at 3A Binks. e and will shortly proceed to RSC
Vessels bo 30-Apr Vessel in p but that the recurrence Master has been fully r 30-Apr 2230 Tug i 2309 Vess 2316 Vess when comp	VTS 15 osition between 9A buoy and l ey were now resolved. He was of a problem with the cranksh been advised that he will be r resolved. VTS 14 nward for RSQ reports engine el observed to be tracking to th el alters back to the south and olete. KGD advised. 0115 Vess	OPALINE OT no.3: Master (PEC No.1129): reports th however making his two tugs fast for passin aft that was thought to have been resolved equired to have a two tug escort when pass SARAH D overheating when entering channel from th he north and into shallow water. advises she is attempting to cool the engin sel proceeding up to RSQ on the flood tide.	at he was having engine problem ng IOT. From Master: This is a before leaving the last port. sing IOT until the problem has Spurn Point e North at 3A Binks. e and will shortly proceed to RSC Berthing AM tide 1st May.
Vessels bo 30-Apr Vessel in p but that the recurrence Master has been fully r 30-Apr 2230 Tug i 2309 Vess 2316 Vess when comp 01-May	VTS 15 osition between 9A buoy and 1 ay were now resolved. He was of a problem with the cranksh been advised that he will be r resolved. VTS 14 nward for RSQ reports engine el observed to be tracking to th el alters back to the south and olete. KGD advised. 0115 Vess VTS 15	OPALINE OT no.3: Master (PEC No.1129): reports th however making his two tugs fast for passin aft that was thought to have been resolved equired to have a two tug escort when pass SARAH D overheating when entering channel from th e north and into shallow water. advises she is attempting to cool the engin sel proceeding up to RSQ on the flood tide. LADY MARTINE	at he was having engine problem ng IOT. From Master: This is a before leaving the last port. sing IOT until the problem has Spurn Point e North at 3A Binks. e and will shortly proceed to RSC Berthing AM tide 1st May. IGT
Vessels bo 30-Apr Vessel in p but that the recurrence Master has been fully r 30-Apr 2230 Tug i 2309 Vess 2316 Vess when comp 01-May After depar	VTS 15 oosition between 9A buoy and 1 ey were now resolved. He was of a problem with the cranksh been advised that he will be r resolved. VTS 14 nward for RSQ reports engine el observed to be tracking to th el alters back to the south and olete. KGD advised. 0115 Vess VTS 15 thing the berth, the pilot reporte	OPALINE OT no.3: Master (PEC No.1129): reports th however making his two tugs fast for passin aft that was thought to have been resolved equired to have a two tug escort when pass SARAH D overheating when entering channel from th e north and into shallow water. advises she is attempting to cool the engin sel proceeding up to RSQ on the flood tide. LADY MARTINE d that the vessel has suffered ME failure th	at he was having engine problem ng IOT. From Master: This is a before leaving the last port. sing IOT until the problem has Spurn Point e North at 3A Binks. e and will shortly proceed to RSC Berthing AM tide 1st May. IGT ree cables to the west of the
Vessels bo 30-Apr Vessel in p but that the ecurrence Master has been fully r 30-Apr 2230 Tug i 2309 Vess 2316 Vess when comp 01-May After depan Holme hoo fast fwd.	VTS 15 oosition between 9A buoy and 1 ey were now resolved. He was of a problem with the cranksh been advised that he will be r resolved. VTS 14 nward for RSQ reports engine el observed to be tracking to th el alters back to the south and olete. KGD advised. 0115 Vess VTS 15 thing the berth, the pilot reporte	OPALINE OT no.3: Master (PEC No.1129): reports th however making his two tugs fast for passin aft that was thought to have been resolved equired to have a two tug escort when pass SARAH D overheating when entering channel from th he north and into shallow water. advises she is attempting to cool the engin sel proceeding up to RSQ on the flood tide. LADY MARTINE d that the vessel has suffered ME failure th hde, tug Svitzer Valiant who had finished as	at he was having engine problem ng IOT. From Master: This is a before leaving the last port. sing IOT until the problem has <u>Spurn Point</u> e North at 3A Binks. e and will shortly proceed to RSC Berthing AM tide 1st May. IGT ree cables to the west of the



Date	Reported By	Ships	General Location
02-May	VTS 14	CLIPPER POINT	Sea Reach
	oorts defect with port windlas hydraulics available for anch	ss hydraulic system. Full mooring capab	ility available but at reduced speed,
		ADM advised. Vessel to effect repair or	n arrival at Immingham
02-May	PILOT	ERNEST SHACKLETON	Grimsby
Rudder an	gle indicator is showing six of	degrees to port when the wheel is amid	ships.
	cking Immingham 2nd 20:30		
03-May	PILOT	ARESSA he main gyro compass. Additionally, bo	Paull
	led from Hull 03/05/2014 13		w thruster is not working.
09-May	PILOT	ALREK	Spurn Point
Pilot report		passage to King George dock, Hull. No	
09-May	VTS 15		Holme Hook
1515 Mast nvestigate	•	gines is stuck on full ahead, vessel will	remain in the 11A deposit ground to
1547 Mast Hook anch	er advises the problem appe	ears to be an electrical fault on the port will not be immobilised as the starboard	
16-May	VTS 15	KOPERSAND	Spurn L/F
	ts that the bow thruster is inc	· ·	
17-May	PILOT	BRO NYBORG	Spurn L/F
2004 Main ordered for	Engine power restored and r berthing as a precaution.	as she approached the South East Che passage resumed. Investigation shows	
<u>Vessel ber</u> 17-Mav	thing 17/05 - 2115. No sailir VTS 15	CEMSEA III	Ouse
		t. Pilot reports that the vessel has suffe	
engines or 0855 All po Next port:	steering. ower now restored and vess Brunsbuttel.	el resuming outward passage.	· · ·
21-May	PILOT	NAVIOS ANTARES	IBT
	accommodation ladder dama	aged by cargo operations. rt. Gangway to be repaired at next desti	ination
22-May	MASTER / CAPTAIN	STEFAN K	Humber
Vessel ber			& Long given to enable safe anchoring.
22-May	PILOT		Chequer
	ter inoperative		
26-May	VTS 15	YASMINE	Sea Reach
	orts that one radar, S-Band		
26-May	VTS 15	due to high exhaust temps, whilst appro	Trent
power was is now at tl	restored and the vessel be	rthed safely port side too. The pilot also rts to rectify the problem.	reports that the vessels superintenden
<u>31-May</u> Master der	MASTER / CAPTAIN	SKS TANA sing. Vessel anchored at the Humber lig	Humber
	nmingham Bulk Terminal da	0 0	ni nual.
03-Jun	MASTER / CAPTAIN	OPALINE	Humber
0549 Prob		sel will remain outside approaches whils captain request anchorage South of the efect rectified.	
04-Jun	MASTER / CAPTAIN	YASMINE	Holme Hook
but has ore Berthing H 08:15 Svitz 08:25 Svitz	dered two tugs for assistanc IST 4 09:00. ETD 20:00 zer Susan departs Immingha zer Josephine departs Immir in attendance.	am E/J	as the second engine and bow thruster
	VTS 15	STENA TRANSPORTER	HST
09:30 Yası 08-Jun			
09:30 Yası 08-Jun	ative. Next port Hook of Hol		
09:30 Yası 08-Jun AIS inoper 10-Jun	VTS 15	THARSIS ffered engine control problems and is ar	Skitter Haven



	D	efect (Ship) Report	ed
Date	Reported By	Ships	General Location
2000 Shov 2036 Tug i	ette departs Alex dock Hull n attendance	to assist vessel.	
2310 All fa	or aweigh proceeding to RS st RSQ, tug to remain in atte n: Duisburg when repairs co	endance until repairs complete as vessel	will be immobilised.
10-Jun	VTS 15		Spurn Point
		estination: Grove LM1 berthing 0445 10th	
13-Jun	PILOT	ATLANTIS DWELLER	Spurn L/F
Repairs are	ter not operational. Tug orde e expected to be completed Repairs completed.	ered for escort passing IOT. Vessel berth prior to departure	ing Immingham dock 13th 0530.
14-Jun	PILOT	ECE NUR K	Spurn Point
	ts engine problem and reque		opunition
0853 Vess 1027 Capta		e. Problem identified as faulty coolant pip te.	e, expected repair time of one hour.
17-Jun	VTS 15	ARISTOTE	New H Pier
	S is inoperative. Destination		
20-Jun	VTS 15	BOMAR MOON o recover both anchors in the event of en	Spurn L/F
repairs car 21/06/14 F 0630 After 0930 Tug I 1116 Tug i	n be made. Agent advised. rom agent, he expects it to consultation, vessel to proc Beamer leaves KGD procee n attendance at Upper Burc	ager, vessel aborts inward passage until s take 1-2 weeks to get the spare parts to f weed to Flixborough with tug escort. ding to the IOT to await arrival of vessel. om. her at Salt end continuing escort duties to	ix the windlass problem.
		ailing with windlass problem and tug sby	
20-Jun	PILOT	SCOT CARRIER	Spurn L/F
Bow thrust	er defective. Vessel on pass	sage to Grove.	
22-Jun	CAPTAIN	054 5140	
		SEA EMS	Humber
Vessel in H therefore d Berthing: 1	lumber DW anchorage, una	ble to start main engine, so cancelled pil ind E'ly 10Kts 1224 Captain declares eng	ot for berthing AM 22nd. Vessel is
Vessel in H therefore d Berthing: 1 23-Jun	Humber DW anchorage, una lisabled at the anchorage W 615 23rd June at Howdend	able to start main engine, so cancelled pil /ind E'ly 10Kts 1224 Captain declares eng yke	ot for berthing AM 22nd. Vessel is gine problem is resolved.
Vessel in F therefore d Berthing: 1 23-Jun One bow th 25-Jun	Humber DW anchorage, una lisabled at the anchorage W 615 23rd June at Howdend CAPTAIN hruster not operational VTS 15	able to start main engine, so cancelled pil ind E'ly 10Kts 1224 Captain declares eng yke ARK GERMANIA GERDA	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier
Vessel in F therefore d Berthing: 1 23-Jun One bow tl 25-Jun Vessel bet 0356 vesse 0650 Tugs 0701 Vess 0820 All fa	Humber DW anchorage, una lisabled at the anchorage W 615 23rd June at Howdend CAPTAIN nruster not operational VTS 15 ween 20a and 21b buoys in el anchored in position 110 x Shovette and Lashette in a el proceeding, under tow, to st RSQ.	ble to start main engine, so cancelled pil ind E'ly 10Kts 1224 Captain declares engine yke ARK GERMANIA GERDA the Skitter channel, Pilot reports ME failu x 0.25 from 21b lt. by. ttendance. Riverside Quay.	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier ure (Gearbox)
Vessel in F therefore d Berthing: 1 23-Jun One bow tl 25-Jun Vessel bet 0356 vesse 0650 Tugs 0701 Vess 0820 All fa 26-Jun	Humber DW anchorage, una lisabled at the anchorage W 615 23rd June at Howdend CAPTAIN hruster not operational VTS 15 ween 20a and 21b buoys in el anchored in position 110 s Shovette and Lashette in a el proceeding, under tow, to st RSQ. PILOT	ble to start main engine, so cancelled pil ind E'ly 10Kts 1224 Captain declares engine (ARK GERMANIA GERDA the Skitter channel, Pilot reports ME failur x 0.25 from 21b lt. by. ttendance. PRiverside Quay. VERA SU	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier ure (Gearbox) Chequer
Vessel in H therefore d Berthing: 1 23-Jun One bow th 25-Jun Vessel bet 0356 vesse 0650 Tugs 0650 Tugs 0820 All fa 26-Jun Inward ves advised. V	Humber DW anchorage, una lisabled at the anchorage W 615 23rd June at Howdend CAPTAIN rruster not operational VTS 15 ween 20a and 21b buoys in el anchored in position 110 x Shovette and Lashette in a el proceeding, under tow, to st RSQ. PILOT sel for Flixborough, unable	ble to start main engine, so cancelled pil- find E'ly 10Kts 1224 Captain declares engines (Marcon Stress of Content of	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier ure (Gearbox) Chequer . Agent uncontactable. Duty manager
Vessel in H therefore d Berthing: 1 23-Jun One bow tl 25-Jun Vessel bet 0356 vesse 0650 Tugs 0820 All fa 26-Jun Inward ves advised. V Vessel ber 27-Jun	Aumber DW anchorage, una lisabled at the anchorage W 615 23rd June at Howdend CAPTAIN hruster not operational VTS 15 ween 20a and 21b buoys in al anchored in position 110 c Shovette and Lashette in a el proceeding, under tow, to st RSQ. PILOT seel for Flixborough, unable essel to proceed to sea and thing 0815 29th June at Flix VTS 15	ble to start main engine, so cancelled pil- find E'ly 10Kts 1224 Captain declares engines (Mark GERMANIA) GERDA the Skitter channel, Pilot reports ME failur x 0.25 from 21b lt. by. ttendance. Priverside Quay. VERA SU to retrieve anchor due to windlass defect drift until next tide - when escort tug can tborough WILSON LIVORNO	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier ure (Gearbox) Chequer . Agent uncontactable. Duty manager be arranged to meet before IOT. Imm Dk
Vessel in H therefore d Berthing: 1 23-Jun One bow th 25-Jun Vessel bet 0356 vesse 050 Tugs 0701 Vess 0820 All fa 26-Jun nward ves advised. V Vessel ber 27-Jun Vessel in lo	Humber DW anchorage, una lisabled at the anchorage W 615 23rd June at Howdend CAPTAIN hruster not operational VTS 15 ween 20a and 21b buoys in al anchored in position 110 3 Shovette and Lashette in a el proceeding, under tow, to st RSQ. PILOT sel for Flixborough, unable essel to proceed to sea and thing 0815 29th June at Flix VTS 15 ock preparing to sail from Irr	ARK GERMANIA  GERDA  the Skitter channel, Pilot reports ME failu x 0.25 from 21b lt. by. ttendance. Riverside Quay.  VERA SU to retrieve anchor due to windlass defect drift until next tide - when escort tug can borough  WILSON LIVORNO  mingham. Pilot reports that the vessel ha	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier ure (Gearbox) Chequer . Agent uncontactable. Duty manager be arranged to meet before IOT. Imm Dk as no working VHF radio sets. Duty
Vessel in H therefore d Berthing: 1 23-Jun One bow tl 25-Jun Vessel bet 0356 vesse 0650 Tugs 0701 Vess 0820 All fa 26-Jun Inward ves advised. V Vessel ber 27-Jun Vessel in Ia manager a 2300 One	Humber DW anchorage, una lisabled at the anchorage W 615 23rd June at Howdend CAPTAIN hruster not operational VTS 15 ween 20a and 21b buoys in el anchored in position 110 3 Shovette and Lashette in a el proceeding, under tow, to st RSQ. PILOT ssel for Flixborough, unable essel to proceed to sea and thing 0815 29th June at Flix VTS 15 ock preparing to sail from Im dvised. Permission to proce radio repaired and permission	ble to start main engine, so cancelled pil- find E'ly 10Kts 1224 Captain declares engines (Mark GERMANIA) GERDA the Skitter channel, Pilot reports ME failur x 0.25 from 21b lt. by. ttendance. Priverside Quay. VERA SU to retrieve anchor due to windlass defect drift until next tide - when escort tug can tborough WILSON LIVORNO	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier ure (Gearbox) Chequer . Agent uncontactable. Duty manager be arranged to meet before IOT. Imm Dk as no working VHF radio sets. Duty ffect repairs to radios.
Vessel in H therefore d Berthing: 1 23-Jun One bow tl 25-Jun Vessel bet 0356 vesse 0650 Tugs 0701 Vess 0820 All fa 26-Jun Inward ves advised. V Vessel ber 27-Jun Vessel in Id manager a 2300 One Vessel dep 28-Jun	Humber DW anchorage, una lisabled at the anchorage W 615 23rd June at Howdend CAPTAIN hruster not operational VTS 15 ween 20a and 21b buoys in el anchored in position 110 3 Shovette and Lashette in a el proceeding, under tow, to st RSQ. PILOT ssel for Flixborough, unable essel to proceed to sea and thing 0815 29th June at Flix VTS 15 ock preparing to sail from Im dvised. Permission to proce radio repaired and permissio parting 0200 from Immingha VTS 15	ARK GERMANIA GERDA the Skitter channel, Pilot reports ME failu x 0.25 from 21b lt. by. ttendance. Riverside Quay. VERA SU to retrieve anchor due to windlass defect drift until next tide - when escort tug can borough WILSON LIVORNO nmingham. Pilot reports that the vessel ha ted declined. Vessel returns to berth to ef on from MCA for vessel to proceed, recei m dock, destination Mosjoen. STENA TRANSPORTER	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier ure (Gearbox) Chequer . Agent uncontactable. Duty manager be arranged to meet before IOT. Imm Dk as no working VHF radio sets. Duty ffect repairs to radios.
Vessel in H therefore d Berthing: 1 23-Jun One bow tl 25-Jun Vessel bet 0356 vesse 0650 Tugs 0701 Vess 0820 All fa 26-Jun Inward ves advised. V Vessel ber 27-Jun Vessel in Ia manager a 2300 One Vessel dep 28-Jun One of the	Humber DW anchorage, una lisabled at the anchorage W 615 23rd June at Howdend CAPTAIN hruster not operational VTS 15 ween 20a and 21b buoys in el anchored in position 110 3 Shovette and Lashette in a el proceeding, under tow, to st RSQ. PILOT sel for Flixborough, unable essel to proceed to sea and thing 0815 29th June at Flix VTS 15 ock preparing to sail from Im dvised. Permission to proce radio repaired and permissio parting 0200 from Immingha VTS 15 vessels two bow thrusters a	ARK GERMANIA  GERDA  the Skitter channel, Pilot reports ME failu x 0.25 from 21b lt. by. ttendance. o Riverside Quay.  VERA SU to retrieve anchor due to windlass defect drift until next tide - when escort tug can borough  WILSON LIVORNO  nmingham. Pilot reports that the vessel ha sed declined. Vessel returns to berth to ef on from MCA for vessel to proceed, recei m dock, destination Mosjoen.  STENA TRANSPORTER are inoperative. Berthing HST 1 0700	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier ure (Gearbox) Chequer . Agent uncontactable. Duty manager be arranged to meet before IOT. Imm Dk as no working VHF radio sets. Duty ffect repairs to radios. ived by email. Spurn L/F
Vessel in H herefore d Berthing: 1 23-Jun One bow tl 25-Jun Vessel bet 0356 vesse 0650 Tugs 0701 Vess 0820 All fa 26-Jun nward ves advised. V Vessel ber 27-Jun Vessel in Id manager a 2300 One Vessel dep 28-Jun One of the 30-Jun	Humber DW anchorage, una lisabled at the anchorage W 615 23rd June at Howdend CAPTAIN hruster not operational VTS 15 ween 20a and 21b buoys in el anchored in position 110 3 Shovette and Lashette in a el proceeding, under tow, to st RSQ. PILOT essel for Flixborough, unable essel to proceed to sea and thing 0815 29th June at Flix VTS 15 ock preparing to sail from Im dvised. Permission to proce radio repaired and permissio parting 0200 from Immingha VTS 15 vessels two bow thrusters a PILOT	ARK GERMANIA  GERDA  the Skitter channel, Pilot reports ME failu x 0.25 from 21b lt. by. ttendance. Riverside Quay.  VERA SU to retrieve anchor due to windlass defect. drift until next tide - when escort tug can tborough  WILSON LIVORNO  mmingham. Pilot reports that the vessel ha eed declined. Vessel returns to berth to ef on from MCA for vessel to proceed, recei m dock, destination Mosjoen.  STENA TRANSPORTER are inoperative. Berthing HST 1 0700  MARLIN	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier ure (Gearbox) Chequer . Agent uncontactable. Duty manager be arranged to meet before IOT. Imm Dk as no working VHF radio sets. Duty ffect repairs to radios. ived by email. Spurn L/F H Bridge
Vessel in H therefore d Berthing: 1 23-Jun One bow th 25-Jun Vessel bet 0356 vesse 0650 Tugs 0701 Vess 0820 All fa 26-Jun Inward ves advised. V Vessel ber 27-Jun Vessel in Ic manager a 2300 One Vessel dep 28-Jun One of the 30-Jun 0943 Vess faulty fuel I 1115 defec	Humber DW anchorage, unalisabled at the anchorage W         615 23rd June at Howdendy         CAPTAIN         hruster not operational         VTS 15         ween 20a and 21b buoys in         el anchored in position 110 3         Shovette and Lashette in a         el proceeding, under tow, to         st RSQ.         PILOT         sel for Flixborough, unable         essel to proceed to sea and         thing 0815 29th June at Flix         VTS 15         pock preparing to sail from Im         dvised. Permission to proceer         radio repaired and permission         vTS 15         vessels two bow thrusters a         PILOT         el moving from Goole to Imm         ine. Vessel rectifying proble         trectified.	ARK GERMANIA  GERDA  the Skitter channel, Pilot reports ME failu x 0.25 from 21b lt. by. ttendance. Riverside Quay.  VERA SU to retrieve anchor due to windlass defect drift until next tide - when escort tug can borough  WILSON LIVORNO  mingham. Pilot reports that the vessel ha ted declined. Vessel returns to berth to ef on from MCA for vessel to proceed, recei m dock, destination Mosjoen.  STENA TRANSPORTER are inoperative. Berthing HST 1 0700  MARLIN  MILSON LIVORIO	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier ure (Gearbox) Chequer . Agent uncontactable. Duty manager be arranged to meet before IOT. Imm Dk as no working VHF radio sets. Duty ffect repairs to radios. ived by email. Spurn L/F H Bridge orts starboard engine stopped due to
Vessel in H herefore d Berthing: 1 23-Jun One bow th 25-Jun Vessel bet 0356 vesse 0650 Tugs 0820 All fa 26-Jun nward ves advised. V Vessel ber 27-Jun Vessel in k manager a 2300 One Vessel dep 28-Jun One of the 30-Jun 0943 Vess faulty fuel I 1115 defec 01-Jul	Humber DW anchorage, unalisabled at the anchorage W         615 23rd June at Howdendy         CAPTAIN         hruster not operational         VTS 15         ween 20a and 21b buoys in         el anchored in position 110 3         Shovette and Lashette in a         el proceeding, under tow, to         st RSQ.         PILOT         seel for Flixborough, unable         essel to proceed to sea and         thing 0815 29th June at Flix         VTS 15         ock preparing to sail from Im         dvised. Permission to proce         radio repaired and permission         varting 0200 from Imminghat         VTS 15         vessels two bow thrusters a         PILOT         el moving from Goole to Immine,         vessel rectifying proble         tractified.         PILOT	ARK GERMANIA  GERDA  the Skitter channel, Pilot reports ME failu x 0.25 from 21b lt. by. ttendance. Riverside Quay.  VERA SU to retrieve anchor due to windlass defect drift until next tide - when escort tug can borough  WILSON LIVORNO  mingham. Pilot reports that the vessel ha ted declined. Vessel returns to berth to ef on from MCA for vessel to proceed, recei m dock, destination Mosjoen.  STENA TRANSPORTER are inoperative. Berthing HST 1 0700  MARLIN  ARVELOR FIGHTER	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier ure (Gearbox) Chequer Agent uncontactable. Duty manager be arranged to meet before IOT. Imm Dk as no working VHF radio sets. Duty ffect repairs to radios. ived by email. Spurn L/F H Bridge orts starboard engine stopped due to Apex
Vessel in H therefore d Berthing: 1 23-Jun One bow th 25-Jun Vessel bet 0356 vesse 0650 Tugs 0701 Vesse 0820 All fa 26-Jun Inward vess advised. V Vessel ber 27-Jun Vessel on h manager a 2300 One Vessel dep 28-Jun One of the 30-Jun 0943 Vess faulty fuel 1 1115 defec 01-Jul Vessel out Pilot report 0033 Engin	Humber DW anchorage, unalisabled at the anchorage W         615 23rd June at Howdendy         CAPTAIN         hruster not operational         VTS 15         ween 20a and 21b buoys in         el anchored in position 110 b         Shovette and Lashette in a         el proceeding, under tow, to         st RSQ.         PILOT         sesel for Flixborough, unable         essel to proceed to sea and         thing 0815 29th June at Flix         VTS 15         ock preparing to sail from Im         dvised. Permission to proce         radio repaired and permission         vTS 15         vessels two bow thrusters a         PILOT         el moving from Goole to Imr         ine. Vessel rectifying proble         tractified.         PILOT         bound from Gunness to sea         ts blown gasket, attempting         hound from Gunness to sea	ARK GERMANIA  GERDA  the Skitter channel, Pilot reports ME failu (GERDA the Skitter channel, Pilot reports ME failu (C.25 from 21b lt. by. ttendance. Priverside Quay.  VERA SU to retrieve anchor due to windlass defect drift until next tide - when escort tug can borough  WILSON LIVORNO mingham. Pilot reports that the vessel ha bed declined. Vessel returns to berth to ef on from MCA for vessel to proceed, recei m dock, destination Mosjoen.  STENA TRANSPORTER are inoperative. Berthing HST 1 0700  MARLIN  MINGHAM dock No3 Coal Hoist. Pilot report suffered main engine failure at the Apex repairs. 7 POB, 4.9 mt Diesel, 164 lts Lul	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier ure (Gearbox) Chequer Agent uncontactable. Duty manager be arranged to meet before IOT. Imm Dk as no working VHF radio sets. Duty ffect repairs to radios. ved by email. Spurn L/F H Bridge rts starboard engine stopped due to Apex s, vessel anchored at the Apex.
Vessel in H therefore d Berthing: 1 23-Jun One bow th 25-Jun Vessel bet 0356 vesse 0650 Tugs 0701 Vessel 0701 Vesse 0820 All fa 26-Jun Inward vess advised. V Vessel ber 27-Jun Vessel on la manager a 2300 One Vessel dep 28-Jun One of the 30-Jun 0943 Vess faulty fuel I 1115 defec 01-Jul Vessel out Pilot report 0033 Engir 0045 Anch	Humber DW anchorage, unalisabled at the anchorage W         615 23rd June at Howdendy         CAPTAIN         hruster not operational         VTS 15         ween 20a and 21b buoys in         el anchored in position 110 b         Shovette and Lashette in a         el proceeding, under tow, to         st RSQ.         PILOT         sesel to proceed to sea and         thing 0815 29th June at Flix         VTS 15         ock preparing to sail from Im         dvised. Permission to proce         radio repaired and permission         parting 0200 from Immingha         VTS 15         vessels two bow thrusters a         PILOT         el moving from Goole to Imr         ine. Vessel rectifying proble         tractified.         PILOT         bound from Gunness to sea         ts blown gasket, attempting         ne repairs completed.         or aweigh, resumed outward	ARK GERMANIA  GERDA  the Skitter channel, Pilot reports ME failu x 0.25 from 21b lt. by. ttendance. Priverside Quay.  VERA SU to retrieve anchor due to windlass defect drift until next tide - when escort tug can borough  WILSON LIVORNO  mingham. Pilot reports that the vessel ha bed declined. Vessel returns to berth to ef on from MCA for vessel to proceed, recei m dock, destination Mosjoen.  STENA TRANSPORTER are inoperative. Berthing HST 1 0700  MARLIN  mingham dock No3 Coal Hoist. Pilot report suffered main engine failure at the Apex repairs. 7 POB, 4.9 mt Diesel, 164 Its Lul d passage.	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier ure (Gearbox) Chequer Agent uncontactable. Duty manager be arranged to meet before IOT. Imm Dk as no working VHF radio sets. Duty ffect repairs to radios. ived by email. Spurn L/F H Bridge orts starboard engine stopped due to Apex vessel anchored at the Apex. be oil. In ballast.
Vessel in H therefore d Berthing: 1 23-Jun One bow th 25-Jun Vessel bet 0356 vesse 0650 Tugs 0701 Vesse 0701 Vesse 0820 All fa 26-Jun Inward vess advised. V Vessel ber 27-Jun Vessel ber 27-Jun Vessel ber 27-Jun Vessel ber 27-Jun Vessel ber 27-Jun Vessel ber 27-Jun Vessel der 28-Jun One of the 30-Jun 0943 Vess faulty fuel 1 1115 defec 01-Jul Vessel out Pilot report 0045 Anch 01-Jul	Humber DW anchorage, unalisabled at the anchorage W         615 23rd June at Howdendy         CAPTAIN         hruster not operational         VTS 15         ween 20a and 21b buoys in         el anchored in position 110 b         Shovette and Lashette in a         el proceeding, under tow, to         st RSQ.         PILOT         sesel for Flixborough, unable         essel to proceed to sea and         thing 0815 29th June at Flix         VTS 15         ock preparing to sail from Im         dvised. Permission to proce         radio repaired and permission         parting 0200 from Immingha         VTS 15         vessels two bow thrusters a         PILOT         el moving from Goole to Imr         ine. Vessel rectifying proble         trectified.         PILOT         bound from Gunness to sea         to aweigh, resumed outward         VTS 15	ARK GERMANIA  GERDA the Skitter channel, Pilot reports ME failu x 0.25 from 21b lt. by. ttendance. Priverside Quay.  VERA SU to retrieve anchor due to windlass defect drift until next tide - when escort tug can borough  WILSON LIVORNO mingham. Pilot reports that the vessel ha bed declined. Vessel returns to berth to ef on from MCA for vessel to proceed, recei m dock, destination Mosjoen.  STENA TRANSPORTER are inoperative. Berthing HST 1 0700  MARLIN  mingham dock No3 Coal Hoist. Pilot report suffered main engine failure at the Apex repairs. 7 POB, 4.9 mt Diesel, 164 Its Lul d passage.  DOLFIJN	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier ure (Gearbox) Chequer Agent uncontactable. Duty manager be arranged to meet before IOT. Imm Dk as no working VHF radio sets. Duty ffect repairs to radios. ived by email. Spurn L/F H Bridge orts starboard engine stopped due to Apex , vessel anchored at the Apex. be oil. In ballast. New H Pier
Vessel in H therefore d Berthing: 1 23-Jun One bow th 25-Jun Vessel bet 0356 vesse 0650 Tugs 0701 Vesse 0701 Vesse 0820 All fa 26-Jun Inward ves advised. V/ Vessel ber 27-Jun Vessel ber 27-Jun Vessel ber 27-Jun Vessel ber 27-Jun Vessel ber 27-Jun Vessel ber 27-Jun Vessel ber 27-Jun Vessel ber 27-Jun Vessel ber 27-Jun Vessel ott Palot report 0045 Anch 01-Jul Pilot report	Humber DW anchorage, unalisabled at the anchorage W         615 23rd June at Howdendy         CAPTAIN         hruster not operational         VTS 15         ween 20a and 21b buoys in         el anchored in position 110 b         Shovette and Lashette in a         el proceeding, under tow, to         st RSQ.         PILOT         ssel for Flixborough, unable         essel to proceed to sea and         thing 0815 29th June at Flix         VTS 15         ock preparing to sail from Im         dvised. Permission to proce         radio repaired and permission         vTS 15         vessels two bow thrusters a         PILOT         el moving from Goole to Immingha         VTS 15         vessels two bow thrusters a         PILOT         el moving from Goole to Immingha         vTS 15         bound from Gunness to sea         ts blown gasket, attempting         te repairs completed.         or aweigh, resumed outward         VTS 15         ts that he is aborting passage	ARK GERMANIA  GERDA  the Skitter channel, Pilot reports ME failu x 0.25 from 21b lt. by. ttendance. Priverside Quay.  VERA SU to retrieve anchor due to windlass defect drift until next tide - when escort tug can borough  WILSON LIVORNO  mingham. Pilot reports that the vessel ha bed declined. Vessel returns to berth to ef on from MCA for vessel to proceed, recei m dock, destination Mosjoen.  STENA TRANSPORTER are inoperative. Berthing HST 1 0700  MARLIN  mingham dock No3 Coal Hoist. Pilot report suffered main engine failure at the Apex repairs. 7 POB, 4.9 mt Diesel, 164 Its Lul d passage.	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier ure (Gearbox) Chequer . Agent uncontactable. Duty manager be arranged to meet before IOT. Imm Dk as no working VHF radio sets. Duty ffect repairs to radios. ived by email. Spurn L/F H Bridge orts starboard engine stopped due to Apex c, vessel anchored at the Apex. be oil. In ballast. New H Pier tide and he is unhappy with the
Vessel in F therefore d Berthing: 1 23-Jun One bow tl 25-Jun Vessel bet 0356 vesse 0650 Tugs 0701 Vess 0701 Vess 0820 All fa 26-Jun Inward ves advised. V Vessel ber 27-Jun Vessel ber 27-Jun Vessel ber 27-Jun Vessel ber 27-Jun Vessel ber 27-Jun Vessel ber 27-Jun Vessel der 28-Jun One of the 30-Jun 0943 Vess faulty fuel I 1115 defec 01-Jul Vessel out Pilot report vessel's sta 02-Jul	Humber DW anchorage, unalisabled at the anchorage W         615 23rd June at Howdendy         CAPTAIN         hruster not operational         VTS 15         ween 20a and 21b buoys in         el anchored in position 110 3         Shovette and Lashette in a         el proceeding, under tow, to         st RSQ.         PILOT         essel for Flixborough, unable         essel to proceed to sea and         thing 0815 29th June at Flix         VTS 15         ock preparing to sail from Im         dvised. Permission to proce         radio repaired and permission         vTS 15         vessels two bow thrusters at         PILOT         el moving from Goole to Imminghat         VTS 15         vessels two bow thrusters at         PILOT         bound from Gunness to sea         ts blown gasket, attempting         he repairs completed.         or aweigh, resumed outward         VTS 15         is that he is aborting passag         ability. Excessive heeling on         MASTER / CAPTAIN	ARK GERMANIA GERDA the Skitter channel, Pilot reports ME failu x 0.25 from 21b lt. by. ttendance. o Riverside Quay. VERA SU to retrieve anchor due to windlass defect drift until next tide - when escort tug can borough WILSON LIVORNO mingham. Pilot reports that the vessel ha red declined. Vessel returns to berth to ef on from MCA for vessel to proceed, recei m dock, destination Mosjoen. STENA TRANSPORTER are inoperative. Berthing HST 1 0700 MARLIN mingham dock No3 Coal Hoist. Pilot report m. ARVELOR FIGHTER a suffered main engine failure at the Apex repairs. 7 POB, 4.9 mt Diesel, 164 Its Lul d passage. DOLFIJN te to Grove as the vessel is max draft for helm movements. Returning to Bull ancl CLEMENTINE	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier ure (Gearbox) Chequer . Agent uncontactable. Duty manager be arranged to meet before IOT. Imm Dk as no working VHF radio sets. Duty ffect repairs to radios. ived by email. Spurn L/F H Bridge orts starboard engine stopped due to Apex s, vessel anchored at the Apex. be oil. In ballast. New H Pier tide and he is unhappy with the horage. Humber
Vessel in H therefore d Berthing: 1 23-Jun One bow th 25-Jun Vessel bet 0356 vesse 0650 Tugs 0701 Vesse 0701 Vesse 0820 All fa 26-Jun Inward vess advised. V Vessel ber 27-Jun Vessel ber 27-Jun Vessel oth manager a 2300 One Vessel dep 28-Jun One of the 30-Jun 0943 Vess faulty fuel I 1115 defec 01-Jul Vessel out Pilot report 0033 Engir 0045 Anch 01-Jul Pilot report vessel's sta 02-Jul Vessel in bu	Humber DW anchorage, unalisabled at the anchorage W         615 23rd June at Howdendy         CAPTAIN         hruster not operational         VTS 15         ween 20a and 21b buoys in         al anchored in position 110 at the second se	ARK GERMANIA  GERDA the Skitter channel, Pilot reports ME failu x 0.25 from 21b lt. by. ttendance. Riverside Quay.  VERA SU to retrieve anchor due to windlass defect drift until next tide - when escort tug can cborough  WILSON LIVORNO mingham. Pilot reports that the vessel ha eed declined. Vessel returns to berth to ef on from MCA for vessel to proceed, recei m dock, destination Mosjoen.  STENA TRANSPORTER are inoperative. Berthing HST 1 0700  MARLIN  mingham dock No3 Coal Hoist. Pilot report  ARVELOR FIGHTER  a suffered main engine failure at the Apex repairs. 7 POB, 4.9 mt Diesel, 164 Its Lul d passage.  DOLFIJN ge to Grove as the vessel is max draft for helm movements. Returning to Bull ancl	ot for berthing AM 22nd. Vessel is gine problem is resolved. IOH New H Pier ure (Gearbox) Chequer . Agent uncontactable. Duty manager be arranged to meet before IOT. Imm Dk as no working VHF radio sets. Duty ffect repairs to radios. ived by email. Spurn L/F H Bridge orts starboard engine stopped due to Apex s, vessel anchored at the Apex. be oil. In ballast. New H Pier tide and he is unhappy with the horage. Humber auxiliary engine off line therefore no



1

Date	Reported By	Ships	General Location
	s that the bow thruster is inop		-
4-Jul	VTS 14	HANSEATIC SPIRIT	Spurn L/F
		George dock 10 quay 1130 hrs	One was h /F
5-Jul	VTS 14	PRIDE OF YORK e next 2 or 3 weeks due to a technical issue	Spurn L/F
	GD 5 quay west.	e fiext 2 of 5 weeks due to a technical issue	with a crankshan.
6-Jul	VTS 15	REMORA	Chequer
essel is o	perating on one engine due to	o a gear box problem with the port engine.	
estination	: Flixborough berthing 1300 (	Deth July.	
5-Jul	PILOT	RIG	Skitter Ness
RSQ reque 218 - Tug ne river at Baltic Sea]	sted. Agent advised and is an Shovette in attendance, mad	oy, vessel reports engine overheating proble rranging tug and boatmen. le fast as vessel passes the entrance to King ention the recent incident between the m/v F	g George Dock. [Another pilot on
1-Jul	PILOT	AMANDA	Trent
0	e will not operate astern.		
1-Jul	VTS 15	SORMOVSKIY 3064	Cleeness
	to pilot is inoperative, using h Nakskov, Denmark	เล่าน รเษยาแห บาแห.	
2-Jul	VTS 15	HORST B	Imm Dk
vilot reports	s whilst in the lock that the bo	ow thruster can only operate up to a maximu	
erthing: In	nmingham Dock 7 Quay.		
2-Jul	PILOT	SAMSKIP AKRAFELL	Burcom Deposit
	en passing the No.8 Middle B The IOT standby tug, Svitzer	urcom, the pilot of the vessel reports a comp	plete power failure and may need
		restored, but that the situation has not yet b	een fully resolved. The vessel
	o proceed outwards.		
016 - Pilot	reports that the situation is u	under control and that the ship is proceeding	as normal. The Standby tug is
	nd stands down. Next port Ro		1
23-Jul	PILOT		Apex
	lost full power on 3 occasion ixborough wharf 23/7/14 1740		
26-Jul	MASTER / CAPTAIN	SOLENT FISHER	IOT8
	orts AIS is inoperative. Vesse		
29-Jul	MASTER / CAPTAIN	THAMES FISHER	Humber
nward for I	OT has lube oil pump probler	m and anchored in position 53° 34.5'N, 000°	28.6'E. Coastguard advised.
Vessel in b		ante de la colo Para en el la tem	
	d 30/7 0800:Advised spare pa	arts to be delivered later. airs are complete and is now awaiting berthi	na ordoro
	PILOT		Spurn L/F
		ble due to cylinder problem. KGD advised.	Span L/I
)9-Aug	VTS 15	BEN MAYE	Bull
0		reports that vessel requires the Bull anchora	
oroblem an	d the vessel will not be immo	bilised whilst at anchor.	
	el anchored position "A" in Bu		
		one defective fuel pump out of six and would ed one tug will be required to escort the ves	
	10th, berthing Grimsby Roya		ser mu eminaby.
2-Aug	PILOT	SUPERIORITY	Spurn Point
	-	e. Only one anchor available for use. Last po	
Berthing IO	T 6 1530.	· · · ·	<u>.</u>
14-Aug	PILOT	ROSEBURG	Chequer
		4/08/14 2200. Pilot reports no auto pilot and	
I6-Aug	VTS 15	ROSEBURG	Foul Holme
	s that the auto pilot is inopera le to berth at Barrow haven 1	ative, using hand steering only. Vessel outwa	and bound to the Bull anchorage,
7-Aug	VTS 15	FEHN SIRIUS	Chequer
0		ning Immingham dock 4 quay at 1030. Immir	
9-Aug	MASTER / CAPTAIN	CHRISTINA	Spurn Point
		loys declared a main engine problem, name	
		on passage to Tjedbergodden, Norway. ETA	
	CAPTAIN	ANJA	Humber
20-Aug			which would require energy 20
On approad	ching the Hotspur buoy, the v		mich would require approx. 30
On approact	repair. ADM Immingham adv	ised.	which would require approx. 30
On approact	repair. ADM Immingham adv		SEJ1



	De	efect (Ship) Reported	
Date	Reported By	Ships	General Location
		ne outward journey, vessel bound for Antwerp	
21-Aug	cheduled to return to the Hur PILOT	B GAS LAURA	IGT
	_	et technician to attend before departure.	
Techniciar	ordered for next port - Goth	enburg.	
25-Aug	MASTER / CAPTAIN	PALATINE ade. Fire tug Svitzer Susan, advised to prepa	Foul Holme
required at 0629 Mast 0650 Unde HMCG adv 0713 Svitz 0715 Mast	t this time. IOT advised. ADM er requests fire tug to assist. er tow and proceeding to WB vised. HST informed via ansv er Kathleen attending. er advises that main engine	1 Immingham advised. R. POB 23, Bunkers HFO 651tonnes DO 34t	onnes, 4833 tonnes general RoRo
	ecure at HST3.		Charuan
30-Aug Vessel out	MASTER / CAPTAIN	PRIDE OF YORK ter declares starboard shaft stopped unknow	Chequer
	bound for Zeebrugge eta AM		action, our invooligating.
03-Sep	VTS 15	PRIDE OF YORK	Spurn L/F
technician Berthing: k	look at the unit whilst alongs King George dock 1100 Hrs. I	ETD 1800 3rd	
04-Sep	VTS 15	COASTALWATER	Chequer
Vessel's b advised.	ow inruster is inoperative. Ve	essel berthing Immingham west jetty berth 4,	USIS HIS. IMMINGNAM dock
06-Sep	PILOT	REMORA	Trent
	ts starboard engine blackout.	Suspected fuel line. Vessel continued on on	e engine to Flixborough SE. ETA
06/09/14 1			
11-Sep	VTS 15	LEVANA	Spurn L/F
emergency		on a joining shackle. Anchor is secure but cre are fully operational. IOT advised. 3 1445 11th September.	w unable to lower the anchor in a
14-Sep	VTS 14	PORTH DAFARCH	Spurn L/F
U		Lincs Wind farm to Grimsby Fish Dock.	1
	MASTER / CAPTAIN eclares stbd engine has only n dock 2359/16th, defect to b PILOT	FUGRO SALTIRE 50% pitch available due to defective electrica pe rectified while in port. THUN GOTHENBURG	Humber I drive. Vessel berthing
	ct rectified vessel continued of	problem. Standby tug sent to assist. on passage to the deep water anchorage. Re	turning to IOT Immingham date
19-Sep	PILOT	SAN DIEGO	Spurn Point
20-Sep	PILOT	ermittent target acquirement. Next port Jelsa	Ouse
	_	head. Other engine movements are OK.	Ouse
	thed at Goole. ETD 21/9/14		
22-Sep	VTS 14	ICEBEAM	Rosse Reach
steerage u permissior employ on	sing azimuth engine capabili n to proceed to the Hawke An e and make provision for a b	ctive and non-operational. Vessel is fully DP of ties. Course accuracy monitored and found s inchorage. At this time there is no local agent a erth in the Humber where a technician can at a vessel departing the anchorage for sea.	atisfactory and vessel given allocated, but later today they will tend to rectify the problem.
24-Sep	PILOT	KAILI	KGD
	ts bridge M/E telegraph none PILOT	operational. Vessel proceeding on passage GOLDEN DIAMOND	using back up button control Bull
	-	allast developed engine problem passing Cle	-
22 Crew + 900: Ves	2 Pilots. Fuel Oil 947 tonnes	s. MCA advised. t via Sea Reach and will disable and drift whe	n clear of VTS Humber area.
29-Sep	VTS 15	ST CHARLOTTE	Spurn L/F
	ts that the main CPP control PILOT	is inoperative. Proceeding, using, back-up, p BOMAR MOON	ush button controls. Spurn Point
05-Oct		ator rendering the bow-thruster inoperable. Tu at Immingham dock, (9B Mineral Quay), at 20	ŏ0.
05-Oct Vessel is u ordered by	PiloT	KING FISHER	1013
05-Oct Vessel is u ordered by 05-Oct	PILOT	KING FISHER fective. Vessel departing IOT, next port Ams	IOT3 terdam.
05-Oct Vessel is u ordered by 05-Oct Pilot report 09-Oct	PILOT ts starboard gyro repeater de VTS 14	efective. Vessel departing IOT, next port Ams	terdam. Spurn L/F
05-Oct Vessel is u ordered by 05-Oct Pilot report 09-Oct	PILOT ts starboard gyro repeater de VTS 14	fective. Vessel departing IOT, next port Ams	terdam. Spurn L/F



1


Date	Reported By	Ships	General Location
tug has be	een ordered to meet the vesse	el east of the IOT.	
/essel bour	nd for Immingham Outer Harb	our, berthing at 1515. ADM Immingham adv	vised.
5-Oct	VTS 15	JONGLEUR	Grove
vilot reports	main engine is currently beir	g operated in engine room control mode.	
5-Oct	PILOT	BRUGGE MAX	IBT
		le 15 minute delay sailing. Inward PPV advi	sed.
242 proble		e required to resolve the problem ead and astern on 3 occasions without furth	er problem.
6-Oct	PILOT	EEMS SPRING	Trent
	-	indicators is not working. Captain advises t	
	is yet to be determined.	indicatore is not working. Captain advises i	nat it will get fixed at the flext
6-Oct	VTS 15	WIEBKE B	lmm Dk
'essel's bo	w thruster is inoperative, vess	el berthed Immingham dock 9A quay.	
6-Oct	VTS 15	SEA EMS	Cleeness
ilot reports	s that the gyro compass is 10	degrees out. Vessel berthing Howdendyke a	at 0100 hrs 17th.
7-Oct	PILOT	MERIT	Bull
		Anchorage, position 'Hotel' at 1950.	
		motor had burnt out. The crew require at lea	
		t, berthing had to be cancelled and has bee	n re scheduled for King George
<u>юск QE 10</u> 8-Oct	) Quay East at 0830 on 18th 0	BRITANNIA SEAWAYS	Spurn L/F
	_	outer harbour 18/10/14 14:30. Intended to	
1-Oct	PILOT	VERA SU	Bull
		no. 2 poor picture and gyro input inoperative	
	port. ETA Grove 1800/21.	no. 2 poor picture and gyro input inoperative	e. Mastel states the will have a
1-Oct	VTS 15	PRIDE OF YORK	Sea Reach
		reports: Still running on 3 out of 4 main eng	
epairs.			
1-Oct	MASTER / CAPTAIN	LADY AMALIA	Rosse Reach
eports eng	gine overheating on reduced s	peed vessel inbound for Grove.	
	r cancels berthing returning to		
2-Oct	VTS 15	RMS SAIMAA	KGD
		el departing the Humber for Rotterdam	
3-Oct	VTS 15	BEAUMARIS BAY	Humber
		a gear box fault. Starboard engine is fully o imsby fish dock ADM advised.	perational, craft en-route to
4-Oct	VTS 15	MIKHAIL LOMONOSOV	Chequer
		ble error. Destination: Albert dock Hull SE c	
		arranged for gyro to be repaired alongside.	
6-Oct	VTS 14	ARCO BECK.	Spurn L/F
		due to lube oil pump failure. Port engine fully	
	Alexander dock Hull MMS be		
8-Oct	VTS 15	ASIA RUBY 1	HIT
		informs VTS that the engine controls are inc	
		and that if allowed to sail, then two addition	nal tugs will be required. Duty
	formed and tug company cont		and you has normalization to sail
		problem has been resolved and that the ve	ssel now has permission to sail
	allonal lug.		
ith one ad	l sails for Ventspils		
ith one ad 755 Vesse	l sails for Ventspils.	EEMS COAST	Goole
rith one ad 755 Vesse 9-Oct	VTS 15	EEMS COAST king towards Goole Middle pier. Helm would	Goole only go to 10 degrees either
rith one ad 755 Vesse 9-Oct ilot reports	VTS 15	king towards Goole Middle pier. Helm would	
rith one ad 755 Vesse 9-Oct ilot reports ide. Maste	VTS 15 that, after swinging, and bac	king towards Goole Middle pier. Helm would	
ith one ad 755 Vesse 9-Oct ilot reports de. Maste 1-Oct	VTS 15 s that, after swinging, and bac r states that problem will be in VTS 15	king towards Goole Middle pier. Helm would vestigated.	l only go to 10 degrees either Spurn L/F
ith one ad 755 Vesse 9-Oct ilot reports de. Maste 1-Oct essel has 1-Nov	VTS 15 s that, after swinging, and bac r states that problem will be in VTS 15 one inoperative bow thruster a VTS 14	king towards Goole Middle pier. Helm would vestigated. ATLANTIC CARRIER and stern thruster. Immingham dock informe MARGARETA B	d only go to 10 degrees either Spurn L/F ed, berthing 1 quay at 1615 hrs. Spurn L/F
rith one ad 755 Vesse 9-Oct ilot reports ide. Maste 1-Oct essel has 1-Nov ilot reports	VTS 15 s that, after swinging, and bac r states that problem will be in VTS 15 one inoperative bow thruster a VTS 14	king towards Goole Middle pier. Helm would vestigated. ATLANTIC CARRIER and stern thruster. Immingham dock informe MARGARETA B erates up to 75%. Immingham dock advised	d only go to 10 degrees either Spurn L/F ed, berthing 1 quay at 1615 hrs. Spurn L/F d.
ith one ad 755 Vesse 9-Oct ilot reports de. Maste 1-Oct essel has 1-Nov ilot reports 4-Nov	VTS 15 that, after swinging, and bac r states that problem will be in VTS 15 one inoperative bow thruster a VTS 14 that the bow thruster only op PILOT	king towards Goole Middle pier. Helm would vestigated. ATLANTIC CARRIER and stern thruster. Immingham dock informe MARGARETA B erates up to 75%. Immingham dock advised PEAK BERGEN	d only go to 10 degrees either Spurn L/F ed, berthing 1 quay at 1615 hrs. Spurn L/F d. Spurn L/F
ith one ad 755 Vesse 9-Oct ilot reports ide. Maste 1-Oct essel has 1-Nov ilot reports 4-Nov one radar il	VTS 15 that, after swinging, and bac r states that problem will be in VTS 15 one inoperative bow thruster VTS 14 that the bow thruster only op PILOT poperative. Master intends to	king towards Goole Middle pier. Helm would ovestigated. ATLANTIC CARRIER and stern thruster. Immingham dock informe MARGARETA B erates up to 75%. Immingham dock advised PEAK BERGEN repair soonest. Vessel bound Grove ETA 1	d only go to 10 degrees either Spurn L/F ed, berthing 1 quay at 1615 hrs. Spurn L/F d. Spurn L/F 730/04
rith one ad 755 Vesse 9-Oct ilot reports ide. Maste 1-Oct essel has 1-Nov ilot reports 4-Nov one radar in 0-Nov	VTS 15 that, after swinging, and bac r states that problem will be in VTS 15 one inoperative bow thruster a VTS 14 that the bow thruster only op PILOT noperative. Master intends to VTS 14	king towards Goole Middle pier. Helm would vestigated. ATLANTIC CARRIER and stern thruster. Immingham dock informe MARGARETA B erates up to 75%. Immingham dock advised PEAK BERGEN	d only go to 10 degrees either Spurn L/F ed, berthing 1 quay at 1615 hrs. Spurn L/F d. Spurn L/F
rith one ad 755 Vesse 9-Oct filot reports ide. Maste 1-Oct 2essel has 1-Nov filot reports 4-Nov One radar in 0-Nov 2essel has	VTS 15 that, after swinging, and bac r states that problem will be in VTS 15 one inoperative bow thruster a VTS 14 that the bow thruster only op PILOT noperative. Master intends to VTS 14 only one engine in operation.	king towards Goole Middle pier. Helm would ovestigated. ATLANTIC CARRIER and stern thruster. Immingham dock informe MARGARETA B erates up to 75%. Immingham dock advised PEAK BERGEN repair soonest. Vessel bound Grove ETA 1 WINDCAT 18	d only go to 10 degrees either Spurn L/F ed, berthing 1 quay at 1615 hrs. Spurn L/F d. Spurn L/F 730/04 Chequer
vith one ad 755 Vesse 9-Oct Vilot reports ide. Maste 1-Oct 2essel has 1-Nov Vilot reports 4-Nov One radar in 0-Nov 2essel has 5-Nov	VTS 15 that, after swinging, and bac r states that problem will be in VTS 15 one inoperative bow thruster only op VTS 14 that the bow thruster only op PILOT noperative. Master intends to VTS 14 only one engine in operation. MASTER / CAPTAIN	king towards Goole Middle pier. Helm would ovestigated. ATLANTIC CARRIER and stern thruster. Immingham dock informe MARGARETA B erates up to 75%. Immingham dock advised PEAK BERGEN repair soonest. Vessel bound Grove ETA 1 WINDCAT 18 SOLENT FISHER	d only go to 10 degrees either Spurn L/F ed, berthing 1 quay at 1615 hrs. Spurn L/F d. Spurn L/F 730/04 Chequer Middle Gby
rith one ad 755 Vesse 9-Oct Filot reports ide. Maste 1-Oct 'essel has 1-Nov Filot reports 4-Nov One radar in 0-Nov 'essel has 5-Nov Vhile passi	VTS 15 that, after swinging, and bac r states that problem will be in VTS 15 one inoperative bow thruster at VTS 14 that the bow thruster only op PILOT noperative. Master intends to VTS 14 only one engine in operation. MASTER / CAPTAIN ng the Tioxide Outfalls, the m	king towards Goole Middle pier. Helm would ovestigated. ATLANTIC CARRIER and stern thruster. Immingham dock informe MARGARETA B erates up to 75%. Immingham dock advised PEAK BERGEN repair soonest. Vessel bound Grove ETA 1 WINDCAT 18	d only go to 10 degrees either Spurn L/F ed, berthing 1 quay at 1615 hrs. Spurn L/F d. Spurn L/F 730/04 Chequer Middle Gby
vith one ad 755 Vesse 9-Oct Vilot reports ide. Maste 1-Oct Vessel has 1-Nov Vilot reports 4-Nov One radar in 0-Nov Vessel has 5-Nov Vhile passi o anchor in	VTS 15 that, after swinging, and bac r states that problem will be in VTS 15 one inoperative bow thruster a VTS 14 that the bow thruster only op PILOT noperative. Master intends to VTS 14 only one engine in operation. MASTER / CAPTAIN ng the Tioxide Outfalls, the m the Hawke Anchorage.	king towards Goole Middle pier. Helm would vestigated. ATLANTIC CARRIER and stern thruster. Immingham dock informe MARGARETA B erates up to 75%. Immingham dock advised PEAK BERGEN repair soonest. Vessel bound Grove ETA 1 WINDCAT 18 SOLENT FISHER aster reports that the vessel is suffering main	d only go to 10 degrees either Spurn L/F ed, berthing 1 quay at 1615 hrs. Spurn L/F d. Spurn L/F 730/04 Chequer Middle Gby n engine problems and would like
ith one ad 755 Vesse 9-Oct ilot reports ide. Maste 1-Oct essel has 1-Nov ilot reports 4-Nov one radar in 0-Nov essel has 5-Nov /hile passi o anchor in	VTS 15 that, after swinging, and bac r states that problem will be in VTS 15 one inoperative bow thruster a VTS 14 that the bow thruster only op PILOT noperative. Master intends to VTS 14 only one engine in operation. MASTER / CAPTAIN ng the Tioxide Outfalls, the m the Hawke Anchorage. anchored in position F in Ha	king towards Goole Middle pier. Helm would ovestigated. ATLANTIC CARRIER and stern thruster. Immingham dock informe MARGARETA B erates up to 75%. Immingham dock advised PEAK BERGEN repair soonest. Vessel bound Grove ETA 1 WINDCAT 18 SOLENT FISHER	d only go to 10 degrees either Spurn L/F ed, berthing 1 quay at 1615 hrs. Spurn L/F d. Spurn L/F 730/04 Chequer Middle Gby n engine problems and would like

Inspection of turbo reveals a hole in the casing, vessel has ordered spares being delivered Monday. V/I remaining at



	545 Master informs VTS that	Ships	General Location
17/11/14 15 19/11/14 02	545 Master informs VTS that		
		t spares will arrive Tuesday 18th.	
		v/l departs the Humber for Aberdeen.	L burgh a g
	MASTER / CAPTAIN	<b>CENTRICA PRIDE</b> 11 2200 for starboard engine pitch repairs.	Humber
		be achievable when entering Immingham.	
Repairs to l	be carried out AM 17/11/14.		
6-Nov	MASTER / CAPTAIN		Humber
	nd Howdendyke eta 0200 1	faulty, only one anchor available. 7/11/14	
9-Nov	VTS 15	FLUVIUS PLYM	Chequer
vilot report	s that the bridge telegraph is	inoperative. Operating on emergency telegra	
0-Nov	VTS15	BRITANNIA SEAWAYS	IOH
		come fouled. Starboard engine disengaged. I	Duty manager informed.
2045 Vesse 24-Nov	el proceeding outbound with VTS 14	GLOVIS CHALLENGE	Spurn L/F
	-	gham Outer Harbour 1920 24/11/14	
6-Nov	VTS 15	WINDCAT 4	Hawke
	anchor and 10m of cable ar	nd 10m of rope in position 53 23.871 N 000 0	04.820 E to the west of the Hawk
ght float.	: Grimsby river terminal. Gri	maby ADM advised	
	anchor 27/11/14 1425	hisby ADM advised.	
7-Nov	VTS 15	LIV KNUTSEN	Sea Reach
		c pressure to the main engine and is not unde	
		ast made and berth advised. 0750 vessel dec	lares problem fixed, but now too
ate to mak	AGENT	p proceeding to the DW anchorage	HIf
	_	WA (Posn 'L') is now unable to use engines d	
epaired. A	gent arranging for lavby ber	th to effect repairs. Duty manager advised. M	CA advised. 22 POB (20 crew + 2
		DO 41.8t. Ballast condition, inert but NOT gas	
		or tug to be available for immediate deployme	
		Immingham to tow Liv Knutsen to Rotterdam.	
3-Dec		VTS area on route to Rotterdam. CG informe	Paull
	_	ror is remaining steady and not causing any n	
ound for A			
4-Dec	VTS 15	KEY BAY	Spurn Point
		noperative. Vessel bound for Immingham We	est Jetty.
laster con 5-Dec	firms that the defect will be i PILOT	ALFA GERMANIA	Humber
	_	ty on the radar is not operational. Vessel on p	
6-Dec	PILOT	CHEMBULK YOKOHAMA	Sea Reach
	s Gyro compass inoperative	vessel using magnetic. Vessel bound Imming	pham West Jetty eta 16/12 2359.
7-Dec	PILOT	BIENVILLE	Bull
		perating on engine room control. Vessel inbo	ound for Goole (South West
9-Dec	A 18th Dec 0400. VTS 15	GEOPOTES 15	Bull
		ers are working. Vessel operating in the river	
2-Dec	VTS 15	DOGGERSBANK	Cleeness
lassels has	w thrusters is inoperative. A	DM Immingham advised Berthing: Imminghar	n dock 6 quay ETA 0530
	VTS 15	WINDCAT 18	Humber
7-Dec		way windfarm reports on one engine and taki	ng water through the stern gland
7-Dec Vindcat 18			
?7-Dec Vindcat 18 essel pum	ps controlling ingress. Hum	per Coastguard, ADM GY & Fish dock advise	d. ETA Fish dock 1030.
7-Dec Vindcat 18 essel pum 9-Dec	ps controlling ingress. Hum		







Г

	Defect (Pile	ot Ladder) Reporte	ed
Date	Reported By	Ship	General Location
04-Jan	PILOT LAUNCH	KREMPERTOR	Haile Sand
Launch deckhan has been advise Destination King	d to replace.	e pilot ladder has a large split running a	all the way through it. Master
14-Jan	PILOT LAUNCH	ANKE EHLER	Spurn L/F
Pilot launch repo	orts no spreaders on pilot ladder	when boarding.	
15-Jan	PILOT LAUNCH	VASILIY SHUKSHIN	Chequer
	n reports that one of the side rop ige to Flushing, ETA unknown.	es above the 3rd rung from the bottom	of the ladder was parted.
15-Jan	PILOT	SARPEN	Humber L/F
	bination rig did not have securing from the TMB to Tees.	g's for ladder by way of platform, as req	uired by IMO.
31-Jan	COXSWAIN	FEDERAL ST LAURENT	Spurn L/F
	tion ladder to disembark pilot (pi	o be in poor condition and possibly war lot ladder only, freeboard 7.5m).	ped. Decision made not to
04-Feb	VTS 15	LEIRIA	Spurn Point
whipping are frag	yed. This was the second pilot la to replace before next visit.	condition, some of the steps are cracked dder to be used as the pilot expressed	
17-Feb	LAUNCH	STEN AURORA	Spurn L/F
Launch deckhan on the next visit. Next port Murma		pears frayed. Master advised and state	d a new ladder will be used
23-Feb	VTS 15	ARGYROULA	Spurn L/F
advised.	vise the that winnets on the spreading George dock 12 shed.	ader are missing, causing the step to b	ecome very loose. Master
24-Feb	PILOT LAUNCH	CEPHEUS J	Spurn L/F
advised.		ader are missing, causing the step to b 345. Departing 0115 25th to Rotterdam.	
20-Mar	VTS 15	SUNNANHAV	Spurn L/F
before departure		e worn and need replacing. Master inte	nds to replace the ladder
21-Mar	PILOT		Spurn L/F
	-	pair appears to have been made.	
Next port Iceland			Course Deint
25-Mar Pilot reports that	VTS 15	ANTARI are in an unsatisfactory condition. Ves	Spurn Point
	e remedial action.		
29-Mar	PILOT	ORANESS	Spurn Point
Gate at disemba for the pilot. Mas Destination: Ros	ster is aware.	n IMO regs) with no stanchions availab	le so limited handrail options
30-Mar	PILOT	PAPER MOON	Chequer
Ladder was not		the ships handrails and therefore not rig on. Master has been advised to rig corre	
31-Mar	LAUNCH COXSWAIN	SCANLARK	Spurn L/F
Pilot launch repo Next port Amrun		Winnets loose and lashings in poor co	ndition. Master advised.
01-Apr	VTS 15	PHANTOM	Spurn L/F
	/ before next visit.	mmets and that the ladder is in general	ly poor condition. Master
01-Apr	PILOT	H & S FAIRNESS	Spurn Point
	I	I	I



	Defect (Pilot Ladder) Reported				
Date	Reported By	Ship	General Location		
	securing eyes on deck to secure	pilot ladder. Ladder secured to vessels	rail.		
03-Apr	ck Hull ETA 1930 PILOT	WILSON MAAS	Spurn Point		
		r winnets loose and ladder not securely	1		
Vessel Master a Next port Ostend	dvised.				
08-Apr	VTS 14	ENERGY CHAMPION	Humber		
	Master advised to rectify before s	iteps too far apart, ladder not secured t ailing.	o ships side. Dimensions		
09-Apr	PILOT	TWISTER	Spurn L/F		
	ucted by a spreader step of the pi	r ships rail to pad eyes. Pilot had to ste ilot ladder. Master advised.	ep into the gate access which		
18-Apr	PILOT LAUNCH	WARNOW STAR	Spurn L/F		
	s the spreader is step number 8 a for Humber International Termina	and the ladder appears to be in poor co	ndition.		
27-Apr	VTS 15	SKAGEN	SLF		
	ngly and agreed to rectify the issu	he handrails and that no deck lugs wer ie.	e available for securing. Ship		
02-May	PILOT	THRESHER	Spurn L/F		
Question from V	Pilot ladder is secured to the railings and not the deck. Captain reports that they always do it that way. Following the Question from VTS "Can you confirm that your pilot ladder is properly constructed and recently inspected, is in good condition and will be rigged as per IMO requirements" the reply from the ship was affirmative. The pilot still embarked				
03-May	PILOT	NEPTUNE	Spurn Point		
will inspect with inbound for Goo	Master and advise him according	r has rags and canvas lashed to the roj Jly. VTS advised pilot it must be rectifie 05/14. 1830 Pilot reports new ladder or the old ladder.	d before departure. Vessel		
07-May	VTS 15	LADY ALEXANDRA	Haile Sand		
	ed to the deck in the future.	s secured to the ships handrails. Maste	er advised that the ladder		
09-May	PILOT	STOLT CORMARANT	Spurn L/F		
		aster declares that lugs will be fitted to Id be fitted at the earliest opportunity	the deck when the ship next		
09-May	PILOT	STOLT CORMARANT	Haile Sand		
	t the pilot ladder was rigged to th end, berthing PM 9th after tank c	e handrails and had to climb around th	e gate to get to the ladder.		
10-May	VTS 15	CETUS J	Spurn L/F		
		advised to rectify before departure.			
12-May	gham dock 8 quay 1230. Departir PILOT	NORDIC	KGD		
Approx. 1710 KC proceeded out o ladder not rigged that it is not poss the situation can KGDk telephone	Description of the second seco	t the pilot was on deck checking the pilot 719 Pilot contacted VTS for clearance t deck). Pilot has discussed matter with s ce given with caveat that vessel may ha await further instructions after liaising gainst the red light. 1745 KGDk telepho ie ladder now rigged to the ship's deck	t ot ladder and the ship has o depart and reported pilot ship's master and advised ave to return to the dock if with Harbour Master. 1730 oned with information from		
15-May	LAUNCH COXSWAIN	CAPELLA	Chequer		
		der before pilot boards. 0408 Ladder c . 0411 Pilot boarded and reports ladder			
05-Jun	VTS 15	OSTEREMS	Chequer		
Pilot reports that the handrails. V/	the v/l's pilot ladder does not cor L advised that no alternative ladd destination Grimsby.	nply with regulations, namely 10 steps ler was available. Pilot returning to GY.	, no spreader, and rigged to		
29-Jun	VTS 15	FILIA FAITH	Spurn L/F		



<u>I</u> BP	HUMBER   ESTUARY	SERVICES
-------------	---------------------	----------

Date	Reported By	Ship	General Location
		pilot ladder, were uneven due to mis	
and said that the bassage.	ere was a new ladder available a	nd that it would be used in future. To	be checked on outward
Berthed Imming	ham Dock.		
30-Jun	VTS 15	JEROME H	Chequer
		ships railings and the master inform	
deck amid ships	s. After departing Immingham, the or condition all round. He added	alongside the ship, the coxswain no pilot informed VTS that the ladder h that the master was reluctant to use a	e was to use had no spreader
08-Jul	VTS 15	NOVA CURA	Spurn L/F
namely, made fa	t several steps were loose on the ast to the railings. Master had been nmingham Dock.	pilot ladder. Ladder securing arrang en informed.	ements were not satisfactory,
09-Jul	VTS 15	KATI	Spurn Point
Launch 'Neptun Next port Rotter		dder has no spreaders. Master inforn	ned.
19-Jul	VTS 15	AFRICAN HIGHWAY	Spurn L/F
Pilot launch rep	orts that the ladder was not fitted		
	rimsby River Terminal.		
22-Jul	VTS 15	SCAN FJORD	Haile Sand
Destination: Eer	•	the ship's rails and not to the deck as	requirea.
27-Jul	LAUNCH	CETUS J	Spurn L/F
Pilot ladder did Next port Rotter		cers. Captain stated that it was import	ssible as the ladder is new.
27-Jul	LAUNCH	LADY NOVA	Spurn L/F
the launch atten Berthing Flixbor	nding. ough PM 27th. ETD 28/7/14 192		
29-Jul	VTS 15	FLINTERBOTHNIA	Haile Sand
	as used out of 15 steps. Master a	ured to the ships rails and not to the p dvised to rectify before return.	
10-Aug	PILOT	ANDRE W	Spurn Point
oarted. Pilot deo		conditions, when the pilot started to c as rigged and the pilot boarded. Duty 0/08 at 1900.	
12-Aug	PILOT	GRONA BIESSUM	Spurn Point
and possibly no	0	he Pilot ladder was secured to a bar t A 2100 12/08/14.	that seemed in poor condition
14-Aug	PILOT	NEKTON	Chequer
	pilot ladder access inadequate, I for Goole South Dock ETA 14/08	adder rigged between two bollards. 2200.	
23-Aug	PILOT LAUNCH	ULTRAMAR	Spurn Point
•	orts no spreader on the ladder. d destination unknown.		
01-Sep	PILOT LAUNCH	NORDFJORD	Spurn L/F
will check the la	aunch was boarding the pilot, the dder and carry out repairs as neo ningham dock 9B Min quay 1/09/		oden step. Master advised and
13-Sep	LAUNCH	ANNELISE THERESA	Spurn L/F
The bottom spre Next port Sluisk	eader on the pilot ladder is loose. il	Master advised.	
14-Sep	PILOT	SUDERAU	Haile Sand
on next visit.		nerally the ladder is in a poor condition	on. Master advised to replace
Next port: Ghen 23-Sep	VTS 12	FPMC 17	HLF
-0 00p	1012		




	Defect (Pilo	ot Ladder) Reporte	d		
Date	Reported By	Ship	General Location		
On disembarking the vessel at the Humber Light Float the pilots report that the ladder is in a poor state of re loose and uneven steps. VTS advise Master to renew ladder as soon as possible. Vessel bound to sea for orders.					
20-Oct	VTS 15	SALLIE KNUTSEN	Humber		
handrails. Also th		correctly rigged. Namely, the rope ladd ot secured against the ships side. stination unknown.	er was secured over the		
30-Oct	VTS 15	BODIL KNUTSEN	Humber		
		er rigged. Pilot reports that the ladder v m, as required. Note inserted on PAVIS			
08-Nov	VTS 15	JEROME H	Chequer		
On discussion wi	th the master, the master stated	eports that the ladder is still incorrectly that the French authorities had approv the deck at the earliest opportunity.			
26-Nov	LAUNCH	SELFOSS	Spurn Point		
The securing sha Next port Rotterd	ackle failed, but was swiftly replace lam.	ced.			
01-Dec	VTS 15	MORNING CHAMPION	Sea Reach		
Pilot reports that	there are only three steps below	the lowest spreader. Pilot will inform m	naster.		
03-Dec	VTS 15	AHMET CIHAN	Spurn Point		
before departure		lot ladder has a spilt in it. Master advis orders at present.	ed this will be replaced		
05-Dec	VTS 15	PAPER MOON	Spurn Point		
Pilot ladder was a Destination: Aber		nd not in accordance with IMO regulation	ons.		
16-Dec	PILOT LAUNCH	EVERBRIGHT	Humber		
condition. Pilot re and unable to rig reported inoperat	Pilot launch reports starboard ladder in poor condition. Vessel asked to rig port ladder and confirms in good condition. Pilot reports starboard ladder homemade, step spacing incorrect, lose lashings and incorrectly secured and unable to rig against ships side. Port ladder good condition but still not quite against ships side. Port radar also reported inoperative. Vessel inbound for IOT 1 ETA 0130 17/12.				
21-Dec	COXSWAIN	FLUVIUS TAW	Chequer		
	l lashed to the handrails and not ir ngham dock 9B quay. ETA 1615	n accordance to IMO regulations.	1		



	Anchorage Problems			
Date	Ships Name	Remarks		
16-Apr	SPIRIT OF HOTON	Wind Farm vessel Spirit of Hoton departed Grimsby and requested training near to the 4B Buoy. Soon after he reported losing his anchor. Position 53.34.9 N 000.00.6 E Agent, North Sea Services. Working for EON.		
14-Aug	NOVATRANS	Vessel at the deep water anchorage, Master declares unable to heave anchor due to windlass problems. 1825 Master reports windless operational and is proceeding to pilot station. Vessel bound for Immingham Dock 9B Mineral Quay 14/08 2000.		









	Reported By	Ships	Location	
10-Feb VTS 15		NAVION SCANDIA		
		HARM JOHANNES	New Sand Hole	
north crosse CH14. VTS hen procee and request	es ahead of the PPV in vio contacts FV on CH16 an eded to attempt to pass th ted to stay east of the win	ey Monobuoy in NSH TSS. Fishing Vessel "Harm Johannes" (2YZH) trans cinity of North Binks Buoy. FV did no report to VTS, AIS was defective and d asked her intentions. VLS had to go astern on her engines as the FV pa- rough the Gateway Windfarm. FV warned by VTS about the close quarters d farm. Further Navigation Assistance was then required for the FV to safe v close to North New Sand Buoy.	l was not listening to ssed close ahead and s situation/AIS defect	
13-Feb	VTS 12	AB LIVERPOOL	Albert Dock	
Pilot Nedyla	akov.			
	DH OT	BOMAR PLUTO		
17-Feb	PILOT	SCOTSMAN	Sunk Spit	
	l otsman, in very poor visibi between Sunk Spit and th	l lity, made a dangerous manoeuvre in respect of the 2 inward vessels: Bor le Ridge	I nar Pluto and Stavfjord	
		CATCH 22		
01-Apr	OWNER	AnneThierry M199	<ul> <li>Grimsby Approache</li> </ul>	
		el off Cleethorpes beach reports outbound fishing vessel Anne Thierry pa . The Catch 22 reported he was anchored with anchor lights and has a rad		
30-Apr	VTS 14	PLEASURE CRAFT	Spurp Doint	
30-Api		PRIDE OF HULL	<ul> <li>Spurn Point</li> </ul>	
seemed uns was South o ocation and ntentions b nad a magr proceeded	sure of her location and w of Spurn Head and was c d requested to speak bridg ut was forced to go astern hetic compass and advise to buoy-hop to Grimsby. V on giving warnings and t	sby Marina contacted VTS 2100 to advise her intention to enter the river a as requested to keep to the starboard side of the channel. Launch Neptun rossing the channel to Bull Lt Float. Outward Pride of Hull at Cleeness was ge to bridge with Trotton if in doubt. 2120 Pride of Hull made contact and to h when Trotton seemed unable to maintain a steady heading. 2124 Pride of d Trotton to proceed West. Trotton eventually entered the Bull anchorage /TS Humber were unable to track the Trotton due to not having a working raffic information based on the information from vessels in the vicinity. Info	e advised that Trotton advised of the vessels ried to establish Trotton of Hull asked if Trotton towards the No 4 and Spurn Head radar, and	
03-Sep	MASTER / CAPTAIN	LERRIX	New Sand Hole	
00 000		HORST B		
nanoeuvre	the Horst B passed less t	oncern with regards to overtaking manoeuvre of the Horst B. Upon comple than a cable off the Lerrix starboard bow. 0845 Pilot reports after boarding rtaking the Lerrix and this caused the ship to sheer to starboard. The vess	the Horst B that the	
	PILOT	GERD	ют	
21-Sep		ORION		
21-Sep				
•	concern to PEC holder o	ver closeness of their ships when passing IOT1		
•	concern to PEC holder o	HUMBER MERCURY	Cleeness	
Pilot voices 09-Nov	LAUNCH COXSWAIN	1		
Pilot voices 09-Nov Pilot launch	LAUNCH COXSWAIN Mercury outward from G	HUMBER MERCURY WINDCAT 11		











Date	Ships Name	Remarks / Statement
12-Jan-14	MEKHANIK SEMAKOV	Pilot reports touching bottom in the vicinity of the 22 A buoy. LAT 42.7 N 0 22.7 W. Albert gauge 5.51 -14cm, Humber bridge 4.78 Mtrs. Mekhanik Pustoshnyy confirms touching bottom in same position ten minutes later.
12-Jan-14	MEKHANIK PUSTOSHNYY	Pilot reports that the vessel touched bottom and came to a stop momentarily. In position approx. 1.1 cables SW of the 32 light but Brough gauge 5.07m
13-Jan-14	CEMSKY	Advised touched bottom vicinity 22A inwards Humber Bridge 4.9
19-Jan-14	STOLT RAZORBILL	Piermaster reports that vessel grounded temporarily off berth whe departing SEJ1 outward for sea. No report from Pilot.
03-Feb-14	PILSUM	Vessel grounded opposite Adlingfleet Drain WWD 5.91. 2040 Refloated proceeding to TGF.
12-Feb-14	BEAUMAIDEN	Pilot reports aground mid river opposite Waterton Light River Tre 1712 refloated resume outward passage.
03-Apr-14	ICELANDICA HAV	Vessel grounded Trent Ness inbound for Grove. 2140 Refloated proceeding to berth.
15-Apr-14	FLINTERBOTHNIA	Vessel Touched Bottom' between the No 32C and No 34 buoys. WWD Gauge 5.55m and Brough gauge 5.93m. Vessel continued passage to Goole.
19-Apr-14	NOORDVLIET	Vessel inbound draft 5.3m. Touched Bottom and sheared heavy Port between the No 32C and No 34 buoys. Approximate pos: 53.42.9N 000.38.09W. WWD Gauge 5.6m and Brough gauge 6.0 Vessel continued on passage to Flixborough SE.
19-Apr-14	CRISTINA	Vessel outbound draft 5.3m. Touched bottom between the No 32 and No 34 buoys. Approximate position the same as Noordvliet p 53.42.9N 000.38.09W. Pilot reports he was inside the line. WWE Gauge 5.97m and Brough gauge 6.52m. Vessel continued on passage to sea.
23-Apr-14	ELBETOR	0132 V/L suffered steering gear breakdown and ran aground off t Apex. WWD Gauge 4.68m. 0144 V/L refloated and proceeding o passage. Steering gear problem rectified. No reported damage o pollution. Next port unknown. 1200/24th DVTSM informs MAIB of incident via telephone/ internet.
28-Apr-14	ASTRA	Vessel inbound for Grove draft 5.3m. Touched bottom between to No 32C and No 34 buoys. Approximate position the pos: 53.4321 000.37.52W. WWD gauge 5.58m and Brough gauge 6m. Vessel continued on passage.
02-May-14	ANTWERP	Vessel "touched bottom" on the course line in the vicinity of 32C. Gauges: Brough 5.03m & Wwdyk 4.50m
03-May-14	RICHELIEU	
21-May-14	ANITA	Vessel touched bottom close to the Upper Whitton and stopped i the water. Vessels draft 3.7m WWD 4.48m. Brough 4.95m. Vess continued on passage.
28-May-14	HELSINKI	Vessel in bound for Goole draft 5.5 reported touching bottom at t 34C buoy. Apex 5.84 mtrs & Brough 6.16 mtrs. Vessel continued passage.
03-Jun-14	NIKAR G	V/L 'touched bottom' in the vicinity of the Upper Whitton Lt Float. Brough gauge 5.35m. V/l inbound for Goole.
03-Jun-14	EEMS STAR	V/L' touched bottom' in the vicinity of the No 34 buoy. Brough gat 5.3m. West walker dyke 4.88. V/l inbound for the Trent.
13-Jun-14	CELTIC EXPLORER	Whist departing Grove LM1 berth a rope parted (no one injured) the vessel was set across to the opposite side of the river where grounded. (Bow to midships) 9 POB, cargo of broken glass, 21.7 m.cu F.O. 1904 C/G advised. 2005 refloated and proceeding bar alongside Grove berth. 2031 secure alongside LE1. Duty manag- advised.
18-Jun-14	NEULAND	Vessel approaching Goole, Ocean lock, Pilot reports that whilst swinging vessel, the stern came into contact with the river bank. discernible damage observed.
20-Jun-14	FAST WIL	Vessel touched the bottom briefly passing Grove Dolphin.
21-Jun-14	PROGRESS	Pilot reports touching bottom approaching the 34 buoy. Position 9 42.6 N 0 39.4 W. West walker dyke gauge 4.84 Metres. 8 POB, Cargo: Timber 3061m3 Fuel oil 16.1T MGO, Lub oil 2168 Litres 1332 Vessel refloats WWD 5.02 Metres, Proceeding to Goole.
24-Jun-14	ANMAR S	Vessel touched bottom close to 34 buoy.
25-Jun-14	HESTIA	Pilot reports vessel aground in approx. position: No 34 It.float brg 200 x 2 cables. WWD gauge 5.19m. Vessel refoloats and continu




Date	Ships Name	Remarks / Statement
25-Jun-14	HOOGVLIET	Pilot reports that vessel touched bottom as it approached No.34 lig buoy. WWD gauge 4.86m.
27-Jun-14	LADY CLARA	Approaching no 34 light buoy. Pilot reports vessel touching bottom WWD gauge 5.24m.
29-Jun-14	LUHNAU	Pilot reports vessel grounding in approx. position: 1.5 cables ENE no.34 light.buoy. Vessel then refloated almost immediately and continued passage to Goole. WWD gauge 5.16m.
04-Jul-14	NOEST	Pilot reports touching bottom approaching the 34 buoy. West Walk Dyke gauge 4.63m. Destination: Howdendyke
12-Jul-14	ELISABETH GRACE	14m motor cruiser aground near Blacktoft. Humber Coastguard advised and in direct contact with the vessel. 17:15 Refloated and resume passage.
13-Jul-14	NELLI	Vessel inbound for Gunness draft 5.3mtrs, temporarily grounded 1 cable 250deg from the Upper Whitton Float. Apex 5.6m, Brough 6.07m.
20-Jul-14	NINA	V/L 'touched bottom' just east of the No 32 buoy. Bridge gauge 5.36m Brough gauge 4.48m. V/L continued on passage.
23-Jul-14	CELINE	Touched bottom in a position south of Burton Stather.
24-Jul-14	MEKHANIK BRILIN	Pilot reports touching bottom approaching the Middle Whitton, position 53 43.3 N 000 35.39 W. Brough reading 5.25m. 1804 Vessel touched bottom in position 53 42.7 N 0 39.27 W near 34 buoy. Vessel aborted passage to Blacktoft.
30-Jul-14	YACHT PRIME TIME	Yacht 'Prime Time' runs aground on the Binks. Yacht declares no assistance required and awaiting flood while anchored. 1535 Yacl re floats and declares all is in order and proceeding to the Hull Marina.
02-Aug-14	PROGRES	<ul> <li>Pilot reports that the vessel is aground at Goole bight. Goole tide gauge 4.45m and falling water.</li> <li>CG and duty manager informed. No damage or pollution reported.</li> <li>Cargo 2610t of timber. Bunkers 22t of MDO. POB 8 (Including Pilot V/L to order tug assistance for refloating at approx. 1130/2nd. Tug Shovette to assist departing Albert Dock at 0730.</li> <li>1140 Vessel refloated, proceeding to Goole. 1236 All fast Goole S corner.</li> </ul>
02-Aug-14	ARSLAN 1	V/L' touched bottom' in the vicinity of the No 34 buoy. Gauges WV 4.20M. Brough 4.67m. V/L continuing on passage.
03-Aug-14	SEE STERN	0935 V/L reported aground near the No32 buoy. Gauges Bridge 4.76m. Brough 3.68m. 0944 V/L refloated and proceeding inwards No damage or pollution. Duty manager informed.
08-Aug-14	AMARETTO	Report of pleasure craft aground upstream of Victoria lock, vessel has a slight list but currently does not require assistance. 2 POB, HMCG advised. 1525 Vessel refloated proceeding to Hull marina.
08-Aug-14	SPIDER T	Vessel aground in the vicinity of the 23 buoy. Position 53 42.64 N 000 23.95 W, Humber Bridge tide gauge 2.15m. 5 POB, No assistance required. All ships broadcast made and HMCG advised
23-Aug-14	NORDICA	Outward from Grove grounded at Mere Dyke. Max draft for tide ar tide cutting 10cm at Albert Dock. Refloated immediately, but returning to berth.
24-Aug-14	CELTIC VENTURE	Pilot reports touching bottom inbound for Goole draft 5.35m, half a cable East of the Middle Whitton Float. WWD 5.25m & Brough 5.6 Vessel continued on passage.
25-Aug-14	SMARAGD	Grounded near to Middle Whitton Lt Flt (Brough 5.30m). Refloated immediately.
04-Sep-14	SPIRIT OF HOTON	Report from Humber coastguard, at 0155 the windfarm support cr. was assisting with the search for the MOB around Grimsby area a ran aground on Cleeness sands. Pos'n 53 34.32 N 000 01.43 E. 4 POB. 1219 Refloated and proceeding to GY fish dock with assistance of Cleethorpes lifeboat.
07-Sep-14	NESS	1740 KGD advises vessel on the mud departing Albert Dock. Tug Beamer in attendance. Albert Gauge 7.15 High Water at 1756. De on outer sill 8.4m 1746 KGD advises vessel now clear of the mud now backing into the lock before departing using spring on to the I nose. 1800 KGD advises level is now finished. Tug assisting on th bow. 1810 Vessel clear of the lock and proceeding on passage. N damage or pollution reported. Cargo baled waste. 9 Crew. 107 M



	Summary of Groundings			
Date	Ships Name	Remarks / Statement		
07-Sep-14	ABIS ANTWERPEN	Aground off Grove berth 2. Inward for the berth Cargo Bentonite 3,700T. POB 8, HFO 93T, DO 10T C/G advised 0705. Duty manager advised tug ordered by agent. 1745 tug on scene. 1800 vessel moving. 1815 afloat and proceeding to the berth. 1828 Shovette released and en-route back to KGD. 1836 Vessel secure alongside. C/G updated. Pilot reports shoaling of approx. 1.5m 100m off Grove 2		
10-Sep-14	SVITZER MADELEINE	Aground in position 53 34.7N 000 01.6E (south of Cleeness). 5 POB, 35T DO. Spurn gauge 1.19m, Grimsby gauge 1.63m. 1208 Port House advised and C/G. Tug was inward from TMB to Immingham dock. MAIB advised by VTS Manager. 1355 Svitzer Susan departed Immingham en-route. 1442 On scene. 1522 Vessel re floated proceeding to Immingham.		
14-Sep-14	WILSON TEES	Aground between No.33 and Cappers West. 53 42.38N 000 34.14W. Brough gauge 5.55m. POB 8, Cargo: 3,489T Bunks: 12.4 T GO. 0950 underway again and proceeding to Goole		
23-Sep-14	ANTARI	0555 V/L 'touched bottom' in the vicinity of the Middle Whitton Light float. Brough gauge 5.55m. V/L inbound for the Trent.		
07-Oct-14	FLINTERBIRKA	Vessel inward for Blacktoft grounds to the North on Fax Fleet Ness. (West Walker Dyke 6.37m) Pilot declares if he refloats he will now abort to Bull Anchorage. (POB 7, 3044t steel products, DO 48t, GO10.2t). HMCG and Duty Manager advised. 0716 Deans tug ordered via agent for 1830 tonight at Pilot and Master's request. 1807 Shovette on station. 1841 Refloated. Going to Blacktoft.		
12-Oct-14	EEMS SPRING	2108 Vessel (inbound for Gunness Fina) aground on Trent Ness. WWD gauge 5.38m 2150 V/L refloated and proceeding to Gunness Fina. WWD gauge 5.95m. 2320 vessel alongside port side to. No reported damage or pollution. Duty manager informed.		
16-Oct-14	HUMBER CHARTER	Coxswain (P. Gillyon) reports that the craft grounded at Neap House whilst carrying out a survey. Craft is taking in water, but the on board pumps are coping with the ingress. 2 POB, 12,000Ltrs DO. Proceeding on 1 engine at approx. 11Kts. Expected ETA Alex Dk Hull 1530/1545. No pollution or injuries. DVTS manager and C/G advised 1435 Humber Ranger departs Alex Dk to assist/escort Humber Charter. 1510 H Ranger S'By 1556 Humber Charter returns to Hull Alexandra Dock. 1605 All fast in Alex dock, HMCG advised.		
21-Oct-14	BRITANNIA SEAWAYS	1323 Pilot arrives on bridge and reports vessel aground approx. 2 cables SE of S 1 SDC. 1333 Svitzer contacted to deploy standby/fire tug from Immingham. Standby tug Svitzer Bristol engaged sailing the Besiktas Orient off IOT 6. ETD 1330 1356 Vessel refloated and proceeding to IOH. No pollution reported or observed by PV Venus on scene. 1405 Pilot reports all appears in order. 1427 CG informed.		
23-Oct-14	SEA MELODY	Pilot reports that the vessel grounded and subsequently refloated in approx. position No.33a Light Float. Brg 098 x 0.08' Brough gauge 5.94 m. Draught 5.5m		
25-Nov-14	BEKAU	Pilot reports that the vessel grounded and subsequently refloated between the 33A and Middle Whitton light float. Vessel's draft 5.4m and Brough tide gauge 5.93m.		
07-Dec-14	HELEN ANNA	Vessel moving from Flixborough to Gunness Main grounded for a short period on the east bank near to Man Reval Lt. 0700 refloated.		
14-Dec-14	LADY MATHILDE	Pilot reports vessel touching bottom in approximate position, on the line between Cappers West and No 33 buoy approx. 0.27 cables from Cappers West. Gauge reading 4.45m Draft 4.0m.		
20-Dec-14	WILSON BRUGGE	Pilot reports touching bottom in position 53 42.62 N 000 39.19 W, to the west of the 34 buoy. West Walker Dyke gauge 5.3m.		








Contact with Sea Marks			
Date	Reported By	Details	
06-Jan	PILOT	No.15 top mark damaged. Light reported lit but at angle. DIMINISHED. 17/01/14 Buoy replaced by UKD Seahorse	
12-Feb	JUTLANDIA SEAWAYS	No.15 Holme Hook OFF STATION. Light and top mark missing. Position 2 cables NW of charted position. Buoy replaced. (20/02/14)	
27-Sep	KORIANGI	FH4 Lt Buoy OFF STATION in position: approx. 400 metres ESE of FH3 Lt Buoy. (See occurrence no.14851). 1100 29/09/14 Buoy Back On Station (UKD Seahorse)	
13-Oct	ADM KGD	Pillar Nav Mark 2FG off the entrance to Albert Dock IS DAMAGED. The light is missing and the pillar is leaning at angle 20 degrees from vertical in a NW direction.	







Date	Ships Name	Location	Remarks / Statement
02-Jan	THULE	KGD	Pilot reported vessel clipped east corner on entry to KGD lock with starboard bow.
03-Jan	WILSON LEER	Blacktoft	When going alongside Blacktoft jetty to change pilots, the ship's bow made heavy contact with the wood fendering on the east end of the jetty causing approx. 2 metres to be damaged. No apparent damage to the ship
04-Jan	CLIPPER POINT	lmm Dk	On manoeuvring for Immingham Lock vessel made contact with lockside causing damage to the vessel's rubbing band.
06-Jan	KOSSAU	Trent	Vessel shifting from Neap House 1 o Grove LE1 caused damage to a shore ladder. No damage to ship.
13-Jan KUZMA MINIM		KGD	On departing the lock the vessel made contact with the west outer lock gate causing damage to two stanchions. No damage to the vessel or pollution.
24-Jan	CLIPPER POINT	lmm Dk	Vessel manoeuvring for Imm Lock, made contact with walkway on east side of the dock. Bent walkway, no damage to vessel.
24-Jan	CLIPPER POINT	lmm Dk	Pilot reports making contact with the east outer gate walkway rails whilst entering the lock.
31-Jan	AMUR STAR	SKJ	Made contact with west end of SKJ whilst departing berth. Pilot reports damage to berth and slight damage to vessel. Slight indentation above waterline not affecting seaworthiness. Vessel proceeding to Tees.
05-Feb	AUTORUNNER	GY Royal	Vessel made contact and damaged timber on the east inner fender whilst transiting the lock, outwards to sea.
09-Feb	ATLANTIC EXPLORER	GY Royal	Whilst departing the berth at GY Royal the v/l made contact with the quay causing damage to the bow. Sailing cancelled.
11-Feb	ATLANTIC EXPLORER	GY Royal	Vessel bound to Grimsby Royal Dock. On manoeuvring for the lock the vessel mad contact with the west outer gate and caused and indentation to the vessel's stbd shoulder. No pollution or injury.
12-Feb	CLARE CHRISTINE	lmm Dk	Pilot reports making contact with lock side whilst entering lock.
12-Feb	ALINA	lmm Dk	Made contact with lock side whilst entering lock outbound. No apparent damage
18-Feb	SAXUM	Alex Dk	Made contact with west approach jetty Alexandra Dock Hull
18-Feb	MEKHANIK TYULENEV	GY Royal	Vessel bound from sea to GY Royal Dock. On entering the lock made contact to the east knuckle causing some damage to fendering.
23-Feb ARGYROULA		KGD	Pilot reports that whilst manoeuvring to enter the lock the vessels Stbd shoulder landed heavily on the east knuckle quadrant fender, sheering some bolts and causing damage to the ships bulwark.
02-Mar	MELUSINE	lmm Dk	Made contact with lock side whilst entering outbound.
03-Mar	AVALON	Goole	Fender damage on berthing in South Dock.
10-Mar	CEPHEUS J	Imm Dk	Vessel inward for Immingham Dock. Whilst making fast in the lock one spring caught a walkway stanchion causing slight damage.
12-Mar	KADRI	Blacktoft	Whilst making fast at Blacktoft jetty one of the ship's mooring lines caused damage to a stanchion and light at the eastern encourt of the jetty. Goole advised and engineer to attend.
17-Mar	PRIDE OF YORK	KGD	ADM reports that whilst manoeuvring to enter the lock at KGD, Pride of York made contact with the east inner gate, resulting in damage to the ship and the gate. Due to the damage the gate cannot be operated until further notice. All vessels over 140m can only transit the lock on the level until repairs complete. (MCA and MAIB advised by Dock Master - 18/03/14)
27-Mar	THURKUS	GY Royal	Pilot reports that the vessel made contact with the Birley wheels on the ships starboard side causing damage to the ships hand rails, whilst exiting the lock outwards. No other reported damage or pollution reported.
13-Apr ARK FORWARDER		Imm Dk	Made contact with outer lock gate whilst entering.
17-Apr	ARK GERMANIA	IOH	PEC reports 'too close to fender before landing.' One chain broken fender at 25 metre mark.
18-Apr	JS ALULAR	SKJ	Vessel departs SKJ for sea causing minor fender damage at the jetty, and a small dent to the vessel's port quarter. No injury or pollution reported.
23-Apr	SORMOVSKIY 3052	lmm Dk	Vessel lowering down in the lock bound for sea has caused some minor damage to the lock wall in way of a metal plate.
30-Apr	SMARAGD	Goole	Slight damage to railings on south dock bridge whilst manoeuvring the vessel through. No damage to vessel.




03-May	SORMOVSKIY 3057	Alex Dk	On entering Alex dock the vessel made contact with the east outer gate, damaging 3 vertical handrails on the gate.
14-May	AUTORUNNER	GY Royal	Pilot reports that whilst entering Grimsby Royal Dock basin, the vessel came into contact with the east inner Birley wheel some wood broken.
18-May	CHARON J	Imm Dk	Vessel inward for Immingham. On entering lock, displaced a coping stone on lock side. ADM informed.
27-May	KATRIN	Imm Dk Bellmouth	Whilst entering Immingham lock the vessel made contact with the west side damaging concrete and fenders.
28-May	SE CERULEAN	Imm Dk	Whilst entering the lock the vessel made contact with East outer Riverside fendering, causing damage to the rubber fendering. No reported damage to the vessel.
30-May	CEMBAY	Goole	Vessel made contact with the berth whilst departing. No damage apparent to ship or jetty. No injury or pollution.
31-May	CK PEARL	KGD	Slight contact with middle west gate of KGD lock whilst entering has caused damage to securing bolts. No damage to vessel.
08-Jun	LADY MARTINE	SKJ	Vessel made contact with the jetty whilst berthing at South Killingholme, pilot reports minor damage to ships rails.
08-Jun	OSTEREMS	GY Royal	Whilst departing GY Royal lock the vessel made contact with the tyre roller causing slight damage to the wooden structure. No reported damage to the vessel.
11-Jun	VASILY SHUKSHIN	Imm Dk Bellmouth	Vessel made contact with fender on the approach to Immingham Lock.
21-Jun	PRIDE OF YORK	KGD	Master reports that whilst manoeuvring to enter the lock on arrival, the vessel damaged and cracked a steel faced coping stone approximately 15 metres from the lock gates on the western approaches. No damage to the vessel or pollution.
25-Jun	NIKAR G	Goole	Contact made with gate whilst backing into Victoria Lock, stanchions bent.
02-Jul	WILSON AVONMOUTH	lmm Dk	Pilot reports that on departing the berth, the port quarter came into contact with the quay. Vessel returned alongside to inspect damage. Superficial damage to port quarter. Vessel to sail on next available pen.
06-Jul	CELANDINE	lmm Dk	Pilot reports whilst the vessel was manoeuvring to enter the lock, the vessel landed heavily on one of the fenders and broke one of its chains on the eastern approach jetty. No damage to the vessel or pollution.
09-Jul	HAREN	KGD	Stern landed heavily on East Knuckle causing indentation on vessel.
15-Jul	H & S FAIRNESS	Trent	On entering the river Trent "touched the bank". No damage to report.
03-Aug	DIAMONDE	Goole	Whist entering the lock at South pier the vessel made contact resulting in a small indentation on the stern of the vessel and damage to a shore side fender.
16-Aug	CLEMENTINE	lmm Dk	Vessel departs Imm lock, causing minor damage to the East Side Inner Knuckle rubber fendering. (Wind WSW 5/6).
18-Aug	EXPORTER	KGD	Pilot reports that whilst manoeuvring to enter the lock, the vessel damaged the inner stanchion bending it approximately 20 degrees, on the east outer lock gate. No damage to the vessel.
27-Aug	AFRICAN HIGHWAY	Grimsby River Terminal 1	Whilst berthing at the River Terminal Grimsby the v/l's stbd side made contact with the fendering on the Eastern jetty causing some damage to the fendering. No reported damage to the v/l.
28-Aug	SEELAND	KGD	Whilst berthing at KGD 7/8 Quay the v/l made contact with the quay resulting in damage to the quay. No reported damage to the v/l.
29-Aug	ABIS BILBAO	Goole	Contact made with South Dock Bridge north knuckle. Slight damage to quay edge.
03-Sep	HORST B	lmm Dk	Vessel lifting up in Imm Lock, caused damage to a coping stone and fender.
09-Sep	HUMBER JUPITER	Cleeness	Whilst en-route to Spurn via Grimsby, pilot launch made contact with a large piece of timber in the vicinity of the Gate buoy. After inspection the coxswain reports that the launch has no damage and is still in service.
11-Sep	PROGRES	Goole	Backing out of West Dock, vessel made light contact with West Dock Bridge railings causing some to bend over.
12-Sep		Selby	At 0810 the pleasure craft "Wanderer" departed Goole with 2 POB. Destined for York. She struck the Selby toll bridge and sank. Person's safe, recovery of the wreck is "in hand". No craft to transit the Ouse to Selby or York until further notice. 15/9/14 - Boat secured and waterway open.
14-Sep	NORDIC INGE	KGD	Vessel manoeuvring out of dry dock in KGD Hull with tug assistance made light contact with hose platform as vessel passed. No apparent damage to vessel or structure.
07-Oct	NESTOR	Grove	Whilst berthing at Grove LM1 the vessel made contact with the quay causing minor damage to a concrete section. No reported damage to the vessel.



13-Oct	PETER RONNA	Imm Dk	On entering Imm Dock the vessel made contact with east outer gate. No visible damage to gate or vessel.
13-Oct	ATLANTIC CARRIER	Albert Dk	Report from ADM that whilst the vessel was manoeuvring to enter the lock one the PM tide 12th the vessel made contact with the pillar navigational mark 2FG damaging the light and causing the pillar to lean at angle 20 degrees from vertical in a NW direction.
14-Oct	PATRIA	New H Pier	On departing NH dock, landed alongside NH Pier. POM advised 1037 Tug Lashette en-route 1108 Underway from New Holland to sea. Pilot confirms that there is no damage to the ship, pollution or injury. Master is advising his classification society and owners. 1215 Master confirms by VHF that both owners and classification society have been informed of contact and that both parties content for the vessel to proceed outwards to sea.
22-Oct	CLIPPER POINT	Imm Dk	Pilot reports that on entering the lock, the vessel made contact with the east side of the lock entrance causing the tarmac to lift. No damage to the vessel reported.
24-Oct	ENDURANCE	GY Royal	Vessel made heavy contact with the E/O rolling wheel causing damage to the woodwork. Paintwork on the ship scraped
02-Nov	ARGYROULA	KGD	KGD ADM advises Argyroula dislodged a coping stone when entering the lock. The coping stone is now on the East inner gate, therefore the inner gates are inoperative. 0027 Pilot S.Hollingworth confirms report, no damage to the vessel. Wind S'ly 5-6. 0101 Sailing cancelled due to tidal window, vessel proceeding back to berth.
05-Nov	LUNAMAR	Albert Dk	Whilst manoeuvring in Albert Dock the vessel made light contact with the North Wall causing some paint work damage to the bulbous bow.
10-Nov	HC BEA LUNA	Imm Dk	2300 Whilst entering the lock at Immingham with 2 tugs the v/l lost all power and steering. The v/l made contact with the West outer gate. No reported damage. Power restored at 2320.
12-Nov	RIDER	Grimsby	Whilst departing the lock at Grimsby Royal Dock the vessel's stbd side handrails were damaged when contact was made with East inner lock wheel.
12-Nov	ALMA	Imm Dk	Whilst approaching Immingham lock the v/I made contact with the western approach jetty causing possible damage to a fender chain. Vessel suffered small indentation on the bow and some paint damage.
18-Nov	JURA	Albert Dk	1445 Whilst departing the berth at Wm Wright dock the vessel made contact with the quay causing damage to the Bulbous Bow. The scale of damage to be assessed after an inspection. Sailing of the vessel cancelled.
20-Dec	WILSON BRUGGE	Goole	Whilst manoeuvring in Goole Docks vessel made contact with West Dock wall in way of her bow. No damage reported.
21-Dec	DENIZ A	IOT	APT berthing master informs the pilot that whilst manoeuvring to berth at IOT6 the vessel has damaged one of the mooring fenders causing a split down the middle.
22-Dec	CLIPPER POINT	lmm Dk	Whilst departing No 12 quay the vessel made contact with the quayside cause a split in the shell plating in way of the stbd bow. Damage confirmed as a split in the Hull of approx. 10cm, about 1.5m above the w/l. Sailing cx and surveyor to attend. MAIB informed by Immingham ADM. ETD 2200 From Immingham dock. Master confirms repairs have been approved by the classification society and MCA. Destination: Cuxhaven. 2230 V/L departs Immingham for Cuxhaven.
28-Dec	RED SPIRIT	GY Royal	Pilot Reports whilst entering GY Royal, contact was made with the west outer gate and railings. No apparent damage to vessel.








Γ

٦

	Contact with Vessels				
Date	Ships Name	Location	Remarks / Statement		
16-Jan	STEFFI C	KGD	Pilot reports making contact with the berthed vessel Cecilia on KGD North Gap whilst departing the berth. Pilot reports no damage. Wx S'ly 20kts.		
25-Apr	WILSON MERSIN	lmm Dk	Vessel made contact with vessel "Chyra" whilst manoeuvring to depart Imm dock. Superficial damage to both vessels in way of paint and gangway. Dock master to inform MAIB.		
26-Apr	CHESTNUT	KGD	Class 1 Vessel Chestnut entering King George dock made contact with the lead tug Statesman while in the lock, some damage to the Statesman's rails.		
14-Jun	MEKHANIK MAKARIN	GY Royal	Whilst leaving the berth in GY Royal 9 Quay the vessel made contact with a barge causing damage to the barge. No reported damage to the vessel.		
09-Oct	LISELOTTE ESSBERGER	KGD	Whilst leaving the berth at No 14 quay at KGD the vessel made contact with the berthed vessel Kimberly 'C'. No reported damage to the Kimberly 'C' and one damaged stanchion on the Liselotte Essberger.		







		Collisi	ons wit	h Vessels			
Date	Date Ships Name Location Remarks / Statement						



## Summary of Bunker Operations at

# Whitebooth Roads, Holme Ridge and Tetney Mono Buoy

Month	Total Operations (Tonnes)	Max Single Op (Tonnes)	Total (Tonnes)
January	21	100	998
February	12	100	612
March	22	150	1343
April	20	130	1176
Мау	17	155	886
June	20	90	970
July	20	90	926
August	17	90	875
September	13	80	715
October	19	100	1157
November	22	75	901
December	13	100	412
Totals for the Year 2014	216 operations		10971



Date	Reported By	Remarks		
02-Feb	PILOT	Pilot reports sighting a piece of timber in the water in the vicinity of Alex Dock Hull, approximate size 10mtrs in length. Broadcast made to advise shipping.		
04-Feb	MASTER / CAPTAIN	Master reports a large piece of timber in the outer harbour, 2 metres long and 40cm wide. Immingham dock informed.		
01-Apr	VTS 14	Launch reports baulk of timber between No 4B and Clee Ness buoy, navigation broadcast made.		
01-May	MASTER / CAPTAIN	Vessel moored at the west jetty reported a large log floating in the river approx. 50m off his starboard side. 0855 reported off e/j. 0903 reported south of A1 dolphin. 0906 reported south IOT1 heading for E/J expected to run aground.		
11-May	PILOT	Pilot reports sighting a lifebuoy in the vicinity of the Cleeness light float. Pilot launch Venus in the vicinity requested to investigate and recover if possible. 1930 Launch recovers lifebuoy, only markings port of registry Hong Kong and part of the name "Kwai Chung". HMCG advised and lifebuoy left at Grimsby Royal ADM.		
17-May	VTS15	<ul> <li>0745 'Precision 1' reports sighting a floating pontoon, approx. 8 feet square, in position 53 41.7</li> <li>N 000 14.87 E. 'All Ships' warning broadcast made, also requesting further sightings to be reported to VTS Humber.</li> <li>0943 Yacht 'Maybe' reports sighting pontoon approx. 1 cable south of Sand End It.by.</li> <li>0950 Workboat 'Haven Supporter', operating in the vicinity, offers to investigate.</li> <li>1042 'Haven supporter' locates pontoon and secures, to return to North Killingholme Haven.</li> <li>1036 'Haven Supporter', with pontoon, secure in North Killinghome Haven.</li> </ul>		
18-May	VTS 15	<ul> <li>Pilot launch reports sighting a floating pontoon approx. 10' square in position approx. 3 cables SE of S.Shoal It.buoy. 'All Ships' warning broadcast made, also requesting further sightings to be reported to VTS Humber.</li> <li>1822 Aspen, reports sighting in vicinity of Humber Power Intakes.</li> <li>1840 Haven Supporter leaves N. Killingholme Haven to investigate.</li> <li>1900 Haven Supporter locates pontoon in Holme Hook anchorage.</li> <li>1938 'Haven Supporter', with pontoon, secure in North Killingholme Haven.</li> </ul>		
18-May	VTS 15	Windcat 33 reports sighting a tree in the river, approximately 8 metres in length, in position approx. 2 cables SE of 4B It by. Small craft warning broadcast by Ch. 12.		
10-Aug	VTS 15	Master reports sighting a large piece of timber approximately 10m in size, 5 cables south of the Cleeness lightfloat. All ships broadcast made.		
09-Sep	PILOT	Pilot reports sighting a home-made raft in the main channel around Salt end. Barge consists of two 240 litre drums lashed together with wood. No persons on-board. All ships broadcast made		
09-Sep	MASTER / CAPTAIN	Master reports sighting a large piece of timber in the water approximately 2 x 1 metre in size, between the IOT and 9A. All ships broadcast made.		
10-Sep	PILOT	Pilot reports sighting a large tree trunk to the North west of the 9A buoy. All ships broadcast made.		
13-Sep	VTS14	Large baulk of timber reported. Broadcast made.		
17-Sep	PILOT	Partially submerged white coloured vehicle on the bank side opposite Burton Stather near to a slipway. Boot noted to be open. MCA advised. Duty manager aware. 14:29 H Rescue investigating. 1545 H Rescue investigated and returning to Hessle. Police investigating.		
18-Sep	PILOT	Vessel encountered unidentified floating object when passing 34 Buoy. Other vessel nearby advised.		
24-Sep	PILOT LAUNCH	Launch coxswain reports hitting an unidentified object North of the Bull Sand Buoy. All ships broadcast made.		
22-Oct	VTS 15	Master reports sighting a large green buoy with letters on the side (unreadable). In position approx. 0.5' NW of the Inner Sea Reach buoy. 0911 Stena Scotia identifies the buoy as South Binks. 1745 Clipper Point reports that buoy is unlit. 23/10/14 0900 Tug Welshman departs Immingham to recover the buoy current position 8 cables East of Inner sea reach buoy. 1115 Tug recovers the buoy, proceeding to the Hawke anchorage to rendezvous with UKD Seahorse to return buoy to Alex dock.		
06-Nov	VTS 14	Launch had boarded the Eli Knutsen and returning to Grimsby. Launch struck unwater object in the vicinity of the No 3 Chequer. Conducted inspection, no apparent damage to report. 1608 Resumes passage.		
24-Nov	PILOT LAUNCH	Baulk of timber sighted NW Chequer Buoy, flood tide, all ships broadcast made.		
26-Nov	MASTER / CAPTAIN	Baulk of timber sighted North of Delta Buoy, ebb tide, all ships broadcast made.		



Distress and other flare Reports				
Date	Reported By	Remarks		
09-Oct         VTS 15         VTS Humber sight red parachute flare in the vicinity of Grimsby/ Cleethorpes. Confirmed by two vessels in the vicinity Cape Magnolia and Sea Kestrel. HMCG advised.		Confirmed by two vessels in the vicinity Cape Magnolia and Sea Kestrel.		



Failure to report to VTS				
Date	Reported By	Ships Name	Location	Remarks
11-Jul	VTS 15	ATLANTIC COUGAR	Imm Dk	Windfarm support / survey vessel departed Immingham lock for the windfarms with no contact. Vessel advised of his obligation to call VTS.



Ē


\_

	Summary of Fires Reported					
Date	Reported By	Ships Name	Location			
12-Jan	VTS 15		Spurn Point			
the fire and are awaiting the	e fire brigade to assess. Off watch VTS	rator has caught fire; the lifeboat crew SO has been evacuated from the Calli ished, number 3 generator is now inop	sto accommodation			
20-May	VTS 15		Spurn Point			
Fire detected in lookout roo Steve Horton, VTS Manger		uished. RNLI called to assist. Equipm	ent isolated.			
20-May	VTS 15	HUMBER LIFEBOAT	Spurn Point			
1030 CG advises that the fi 1115 Fire crew arrive at Spi	cal fire on board the Humber Lifeboat re service is to attend from Spurn jetty urn (by Helicopter) for transfer to the I e is extinguished. Fire crew depart fro	ifeboat.	y.			
27-Jun	VTS 15	STENA TRANSIT	HST			
At 0700 VTS received a telephone call from the berthing master at the HST. It appears that Stena Transit had a fire in a lorry unit on its upper deck. This was reported to HST at about 0630. The report was updated to HST about 20 minutes later, stating that the fire had been dealt with. The berthing master was asking if we had instructed Opaline, on his final approach, to turn and stem. We had not. By this time Stena Transit was all fast and closed down. No mention of the incident was made to VTS by the Master.						
12-Aug	MASTER / CAPTAIN	LLANDUDNO BAY	Humber			
Call received from Llandudno Bay to say possible fire on board. Vessel bound for Grimsby. Four other windcats on scene, Coastguard advised and monitoring. 1645 vessel proceeding to Grimsby under own power. 1810 Llandudno Bay in Fish Dock. 1825 Call from Humber Coastguard, Llandudno Bay on fire in Fish Dock fire brigade called. ADM Grimsby informed and investigating. Operator Dong Energy. 1900 Fire out.						
16-Aug	16-Aug ADM KGD HST					
Immingham report that the f	ire appears to be just off Rosper Roa	close to the river bank. Immingham d d on farm land behind the HST. Emerg finery and will not their affect operation	ency services on			



	Fishing V/L Incidents				
Date	Date Reported By Ships Name Remarks		Remarks		
29-Aug	VTS 14	ANNE THIERRY	FV Anne Thierry outward approaching the Charlie buoy failed to maintain a listening watch on VHF channel 14 or 16. The outward PPV Yue Dian 103 was unable to make contact to arrange safe passing, ships whistle was sounded but provoked no response. Vessels telephone number obtained from Grimsby Fish dock, 0913 vessel called on VHF 14 and reminded of their obligation to maintain a listening watch on VHF 14 and follow collision regulations.		







Reports of High Speed			
Date	Reported By	Ships Name	Remarks
28-Dec	MASTER / CAPTAIN	RIX OWL	Master of Rix Owl reports whilst attempting to moor alongside the Magsenger 16 on HIT 2 two of his ropes parted, the outbound Misida was passing his station at this time.



	Lost and Fouled Anchors				
Date	Ships Name	General Position	Description		
03-Feb	ADMIRAL	HLB	Vessel in DWA position N fouled an old anchor chain.		
11-Feb	AMBER TRADER	HLB	Lost anchor (no chain) northern edge of anchor circle INDIA		
06-Apr	RYSTRAUM	HLB	Lost anchor (no chain) in DWA position C.		
26-Nov	WINDCAT 4	Hawke	Lost anchor with approximately 10m of chain and 10m of rope, buoyed off with orange fender. Anchor lost between Hawke light float and position "M" in Hawke anchorage.		



# Summary of Low Water Berthing and Sailing Requests

Month	Total Requests	PPV LW Berthing/Sailing	Non PPV LW Berthing/Sailings
January	30	8	0
February	29	4	0
March	42	7	1
April	37	3	0
Мау	23	2	0
June	19	1	2
July	30	4	0
August	26	4	1
September	27	5	0
October	27	0	1
November	23	7	0
December	31	6	1
For the Year 2014	344	51	6



Date	Details	Date Cancelled
03-Jan	West Walker Dyke tide gauge light UNLIT. Confirmed by Celine. Repaired 8/1/14.	08-Jan
03-Jan	KGD upper blue dredge limit light is UNLIT.	04-Jan
04-Jan	Sunk Spit diminished - UNRELIABLE. 4/1/14 19:18 reported to be bright.	04-Jan
06-Jan	No.15 top mark damaged. Light reported lit but at angle. DIMINISHED. Buoy replaced by UKD Seahorse 17/01/14.	17-Jan
13-Jan	Chalderness tide board light is UNLIT (19/02 repair attempt unsuccessful). All repaired 10/3/14.	10-Mar
14-Jan	Clee Ness Lt.Float. Riding light. UNLIT. Repaired 18/02/14.	18-Feb
16-Jan	Hull Middle buoy is OFF STATION approx. 200m NE of its charted position. Re-positioned by UKD Seahorse. (17/01/14).	17-Jan
18-Jan	River Trent, Cliff End upper lead light UNLIT. (Confirmed by Fast Julia 18/01 2030) Fixed 20/01/14.	20-Jan
28-Jan	EAST JETTY TUG BARGE: Red light reported UNLIT. Fixed 30/1/14.	30-Jan
28-Jan	IMMINGHAM DOCK: Lower red docking light: UNLIT. Reported fixed 13/02/14.	13-Feb
29-Jan	All jetty lights on the Imm east jetty are extinguished. UNLIT. Fixed 30/1/14.	30-Jan
03-Feb	SEJ 1 - Lower dredge limit light UNLIT.	15-Feb
04-Feb	Grimsby middle It. float. Riding light. UNLIT. Repaired 18/02/14.	18-Feb
04-Feb	South Trent light reported as DIMINISHED. 11/2/14 Reported operational.	06-Feb
12-Feb	No.15 Holme Hook OFF STATION . Light and topmark missing. Position 2 cables NW of charted position. Buoy replaced 20/02/14.	20-Feb
14-Feb	South Fort buoy UNLIT. (Confirmed by Seacat Reliance) 17.03.14 Eng plans to attend Tues 25th March. Too rough 22.03.14. Repaired 24/03/14.	24-Mar
14-Feb	Foul Home No 5 buoy UNLIT. (Confirmed by Najade)	02-Mar
09-Mar	Imm Dk Tower A Traffic Signals UNLIT. Repaired 10/03/15.	10-Mar
13-Mar	Immingham Dock, docking signals UNLIT Repaired 16/03/14.	16-Mar
02-Apr	No 22 Hook buoy OFF STATION approx. 290 (WNW) x 2.3 cables from charted position. Damage to cage, light is operating. Back on station AM 0804/14.	08-Apr
04-Apr	Apex fog signal INOPERATIVE. (Reported operational 08/04/14)	08-Apr
05-Apr	Pilot reports that Amcotts Hook light is UNLIT. 08/04/14 Confirmed unlit by Nathalie. Repaired PM 08/04/14.	09-Apr
22-Apr	Riding light on the SE Chequer buoy is extinguished. Confirmed 23/4/14. (New battery required) 12/05/14 Light replaced.	12-May
24-Apr	Outer Binks buoy is approx. 0.7 cables on a bearing of 305 degrees from its charted position. No obvious damage to the Buoy. Checked by H. Charter. (To be repositioned by 'Seahorse' at earliest opportunity.) 13/05/14 Position checked by Surveyors and found within limits.	13-May



Date	Details	Date Cancelleo
Dale	Details	Date Cancelleu
26-Apr	North Trent light reported UNLIT. 01/05/14 Reported to be working by Celtic Venture	01-May
01-May	Riding light on the 33A is UNLIT. Confirmed RMS DUISBURG. 18/05/14. Light float replaced 06/06/14	19-Jul
01-May	West Goole light reported as UNLIT. Goole aware. 03/05/14 2235 confirmed unlit by Neptun.	11-May
02-May	Thorngumbald high leading light UNLIT Confirmed SHIPPER 06/05/14. 09/05/14 Samskip Courier advises light is working.	09-May
08-May	South Trent Light reported diminished intensity. UNRELIABLE. Confirmed by Antwerp 0124 8/05/14. Repaired 09/06/14	09-Jun
10-May	Yokefleet rear white leading light is UNLIT. Pilot reported this to Goole ADM Repaired 09.06.14	09-Jun
11-May	TMB fog signal not working	20-May
12-May	North Trent beacon is lit but diminished intensity - UNRELIABLE (when approaching from the East). It appears OK when passing it. Confirmed by Dolfijn 17/05/14. Repaired 09/06/14	09-Jun
16-May	Pilot reports the 'Bravo' buoy is diminished intensity, UNRELIABLE. 0020 25/05/14 Vessel Tharsis reports light OK	25-May
16-May	Cliff End Rear Leading light obscured by foliage. Site visit by IWS found High Light visible from Low Light.	21-May
24-May	Pilot reports 'Sunk Spit' buoy diminished intensity. UNRELIABLE. 0021 25/05/14 Samskip Innovator reports light OK	25-May
24-May	IBT Sector light UNRELIABLE. Fixed sectors only showing. No Al. WG or Al WR. 21/08/14 Spares to be fitted on 27/08/14. Repaired.	27-Aug
27-May	Riding light on the Spurn Light Float reported extinguished. 21/06/14 Riding light repaired by the engineers.	21-Jun
02-Jun	Swinefleet Pier is totally UNLIT. VTS advised Goole ADM.	03-Jun
09-Jun	No 9 Cotness Drain It. reported UNLIT. TBC. Reported OK 'Lady Nova' 17/06/14	17-Jun
13-Jun	IOT finger pier west end light UNLIT	
14-Jun	No 1 shore marker at Bishopsoil drain appears damaged. 19/06/14 Structure to be replaced, Mark and light still reliable.	19-Jun
23-Jun	Middle red light on the tower at Immingham signal tower UNLIT. Reported fixed 0300/4th from ADM	04-Jul
09-Jul	Waddington light reported unlit by vessel Remora. TBC.	11-Jul
18-Jul	Upper & Lower dredge lights on the west end of SEJ UNLIT Upper light repaired 01/08/14. Lower Light reported repaired 14/08/14.	14-Aug
19-Jul	Waddington Lt, River Trent UNLIT. Confirmed by Tove 22/07/14 Replaced 23/07/14.	27-Jul
23-Jul	Lower Whitton is not showing either its green light or white riding light 24/07/14. Reported working by Christine Y.	24-Jul
23-Jul	No.29 and 30 are UNLIT.	24-Jul


Date	Details	Date Cancelled	
24-Jul	Two green lights at the end of Reservation Quay (Alex dock) are UNLIT. No longer in use.	25-Jul	
02-Aug	Waddington light UNLIT. Confirmed by RMS Wedau - 06.08.14. Fixed 11/08/14.	11-Aug	
12-Aug	No 33A Riding light UNLIT. Confirmed by Wiebke D. Rectified 1330/18th Aug by UKD Seahorse.	18-Aug	
15-Aug	Waterton Lt - River Trent UNRELIABLE. 19/08/14 Confirmed extinguished. 20/08/14 Fixed.	20-Aug	
17-Aug	Yellow special mark buoy, marking NE end of import cable is MISSING from station. (EON is stencilled on side). If recovered contact EON duty manager on 07772585044. 19.08.14 - Believed to have cleared Humber Area.	19-Aug	
24-Aug	No 25 West Side pile marker in the Swinefleet Reach DAMAGED (by road traffic incident. Pile rotated 90 degrees now difficult to see). Repaired.	26-Aug	
29-Aug	Unable to activate the Apex fog signal. Engineers Goole advised and investigating. Repaired by engineers 03/09/14	03-Sep	
03-Sep	Flix Nypro lights are UNLIT. Fixed 4/9/14	04-Sep	
10-Sep	Chequer number 3 buoy reported as diminished intensity (UNRELIABLE) Confirmed by Thames Fisher (10/09/14 0045 Hrs). 10/09/14 Nordic Nora reports light ok.	10-Sep	
10-Sep	The lower of the two lights on the Pile 8 light is DIMINISHED. Goole advised. Repaired 22/9/14	22-Sep	
10-Sep	Immingham docking signal Middle white light is UNLIT. Fixed 14/9/14	14-Sep	
17-Sep	Fog horn on the A1 Dolphin INOPERATIVE. IOT investigating. 29/09/14 IOT report that the whole unit may have to be replaced. 17/12/14 Confirmed Fixed.	17-Dec	
20-Sep	Riding light on Middle Whitton is UNLIT. Confirmed unlit by Antari 0600/23rd Sept. 14/10/14 M/V Remora LIT but diminished.	14-Oct	
20-Sep	Navigation lights on the IGT will be inoperative until about 1600 20/09/14	21-Sep	
20-Sep	Pyewipe light is UNLIT. 22/9/14 20:12 Fionia Seaways reports that the light is working	22-Sep	
26-Sep	IGT lower upstream jetty light UNLIT. IOT aware. Reported working by IOT berthing master 07/12/14.	07-Dec	
27-Sep	FH4 It buoy OFF STATION in position: approx. 400 metres ESE of FH3 It buoy. (See occurrence no.14851). 1100 29/09/14 Buoy Back on station UKD Seahorse.	29-Sep	
01-Oct	No.16 Sand End Buoy riding light reported UNLIT. Report confirmed by Frej. 03/10/2014 Reported lit by Alrek.	03-Oct	
06-Oct	HLF temporarily removed from station. Replaced by temporary mark 19/11/14		
13-Oct	Pillar Nav Mark 2FG off the entrance to Albert Dock is DAMAGED. The light is missing and the pillar is leaning at angle 20 degrees from vertical in a NW direction.		
14-Oct	Riding light on the No.33 UNLIT. Confirmed by m/v See Stern.	14-Nov	

Date	Details	Date Cancelled
15-Oct	Hall Staith's light UNLIT.	21-Oct
15-Oct	Cliff End Light, River Trent. Reported UNLIT. Remora 19/10/14 0330 reports light is showing	19-Oct
19-Oct	Grove light is UNLIT Repaired 23/10/14	23-Oct
22-Oct	South Binks light buoy temporarily removed from station. Replaced 19/11/14	19-Nov
25-Oct	Riding light on Middle Whitton UNLIT Repaired by UKD Seahorse AM 14/11/14	14-Nov
02-Nov	Riding light on the Sand end light float UNRELIABLE. Confirmed by Christine Y. Repaired 10/11/14 Mercury.	10-Nov
05-Nov	No. 5A reported showing quick flash (Promulgated characteristic FL G 2s) UNRELIABLE Checked PM 5th confirmed quick flash Repaired AM 6TH	06-Nov
09-Nov	Humber Power Intake UNLIT 1948 Lights reported LIT.	09-Nov
09-Nov	No.5 Gate buoy UNLIT 1710 Reported working	09-Nov
12-Nov	Goole Victoria lock. Top traffic signal UNLIT. Fixed.	19-Nov
12-Nov	West side/East side lights at Victoria steps Hull UNLIT. Fixed.	19-Nov
12-Nov	Front yellow dredge marker at Alex UNLIT. Fixed.	19-Nov
12-Nov	KGD East Bullnose Lt UNLIT. Fixed.	19-Nov
12-Nov	Burton Stather Ferry Inn both lights UNLIT. Repaired 13/12/14	19-Dec
12-Nov	Keadby S. Mooring dolphin lower light UNLIT. Fixed.	19-Dec
12-Nov	Keadby S. end wharf light MISSING. Fixed.	19-Dec
13-Nov	River Trent, Hill side top light UNLIT. Engineers advised.	25-Nov
19-Nov	Whitgift light reported UNLIT. 1700/19th All the lights at Whitgift are reported to be working MV Frifjord.	19-Nov
27-Nov	Immingham lower red signal light UNLIT Reported working by ADM 05/12/14	05-Dec
15-Dec	5 gate buoy light reported as DIMINISHED. Confirmed by Hornisse. 15/12/14 Confirmed ok by Amandine.	15-Dec
19-Dec	Upper Dredge Limit Light SEJ 1 UNRELIABLE UNLIT.	
19-Dec	SDC Papa 2 UNRELIABLE diminished intensity. 20/12/14 Reported ok by Minerva Lydia	20-Dec



	Pollution	Reports	
Date	Reported By	Ships Name:	Location:
20-Feb	ADM KGD	TRADESMAN	KGD
ADM reports tug Tradesm	an at 12 Quay has spilled about 10	00 litres of fuel oil. POLREP from K	GD received.
26-Apr	MASTER / CAPTAIN	HAFNIA SEAWAYS	IOT
IOT2. Both IOT and Immir Immingham Dock advised	essel 'Hafnia Seaways' reported a ngham dock were informed. IOT co that HIT is discharging iron ore an ested to pass through the area, and ed, Duty Manager ADV.	nfirmed the origin was not the bert d that the dust can give the same a	n or vessels alongside. appearance. Outbound
16-May	COASTGUARD	MPI RESOLUTION	Humber
17.276' E) approximately The majority of this amoun The tidal direction at this t	ons at Humber Gateway Offshore N fifty (50) litres of Avia RSL 46 hydra nt was sprayed onto the deck of the ime was approximately 176° and ra the oil was then contained on-boar	aulic oil was accidently released du e vessel due to the direction and pr ate of 2 knots. The hammer was im	e to an oil seal failure. essure of the release. mediately recovered
07-Jul	MASTER / CAPTAIN reports that when the Ark German	FIONIA SEAWAYS	IOH
vessels when alongside. I of the Ark Germania at the 2030 Workboat Onsite1 of 2036 Master on Ark Germ 2145 POLREP received fr	vessel. Oil was also observed on the Master on Ark Germania informed a e IOT could not see any oil sheen of confirms oil in the Outer harbour bet ania confirms no oil has leaked from rom ADM Immingham, area covere to disperse the oil. Source of spill	and asked to investigate. Vessel Ya or rainbow effect emanating from th ween IBT and the DFDS berths. m his vessel. d approx. 100m2 15litres. ABP Pro	asmine who was astern e vessel.
01-Aug	VTS 15	SALLIE KNUTSEN	ТМВ
Reports from the Berthing 3m wide by 100m in lengt 1250 CG reports that the	Master on the vessel of a 'light she h. Crew investigating. CG informed pollution is not from cargo operation hruster gland. Repairs to be carried d out.	ns but probably from the ships thru	sters.
02-Aug	MASTER / CAPTAIN	FICARIA SEAWAYS	Middle Burcom
10 m. PV Saturn in the vice 1210 Pilot launch confirms carried out to sea on the E	t sheen of oil in the water in the vic inity asked to investigate. s it is a light sheen, source unknow bb tide. Due to wind against tide e Duty manager advised. Incident cl	n and isn't increasing in size. Oil ar ffect oil appears to be breaking up.	opears to be getting
04-Dec	VTS 15	Old Harbour	
of spill identified as Rix Fo 1250 Rix representative re subsequently seeped into in the River Humber. POL 1320 Hrs C. Ward and S. has not entered the River	eports that the spill is approximately the ground and drained into the riv REP faxed to HMCG by Hull city co Winterton, attended the mouth of th Humber.	7 10 litres of oil which has drained of er. Rix Eagle on Minerva pier repo- buncil, They expect the oil to dispen- ne river Hull near "The Deep" and of the dispension of the dispension of the dispension of the pier river Hull near "The Deep" and of the dispension of the dispension of the pier river Hull near "The Deep" and of the dispension of the d	off a drip tray and has rts not sighting any oil rse naturally. confirm the oil sheen
16-Dec	MASTER / CAPTAIN		Humber
water possibly emanating Straitview contacted & asl 0738 Straitview reports sc 0749 Straitview reports oil 0804 CG informed. 0826 PL Venus on locatio	me spots off starboard side no ove off starboard quarter.	launch Venus tasked to investigate	and take sample.







ſ

-	Traffic Separa	ation Scheme Contravention
Date	Ships Name	Remarks
17-Jan	BEN VARREY	Vessel departed NSH TSS at S.Binks and passed close to Humber Gateway Wind Farm to west. Vessel contacted and warning issued regards proximity of unlit structures. Instructed to return to TSS. Master refused to acknowledge instruction and stated that ABP had no jurisdiction over his vessel.
29-Apr	FV LE PRECURSEUR	Fishing vessel outward bound approaching the Charlie buoy observed to be tracking towards the inward traffic lane. No contact VHF Ch. 12, 14 or 16. 0754 vessel entered inward lane. No inward traffic. Visibility 1-2 cables. Warning issued on Channels 12 and 14. No details in small craft database. Grimsby Fish dock confirmed departure this morning but has no details. Vessel departed the TSS West of SLF and proceeded to the North and West of the Gateway.
22-May	FV LE PRECURSEUR	F/V Le Precurseur departed Grimsby with no contact. Vessel contravened the traffic lanes between Charlie Buoy and Spurn light float. Repeated attempts to contact the vessel where made. Contact eventually made but command of English was none existent. Vessel left the lanes at Spurn Light Float and proceeded on a course between the New Sand Hole and the Humber Gateway. Gateway vessel Atlantic Explorer advised to monitor the vessel.
06-Aug	CLEMENTINE	Vessel contravenes the Inner TSS whilst overtaking outward vessel Stenberg.
07-Aug	PRIDE OF BRUGES	Outward vessel contravened Sea Reach TSS to achieve overtake manoeuvre. Advised of intended track in precautionary area. Continued with action.



.

Barge w	Barge Movements passing under the Humber						
	Bridge						
2014	Haz	Hazardous Goods			Non Hazardous Goods		
2014	Ebbs	Floods	Total	Ebbs	Floods	Total	
January	10	0	10	0	8	8	
February	1	0	1	0	2	2	
March	5	0	5	0	5	5	
April	3	0	3	0	5	5	
Мау	4	0	4	0	3	3	
June	7	0	7	1	8	9	
July	6	0	6	0	6	6	
August	4	0	4	0	3	3	
September	5	0	5	0	5	5	
October	6	0	6	0	7	7	
November	5	0	5	0	3	3	
December	4	0	4	0	4	4	
Total	60	0	60	1	59	60	

## woments passing under the Humbe



Γ

Date	Reported By	General Location	Remarks
06-Jan	Coastguard	H Bridge	0422 Humber Rescue launched. 0606 Humber Rescue stood down, incident closed.
23-Jan	Bunker Barge	Old Harbour	Potential bridge jumper reported on Drypool Bridge River Hull. CG informed. 2115 No further information.
14-Jul	Coastguard	Old Harbour	Humber Rescue mobilising to report of person in the water near to North Bridge. 2355: Humber Rescue standing down and returning to Hessle.
08-Aug	Coastguard	Keadby	Humber Coastguard report that a female has jumped off the Keadby Bridge. Humber Rescue despatched. 1810 - Humber Rescue returns to station at Hessle.
20-Aug	VTS 15	H Bridge	1615 Potential bridge jumper reported by the Coastguard. All roads to the Humber Bridge shut. Pilot launch sent to Hull for crew change and to pick up pilots. Operating one launch service. 1850 Humber Bridge re-opened and resumed 3 boat service.
04-Oct	VTS 15	Hessle	Telephone call from Humber Coastguard. Reporting bridge jumper. Casualty thought to be in the water off Hessle fore shore. Humber rescue being mobilised. 1946 Update from HMCG. Casualty recovered from water by SAR helicopter and on the way to HRI.
22-Oct	VTS 15	H Bridge	HMCG report one person threatening to jump off the Humber bridge. Humber rescue to launch and no commercial vessels in the area at this time. 2325 Humber rescue stood down, situation resolved.
23-Oct	VTS 15	Albert Dk	HMCG report that at 1050 hrs a person was reported in the water around St Andrews quay area. Humber rescue investigating. 1315 KGD ADM reports possible sighting between RT1 and the shore side, HMCG advised. 1330 Dock security advise that after closer inspection, the sighting is two black dustbins, CG advised. 1445 Humber rescue returns to station.
03-Nov	Coastguard	H Bridge	Possible Humber bridge jumper, Humber rescue or standby.
10-Dec	VTS 15	Old Harbour	Humber coastguard reports a potential bridge jumper outside the railings on Drypool bridge. 2123 Humber rescue launches to attend. 2253 All clear given by coastguard potential jumper off bridge. Humber Rescue returning to Hessle. 2345 H.Rescue back at base.
18-Dec	Coastguard	H Bridge	HCG advise person in water Humber Bridge area, conducting search.



## **Conservancy Activities**

#### December 2013 to December 2014

During this twelve-month period, the Survey Section of Humber Estuary Services undertook 653 individual hydrographic surveys, including 28 contract multibeam surveys for outside parties, 108 for UK Dredging and 72 Ouse leading line surveys. The greater part of the data obtained was passed to the United Kingdom Hydrographic Office to form the basis of Admiralty charts for the Humber Area. All information gained from these surveys was processed and charted, resulting in the production and distribution of over 9,000 chart copies, mainly to be used in Pilotage and general navigation, a number of the local charts also being offered for general sale.



#### Humber Charter

The survey work resulted in the planning and carrying out of some 58 movements of floating navigation marks, in order to mark the fluctuations in the alignment of the navigable channel, mainly in the Upper Humber. In addition, out of a total of 128 local Notices to Mariners issued during the period, based on survey results, 78 of which contained warnings of shoal water.

The monitoring and maintenance of navigational aids dealt with 4 reports of deficiencies in floating marks and 6 in shore marks all being satisfactorily dealt with.

Multibeam survey of the Chequer shoal and Immingham roads continued. 28 outside contract multibeam surveys were conducted.

The Sunk Dredged Channel (SDC) experienced several occurrences of shoaling but these were all subsequently dredged back to 9.5 metres.


The shoaling at Halton Middle improved during the year, though a small encroachment still exists on the Western edge of the channel.

Monthly multibeam monitoring surveys of the Centrica pipeline at Stallingborough showed some spans increasing throughout the year whilst other areas continued to accrete.



The South side of the "East Middle" channel near Hull shoaled during the middle part of the year but had improved again by December.

The Hessle Sands area showed some decline in the second half of the year but The "Skitter" channel continued to be stable for traffic bound to and from the rivers Trent and Ouse.



The "Skitter" channel

The last quarter of the year saw the Upper Humber become a restricting factor for vessels navigating the Trent and the Ouse. Most of the shoaling occurred in the area around Brough stretching to the No. 34 Buoy. The channel to the North of South Ferriby began to stabilise.


The River Ouse remained at over 1 metre for the majority of the year.

Depths in the Trent remained stable for most of the year.




## Sunk Dredged Channel 2014

The following charts indicate the dredged volumes since 1969 to the present, the Least Available depths in the SDC during 2014 and dredged volumes in other parts of the Humber throughout 2014.





## Least Available Depths 2014





Humber Dredging Summary 2014	Т	OTAL	TOTAL
Location	Time (hrs)	Volume (m3)	Tonnes
Hull - Albert Entrance	54.6	3,435	4,890
Hull - Albert Dock	53.4	1,487	2,082
Hull - Alex Entrance	38.1	32,417	42,142
Hull - Alex Dock	113.6	6,725	9,285
Hull - Ro-Ro Terminal	-	-	-
Hull - Queen Elizabeth Dock	-	-	-
Hull - KG Dock	280.8	124,736	165,948
Hull - KG Entrance	204.4	187,720	244,036
Hull - RT1 & RT2	147.3	88,853	118,376
Hull - Saltend	171.5	90,812	119,320
Hull - Other/unspecified	227.3	136,235	177,106
Goole	86.6	3,458	4,841
Grimsby River Terminal (maintenance*)	226.7	141,298	183,687
Grimsby Alex	55.2	7,145	12,448
Grimsby Royal Dock & Basin	310.1	92,572	132,615
Grimsby Entrances	198.9	88,601	128,197
Grimsby Fish Dock	1.3	1,678	2,181
Grimsby Marina	61.5	2,530	7,590
Grimsby - Other/unspecified	11.1	8,428	10,956
Immingham Bellmouth	135.9	176,016	228,821
Immingham Dock	788.8	224,729	311,579
Immingham Gas Terminal	21.9	10,421	14,179
Immingham West Jetty Ext.	86.7	75,838	100,950
Humber International Terminal	317.5	224,283	295,359
Immingham Bulk Terminal	395.0	319,763	421,079
Immingham Outer Harbour	1,588.6	1,720,860	2,241,872
Sunk Dredge Channel	577.1	351,454	456,890
Total	6,153.9	4,121,494	5,436,428
South Killingholme Oil Jetty (11A deposit)	-	-	-
Grand Total	6,153.9	4,121,494	5,436,428

# Humber Dredging Summary 2014

## Harbour Craft

There are five pilot boats presently in service: Humber Neptune, Humber Venus, Humber Saturn, Humber Mercury, Humber Tartan and Humber Jupiter.

There are two dedicated craft used for surveying on the Humber, based in Hull; Humber Charter and Humber Ranger.

	Humber Charter (1991) Humber Ranger (1991)	Humber Tartan (1995)	Humber Neptune (2006) Humber Venus (2006) Humber Saturn (2006)	Humber Mercury (2011) Humber Jupiter (2014)
Builders	Halmatic, Southampton	Halmatic, Southampton	Halmatic, Southampton	Mustang Marine, Milford Haven
L.O.A	14.83 m	15.10 m	15.25 m	15.25 m
Beam	4.17 m	4.26 m	4.26 m	4.26 m
Draught	1.14 m	1.20 m	1.30 m	1.30 m
Speed	21 kts	22+ kts	24 kts	24 kts
Engines (twin)	Volvo Penta	Scania DSI 14	Scania DI16-43M	Scania DI16-43M
Radar	Furuno 1830	Furuno 1830	Furuno 1830	Furuno 1830
VHF Radio	Sailor RT 2048	Sailor RT 2048	Sailor RT 2048	Sailor RT 2048
Sounder	Atlas Deso 20 Atlas Deso 25	Atlas Deso 20	Via Furuno GP7000F Chart Plotter	Via Furuno GP7000F Chart Plotter
Position Fixing Equipment	Sercel NR 106B Differential GPS Receiver		Furuno GP7000F Chart Plotter	Furuno GP7000F Chart Plotter
Digital heave compensator	TSS 325 Sensor			



Humber Charter



Humber Neptune



Humber Tartan




Humber Mercury




## **Statutory Harbour Consents**

Associated British Ports (ABP) gave its statutory consent for two projects during 2014.

Firstly, National Grid for the purposes of a geotechnical survey, 20 boreholes were drilled in the Humber Estuary between Paull and Goxhill, as part of the groundworks for the project to replace the Feeder 9 pipeline.



Secondly, for P66 for the replacement of the Tetney Monobuoy subsea pipeline. The scope of work was to replace a section of 36" pipeline, (including PLEM, isolating ball valve, PLEM frame and pilings) between a tie in point at (E536 636.28 N404 343.86) and the Tetney Monobuoy (E540 111 N406 824).





## **Spurn Point**

On the 05 December 2013 the Humber region experienced a significant tidal surge, the height of which was last seen in the 1950's. Although not as devastating in terms of loss of life, it marked a significant turning point for the long term sustainability of Spurn Point as a base for Pilotage and VTS.

With almost immediate effect, pilotage operations were moved to be permanently based in Grimsby, whilst VTS operations remained at Spurn Point, access by road became twice daily, over the LW period. All other access to Spurn was conducted by launch. As a result of the limits placed upon access, visits to the VTS Tower were stopped. Pre PEC chats, historically conducted at the Tower, were now done in Port House, Hull, with one of the VTS management team.



The road connecting Spurn Point to East Yorkshire looking North.



Γ

1

			lanua	r\/		
		Snu	Janua rn Point		Kina (	George Dock
Day/Date	Wi	-	Visibility	Wi		Visibility
Wed 01	S	4	GOOD	S	4	GOOD
Thu 02	SW X W	4	GOOD	SW X S	4	GOOD
Fri 03	SSW	6-7	GOOD	SXW	6-7	GOOD
Sat 04	SSE	4	GOOD	SSE	4	GOOD
Sun 05	SW	3-4	GOOD	SW	4-5	GOOD
Mon 06	SSW	5-6	GOOD	SSW	5-6	GOOD
Tue 07	SSW	6	GOOD	SSW	6	GOOD
Wed 08	SW	5	GOOD	SW	6	GOOD
Thu 09	WSW	4	MODERATE	WNW	3	MODERATE
Fri 10	WSW	4	GOOD	SW	4	GOOD
Sat 11	WNW	4	GOOD	WNW	4	GOOD
Sun 12	S	3-4	GOOD	SSE	4	GOOD
Mon 13	SW	4	GOOD	SW X S	4-5	GOOD
Tue 14	SW	3	GOOD	SW	3	GOOD
Wed 15	S	4-5	MODERATE	SSE	3	MODERATE
Гhu 16	S	3	GOOD	SSW	3-4	GOOD
Fri 17	S	4	GOOD	S	5	GOOD
Sat 18	SE X S	4	MODERATE	SE X E	3-4	MODERATE
Sun 19	SE	4	GOOD	ESE	3	GOOD
Von 20	SSE	2	GOOD	SW	2	GOOD
Tue 21	SE	3-4	POOR	SE	2-3	POOR
Ved 22	SSE	6	GOOD	SSE	5	GOOD
Thu 23	S	2-3	GOOD	S	2-3	GOOD
Fri 24	SW X S	2	GOOD	SW	2	GOOD
Sat 25	SW X S	3-4	MODERATE	SSW	3	MODERATE
Sun 26	S	4	GOOD	SSE	4	GOOD
Non 27	SW X S	4	GOOD	SXW	5	GOOD
Tue 28	S	4	GOOD	SSE	4	GOOD
Wed 29	ESE	6-7	GOOD	E	5	GOOD
Thu 30	ESE	5	GOOD	E	3	GOOD
Fri 31	SSE	4	GOOD	SSE	4	GOOD



	Daily Weather at 07:03								
February									
Day/Date		Spu	rn Point		King G	eorge Dock			
Day/Dale	Wi	nd	Visibility	Wi	nd	Visibility			
Sat 01	W	5	GOOD	SW	4	GOOD			
Sun 02	SW	6-7	GOOD	SW	5-6	GOOD			
Mon 03	SSE	5	GOOD	SSE	5	GOOD			
Tue 04	SSW	4	GOOD	SXW	4-5	GOOD			
Wed 05	SE	8	GOOD	SE	7	GOOD			
Thu 06	SW	4-5	GOOD	SSW	4-5	GOOD			
Fri 07	NW	4	GOOD	NW	3	GOOD			
Sat 08	S	6-7	GOOD	S	5-6	GOOD			
Sun 09	SSW	6	GOOD	SSW	6	GOOD			
Mon 10	S	3-4	GOOD	S	2-3	GOOD			
Tue 11	S	4-5	GOOD	SE X S	5	GOOD			
Wed 12	SW X S	6	GOOD	S	6	GOOD			
Thu 13	SW	7-8	GOOD	SW	5-6	GOOD			
Fri 14	SW X S	5	GOOD	SW X S	5	GOOD			
Sat 15	SW	7-8	GOOD	SW	7-8	GOOD			
Sun 16	W	5-6	GOOD	WXS	4	GOOD			
Mon 17	S	4	VERY POOR	SSE	3	POOR			
Tue 18	S	3	GOOD	SSW	3	GOOD			
Wed 19	WXS	4	GOOD	SW	4	GOOD			
Thu 20	S	5	GOOD	S	5	GOOD			
Fri 21	SW	4	GOOD	SW X S	4	GOOD			
Sat 22	SW	4	GOOD	SW	4-5	GOOD			
Sun 23	S	5-6	GOOD	S	6	GOOD			
Mon 24	S	6	GOOD	SXE	6	GOOD			
Tue 25	SXW	5	GOOD	S	5	GOOD			
Wed 26	SW	4	GOOD	S	4	GOOD			
Thu 27	S	7	MODERATE	S	7	MODERATE			
Fri 28	ESE	2	GOOD	ESE	2	GOOD			



Daily Weather at 07:03									
March									
Day/Data		Spi	urn Point		King G	eorge Dock			
Day/Date	Wind		Visibility	W	ind	Visibility			
Sat 01	SSW	1-2	VERY POOR	VAR	Lt Airs	VERY POOR			
Sun 02	SSW	5	GOOD	SSW	6	GOOD			
Mon 03	SW	2-3	GOOD	SW	2-3	GOOD			
Tue 04	S	2-3	GOOD	S	3-4	GOOD			
Wed 05	W	1-2	GOOD	SW	1	GOOD			
Thu 06	S	4-5	GOOD	S	5	GOOD			
Fri 07	SW	5	GOOD	SXW	6	GOOD			
Sat 08	S	5	GOOD	S	5	GOOD			
Sun 09	S	3	MODERATE	S	2	MODERATE			
Mon 10	N	5	GOOD	N	4	GOOD			
Tue 11	ENE	3	GOOD	N	2	VERY POOR			
Wed 12	E	2-3	GOOD	ENE	3	GOOD			
Thu 13	W	2	POOR	SW	2	VERY POOR			
Fri 14	S	2	MODERATE	SW	2-3	MODERATE			
Sat 15	WNW	6	GOOD	WXN	5	GOOD			
Sun 16	W	6	GOOD	W	5-6	GOOD			
Mon 17	WXN	4	GOOD	W	4	GOOD			
Tue 18	WSW	4	GOOD	SW	4	GOOD			
Wed 19	WSW	4	GOOD	WSW	6	GOOD			
Thu 20	SW	4-5	GOOD	SW	4-5	GOOD			
Fri 21	SW	4	GOOD	SSW	4	GOOD			
Sat 22	SW	4	GOOD	SW	4-5	GOOD			
Sun 23	WSW	4	GOOD	SW	4	GOOD			
Mon 24	SW	2-3	GOOD	SSW	2	MODERATE			
Tue 25	SXE	4	MODERATE	SE X S	4	MODERATE			
Wed 26	NXE	4	GOOD	NNW	2	GOOD			
Thu 27	E	4	GOOD	NNE	2	GOOD			
Fri 28	E	4-5	MODERATE	E	3-4	MODERATE			
Sat 29	E	3-4	MODERATE	E	3	MODERATE			
Sun 30	EXS	2-3	MODERATE	NNE	2	MODERATE			
Mon 31	ENE	2	POOR	E	2	POOR			



Daily Weather at 07:03									
April									
Day/Date		Spu	rn Point		King G	eorge Dock			
Day/Date	Wi	nd	Visibility	Wi	nd	Visibility			
Tue 01	NW	3	POOR	Ν	2-3	POOR			
Wed 02	EXN	4	VERY POOR	NE X E	3	VERY POOR			
Thu 03	E	4	VERY POOR	NE X E	4	VERY POOR			
Fri 04	VAR	Lt Airs	VERY POOR	Ν	2	VERY POOR			
Sat 05	S	3	GOOD	S	3	GOOD			
Sun 06	SW	3-4	GOOD	SW X S	4	GOOD			
Mon 07	SE X S	2	GOOD	SE X E	2	MODERATE			
Tue 08	W	7	GOOD	W	6	GOOD			
Wed 09	SW X W	3	GOOD	SW	3	GOOD			
Thu 10	W	3	GOOD	SW	2-3	GOOD			
Fri 11	NW	3	GOOD	NW	2	GOOD			
Sat 12	SW	3	GOOD	SW	3	GOOD			
Sun 13	WSW	4	GOOD	WSW	3	GOOD			
Mon 14	WSW	3	GOOD	NW X W	3	GOOD			
Tue 15	NNW	2-3	GOOD	NW	2	GOOD			
Wed 16	W	3	GOOD	SW	2	GOOD			
Thu 17	SW	3-4	GOOD	SW	4	GOOD			
Fri 18	NXW	5-6	GOOD	NXW	3	GOOD			
Sat 19	NE	3	GOOD	NE	3	GOOD			
Sun 20	NXE	4	GOOD	N	3	GOOD			
Mon 21	EXS	4	MODERATE	NXE	2	MODERATE			
Tue 22	NE	4	GOOD	NE	4	GOOD			
Wed 23	S	3	MODERATE	S	2-3	GOOD			
Thu 24	SW	2	GOOD	SW	2	GOOD			
Fri 25	N	4-5	POOR	NNE	3	POOR			
Sat 26	S	6-7	GOOD	SE	3	GOOD			
Sun 27	E	3-4	MODERATE	E	3	GOOD			
Mon 28	VAR	Lt Airs	GOOD	VAR	Lt Airs	GOOD			
Tue 29	ESE	2	VERY POOR	ESE	1-2	POOR			
Wed 30	VAR	Lt Airs	VERY POOR	VAR	Lt Airs	MODERATE			



	Daily Weather at 07:03								
Мау									
Day/Data		Spur	n Point		King G	eorge Dock			
Day/Date	Wi	nd	Visibility	Wii	nd	Visibility			
Thu 01	EXS	3-4	MODERATE	NE X E	3	MODERATE			
Fri 02	NNE	5	GOOD	NNE	4	GOOD			
Sat 03	N	1-2	GOOD	NXW	1	GOOD			
Sun 04	SSW	3	GOOD	SSW	3	GOOD			
Mon 05	SXW	2	GOOD	SXW	1	GOOD			
Tue 06	SW	4	MODERATE	SW X S	4	MODERATE			
Wed 07	SW	3-4	GOOD	SW X W	2-3	GOOD			
Thu 08	SW	3	GOOD	WSW	4-5	GOOD			
Fri 09	SW	5	GOOD	SW	6	GOOD			
Sat 10	S	4	GOOD	S	4	GOOD			
Sun 11	W	6	GOOD	W	3	GOOD			
Mon 12	NW	4	GOOD	NW	2	GOOD			
Tue 13	N	2	GOOD	N	1-2	GOOD			
Wed 14	NW X N	3	GOOD	NW	2	GOOD			
Thu 15	W	2	GOOD	W	2	GOOD			
Fri 16	VAR	Lt Airs	GOOD	WSW	2	GOOD			
Sat 17	W	3	GOOD	WSW	2	GOOD			
Sun 18	SXE	2	GOOD	VAR	Lt Airs	GOOD			
Mon 19	E	2	GOOD	E	2	GOOD			
Tue 20	E	4	GOOD	NE	3	GOOD			
Wed 21	SW	3	MODERATE	SW	3	MODERATE			
Thu 22	N	7	GOOD	NXW	6	GOOD			
Fri 23	NE	4	GOOD	NE	4	GOOD			
Sat 24	NE	2-3	GOOD	NXE	2	GOOD			
Sun 25	SXE	4	GOOD	S	3	GOOD			
Mon 26	SSW	2-3	GOOD	SSW	3	GOOD			
Tue 27	N	4-5	GOOD	N	3-4	GOOD			
Wed 28	NXE	5	MODERATE	NE	3	GOOD			
Thu 29	ENE	4-5	MODERATE	NE	3-4	MODERATE			
Fri 30	NE	2-3	GOOD	NE	2	GOOD			
Sat 31	SSW	2	GOOD	SW	3	GOOD			



	Daily Weather at 07:03								
June									
		Spu	rn Point		King G	eorge Dock			
Day/Date	W	ind	Visibility	Wi	nd	Visibility			
Sun 01	VAR	Lt Airs	GOOD	VAR	Lt Airs	GOOD			
Mon 02	S	3-4	GOOD	S	2	GOOD			
Tue 03	S	3	GOOD	S	3	GOOD			
Wed 04	NE	2	GOOD	NNE	2	GOOD			
Thu 05	W	4	MODERATE	W	2	MODERATE			
Fri 06	SW	2-3	GOOD	SW	2-3	GOOD			
Sat 07	E	5-6	GOOD	E	3-4	GOOD			
Sun 08	SW	2	GOOD	SW	2	GOOD			
Mon 09	VAR	Lt Airs	GOOD	VAR	Lt Airs	GOOD			
Tue 10	SW	2-3	GOOD	SW	3-4	GOOD			
Wed 11	SW	3	GOOD	SW	3	GOOD			
Thu 12	WNW	1-2	GOOD	WXN	2	GOOD			
Fri 13	WNW	2	GOOD	WNW	2	GOOD			
Sat 14	NE	2	MODERATE	NNE	2	MODERATE			
Sun 15	WNW	2	GOOD	WNW	1-2	GOOD			
Mon 16	NW	4-5	GOOD	NW	3-4	GOOD			
Tue 17	NXE	5	GOOD	N	4	GOOD			
Wed 18	N	3-4	GOOD	NXW	3-4	GOOD			
Thu 19	EXN	4	GOOD	NNE	3	GOOD			
Fri 20	NNW	2	GOOD	NW X N	1-2	GOOD			
Sat 21	NW	3	GOOD	NW	3	GOOD			
Sun 22	VAR	Lt Airs	GOOD	NE	2	GOOD			
Mon 23	SSE	2	GOOD	SSE	2	GOOD			
Tue 24	ESE	3	GOOD	SE	1-2	GOOD			
Wed 25	NNW	3	GOOD	NW X W	2	GOOD			
Thu 26	NNE	2	GOOD	N	1-2	GOOD			
Fri 27	E	3-4	GOOD	ENE	3	GOOD			
Sat 28	NE	3-4	GOOD	VAR	Lt Airs	GOOD			
Sun 29	NNW	4	GOOD	NW X N	3	GOOD			
Mon 30	NW	2	GOOD	NW	2	GOOD			



Daily Weather at 07:03									
July									
		Spu	rn Point		King G	eorge Dock			
Day/Date	Wi	nd	Visibility	Wi	nd	Visibility			
Tue 01	VAR	Lt Airs	GOOD	VAR	Lt Airs	GOOD			
Wed 02	SW X S	2-3	GOOD	SW X S	3	GOOD			
Thu 03	SE	3	GOOD	WXS	2	GOOD			
Fri 04	SSW	3-4	GOOD	SSW	2	GOOD			
Sat 05	S	5	MODERATE	SXW	3-4	MODERATE			
Sun 06	ESE	4	GOOD	NE	2	GOOD			
Mon 07	SW	3	GOOD	SW	2-3	GOOD			
Tue 08	W	2	GOOD	NW	2	MODERATE			
Wed 09	NW	6-7	GOOD	NNW	4	GOOD			
Thu 10	NNW	6-7	MODERATE	NNW	5-6	MODERATE			
Fri 11	NW	3-4	GOOD	NW	1-2	GOOD			
Sat 12	N	2-3	VERY POOR	Ν	1-2	VERY POOR			
Sun 13	S	1-2	GOOD	W	Lt Airs	GOOD			
Mon 14	WNW	5	GOOD	W	2-3	GOOD			
Tue 15	W	5	GOOD	W	3	GOOD			
Wed 16	S	4	GOOD	S	3-4	GOOD			
Thu 17	WNW	Lt Airs	GOOD	W	Lt Airs	GOOD			
Fri 18	E	6	GOOD	ENE	5	GOOD			
Sat 19	SE	2	MODERATE	VAR	Lt Airs	MODERATE			
Sun 20	N	2-3	MODERATE	Ν	2	MODERATE			
Mon 21	NW	3	GOOD	NW	3	GOOD			
Tue 22	Ν	3-4	GOOD	NXW	1-2	GOOD			
Wed 23	N	4	MODERATE	NE	4	GOOD			
Thu 24	N	5	VERY POOR	NXE	3-4	GOOD			
Fri 25	N	4	VERY POOR	N	3	GOOD			
Sat 26	N	4	MODERATE	N	2-3	MODERATE			
Sun 27	WNW	4	GOOD	WNW	4	GOOD			
Mon 28	NW	2-3	GOOD	Ν	2-3	GOOD			
Tue 29	W	1-2	GOOD	SW	2	GOOD			
Wed 30	WXN	4-5	GOOD	WSW	4	GOOD			
Thu 31	SW	2-3	GOOD	SW	2	GOOD			



	Daily Weather at 07:03								
August									
Day/Date		Spur	n Point	King George Dock					
Day/Date	Wi	nd	Visibility	Wind		Visibility			
Fri 01	SSW	3	GOOD	SSW	4	GOOD			
Sat 02	SE	2-3	GOOD	SE	2	GOOD			
Sun 03	S	4	GOOD	SXW	4	GOOD			
Mon 04	WSW	3-4	GOOD	SW	3	GOOD			
Tue 05	VAR	Lt Airs	GOOD	N	2	GOOD			
Wed 06	S	4-5	GOOD	S	3	GOOD			
Thu 07	W	5	GOOD	W	4	GOOD			
Fri 08	SE	4-5	GOOD	ESE	2	GOOD			
Sat 09	W	6	GOOD	W	4	GOOD			
Sun 10	SXW	3	GOOD	SW	3	GOOD			
Mon 11	SW X W	5-6	GOOD	SW X S	6-7	GOOD			
Tue 12	SW	5-6	GOOD	SW	5	GOOD			
Wed 13	SW	4	GOOD	SW	4	GOOD			
Thu 14	W	4-5	GOOD	WXS	2-3	GOOD			
Fri 15	NNW	4	GOOD	NW	3	GOOD			
Sat 16	W	4-5	GOOD	W	2-3	GOOD			
Sun 17	WSW	4-5	GOOD	WSW	5	GOOD			
Mon 18	NW	5	GOOD	WNW	2-3	GOOD			
Tue 19	NW	4-5	GOOD	NW	3-4	GOOD			
Wed 20	W	2-3	GOOD	NW	Lt Airs	GOOD			
Thu 21	WSW	4	GOOD	WSW	4	GOOD			
Fri 22	WXN	4	GOOD	NW	3	GOOD			
Sat 23	W	4	GOOD	W	3	GOOD			
Sun 24	W	4	GOOD	W	2	GOOD			
Mon 25	S	3	GOOD	SE	3	GOOD			
Tue 26	NE	6	GOOD	NE	4	GOOD			
Wed 27	NE	3	GOOD	NNE	3	GOOD			
Thu 28	SE	4	MODERATE	SE	4	POOR			
Fri 29	S	5-6	GOOD	S	5	GOOD			
Sat 30	WXS	4	GOOD	SW	3	GOOD			
Sun 31	WNW	4-5	GOOD	W	4	GOOD			



Daily Weather at 07:03 September								
Day/Date	Wi	nd	Visibility	Wi	nd	Visibility		
Mon 01	S	2	GOOD	SW	1	GOOD		
Tue 02	NW X N	2-3	GOOD	NNW	2-3	GOOD		
Wed 03	VAR	2	GOOD	VAR	2	GOOD		
Thu 04	NXW	2-3	POOR	NE	2	GOOD		
Fri 05	N	2	GOOD	Ν	2	GOOD		
Sat 06	N	Lt Airs	POOR	VAR	Lt Airs	POOR		
Sun 07	WNW	2	MODERATE	WNW	2	GOOD		
Mon 08	W	3-4	GOOD	WXN	1-2	GOOD		
Tue 09	NW	1-2	GOOD	NW	1	GOOD		
Wed 10	SE	2	GOOD	VAR	Lt Airs	GOOD		
Thu 11	NE	2	GOOD	N	2	GOOD		
Fri 12	NXE	2-3	GOOD	N	2	GOOD		
Sat 13	NE	2	GOOD	N	2	VERY POOR		
Sun 14	NE	3	GOOD	NE	2	GOOD		
Mon 15	Ν	3	GOOD	Ν	3	GOOD		
Tue 16	NE	1-2	POOR	ENE	2	MODERATE		
Wed 17	N	3	VERY POOR	N	2	VERY POOR		
Thu 18	N	1-2	VERY POOR	N	2	VERY POOR		
Fri 19	NXE	3-4	MODERATE	Ν	2	MODERATE		
Sat 20	Ν	3	GOOD	Ν	3	GOOD		
Sun 21	NW	5	GOOD	NW	3-4	GOOD		
Mon 22	W	4	GOOD	W	4	GOOD		
Tue 23	WSW	4-5	GOOD	SW	3-4	GOOD		
Wed 24	WSW	4	GOOD	SW	3-4	GOOD		
Thu 25	SW	4-5	GOOD	WSW	3-4	GOOD		
Fri 26	SW	4	GOOD	SW	4	GOOD		
Sat 27	WSW	2	GOOD	SW X S	3	GOOD		
Sun 28	SE	2	GOOD	SE	1-2	GOOD		
Mon 29	SSE	2-3	MODERATE	VAR	Lt Airs	VERY POOR		
Tue 30	SW	3	POOR	W	3	POOR		



Daily Weather at 07:03								
October								
Day/Data		Spu	rn Point		eorge Dock			
Day/Date	Wi	nd	Visibility	Wi	nd	Visibility		
Wed 01	S	3	GOOD	S	2	GOOD		
Thu 02	NW	3	GOOD	NNW	2-3	GOOD		
Fri 03	SSW	4-5	GOOD	S	4	GOOD		
Sat 04	SXE	5-6	MODERATE	S	6	GOOD		
Sun 05	S	1-2	GOOD	SW	1-2	GOOD		
Mon 06	SSE	6	GOOD	SSE	6	GOOD		
Tue 07	SSW	1-2	MODERATE	W	1-2	POOR		
Wed 08	S	4-5	GOOD	S	4	GOOD		
Thu 09	S	5-6	GOOD	S	5	GOOD		
Fri 10	SW	4-5	GOOD	SW	4	GOOD		
Sat 11	SXW	2-3	GOOD	SW	2	GOOD		
Sun 12	WSW	2-3	GOOD	W	2	GOOD		
Mon 13	NE	6	GOOD	NNE	4	GOOD		
Tue 14	NXE	5-6	GOOD	NXE	5-6	GOOD		
Wed 15	NNE	4	GOOD	NNE	4	GOOD		
Thu 16	ESE	3-4	GOOD	EXS	3	GOOD		
Fri 17	SSW	3	GOOD	SSW	3	GOOD		
Sat 18	S	7	GOOD	SSE	6-7	GOOD		
Sun 19	SSW	4	GOOD	SSW	5	GOOD		
Mon 20	WSW	4	GOOD	SW	4	GOOD		
Tue 21	SSW	6-7	GOOD	SSW	6	GOOD		
Wed 22	WXS	5	GOOD	WXN	3-4	GOOD		
Thu 23	SW X S	4-5	GOOD	SXW	4	GOOD		
Fri 24	SXW	3	GOOD	S	3	GOOD		
Sat 25	SW	3	GOOD	SW	3	GOOD		
Sun 26	SXW	4-5	GOOD	SW X S	6	GOOD		
Mon 27	S	4	GOOD	SSW	5	GOOD		
Tue 28	SXW	6	GOOD	SXW	5	GOOD		
Wed 29	NE X N	3-4	GOOD	NXW	3	GOOD		
Thu 30	SE X S	4	POOR	SE X S	4	POOR		
Fri 31	S	3-4	POOR	SSW	4	MODERATE		



	Daily Weather at 07:03 November								
		Spu	rn Point		King G	eorge Dock			
Day/Date	Wi	ind	Visibility	Wi	nd	Visibility			
Sat 01	SXW	3-4	GOOD	SW	4-5	GOOD			
Sun 02	SSW	5-6	GOOD	SSW	5	GOOD			
Mon 03	S	5-6	GOOD	SW X S	6	GOOD			
Tue 04	SW	3-4	GOOD	SW	2	MODERATE			
Wed 05	NXE	5	GOOD	NNW	3-4	GOOD			
Thu 06	SW	2-3	GOOD	SW	1-2	MODERATE			
Fri 07	SSE	7-8	MODERATE	SSE	6	MODERATE			
Sat 08	SSW	4	GOOD	SSW	4	GOOD			
Sun 09	WSW	2	GOOD	WSW	2	GOOD			
Mon 10	S	4-5	GOOD	S	3-4	GOOD			
Tue 11	SE	6-7	GOOD	SE	5	GOOD			
Wed 12	SE	5	GOOD	SE	3	GOOD			
Thu 13	SSE	4-5	GOOD	SSE	4	GOOD			
Fri 14	ESE	7-8	GOOD	SE	6	GOOD			
Sat 15	ESE	2	VERY POOR	VAR	Lt Airs	VERY POOR			
Sun 16	EXN	2	GOOD	NE	1	GOOD			
Mon 17	ESE	5	GOOD	ENE	4	GOOD			
Tue 18	E	4	GOOD	NE	2-3	GOOD			
Wed 19	E	3-4	GOOD	ENE	3	GOOD			
Thu 20	ESE	2	GOOD	NE	1	GOOD			
Fri 21	SE	4	GOOD	SE	3	GOOD			
Sat 22	S	4	GOOD	SSE	3	GOOD			
Sun 23	W	4-5	GOOD	WNW	3-4	GOOD			
Mon 24	WXS	4	GOOD	WSW	4	GOOD			
Tue 25	S	2	GOOD	SW	1-2	GOOD			
Wed 26	E	5	GOOD	E	4	GOOD			
Thu 27	SE	3	MODERATE	SE	2	POOR			
Fri 28	E	4	MODERATE	E	3	MODERATE			
Sat 29	ESE	5-6	MODERATE	E	4	MODERATE			
Sun 30	W	3-4	GOOD	WXS	3	GOOD			



Daily Weather at 07:03									
December									
		Spu	rn Point		King G	eorge Dock			
Day/Date	Wi	nd	Visibility	Wi	nd	Visibility			
Mon 01	NNE	3	GOOD	NE	2-3	GOOD			
Tue 02	Ν	6-7	MODERATE	NNW	5	MODERATE			
Wed 03	NE	3-4	GOOD	NNW	3	GOOD			
Thu 04	E	4-5	GOOD	EXN	3	GOOD			
Fri 05	WNW	3-4	GOOD	W	2	GOOD			
Sat 06	W	4	GOOD	WNW	3-4	GOOD			
Sun 07	SW	5	GOOD	SW	5-6	GOOD			
Mon 08	WSW	3-4	GOOD	SW	3-4	GOOD			
Tue 09	SW	3	GOOD	SW	3	GOOD			
Wed 10	W	7	GOOD	W	4	GOOD			
Thu 11	WSW	7	GOOD	WSW	6	GOOD			
Fri 12	NW X W	5	GOOD	NW	3	GOOD			
Sat 13	WXN	3-4	GOOD	WSW	2	GOOD			
Sun 14	SSW	6-7	GOOD	SXW	6	GOOD			
Mon 15	WXS	3-4	GOOD	SW	3	GOOD			
Tue 16	WXS	4	GOOD	SW	3	GOOD			
Wed 17	W	6-7	GOOD	W	5	GOOD			
Thu 18	SW	5-6	GOOD	SW	4	GOOD			
Fri 19	W	6	GOOD	W	4	GOOD			
Sat 20	W	5-6	GOOD	WXS	5	GOOD			
Sun 21	SSW	4	GOOD	SSW	4	GOOD			
Mon 22	SW	7	GOOD	SW	5-6	GOOD			
Tue 23	SW	6	GOOD	SW	4-5	GOOD			
Wed 24	WXN	5-6	GOOD	W	3-4	GOOD			
Thu 25	W	4-5	GOOD	W	4-5	GOOD			
Fri 26	SW	2-3	GOOD	SW	2	GOOD			
Sat 27	NNW	6-7	GOOD	NNW	4	GOOD			
Sun 28	NE	3-4	GOOD	NW	2	GOOD			
Mon 29	NW	4-5	GOOD	NW	3	GOOD			
Tue 30	SW	4	GOOD	SW	4	GOOD			
Wed 31	SW	3-4	GOOD	WSW	3	GOOD			