
NOTICE TO MARINERS

No. H. 120/2023

HUMBER APPROACHES

SPURN LIGHT FLOAT TEMPORARY REPLACEMENT

MARINERS ARE ADVISED that the Spurn Light Float has been removed from station for routine maintenance. Until further notice, a monohull East Cardinal Light Float displaying the same characteristics is being used as a temporary replacement in its charted position (see details below):

- East Cardinal Light Float (monohull)
- Light Characteristics – Q(3)10s
- Position – 53° 33.417' N, 0° 14.148' E (WGS84)
- No Racon is present
- No Name Board is Present

MARINERS ARE FURTHER ADVISED to navigate with caution in this vicinity.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

12th September 2023

LOCAL NOTICE TO MARINERS FOR 2020, 2021, 2022 & 2023 CURRENTLY IN FORCE:

H. 43/2020, H. 07/2021, H. 43/2021, H. 92/2021, H. 109/2021, H. 08/2022, H. 28/2022, H. 68/2022, H. 75/2022, H. 131/2022, H. 02/2023, H. 50/2023, H. 52/2023, H. 61/2023, H. 70/2023, H. 72/2023, H. 73/2023, H. 76/2023, H. 78/2023, H. 82/2023, H. 83/2023, H. 84/2023, H. 89/2023, H. 94/2023, H. 97/2023, H. 99/2023, H. 100/2023, H. 103/2023, H. 104/2023, H. 105/2023, H. 111/2023, H. 112/2023, H. 116/2023, H. 118/2023, H. 119/2023, H. 120/2023.

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com