
NOTICE TO MARINERS

No. H. 47/2021

H U M B E R A P P R O A C H E S

HORNSEA OFFSHORE WIND FARM – CABLE REMEDIAL WORKS – OUTBOUND TRAFFIC SEPARATION SCHEME OBSTRUCTIONS AND RESTRICTIONS

NOTICE IS HEREBY GIVEN that commencing on 19th March 2021 (or as soon after as circumstances permit) and continuing for a period of approximately three weeks, cable remedial works will be undertaken on the Hornsea Offshore Wind Farm northern cable which will result in the placement of two anchors up to 100 metres into the outbound lane close to the No.2 Haile Sand Buoy.

The works in this area will be carried out by the following vessels: -

Vessel Name	LOA (m)	Call Sign	Vessel Type
Boka Barge 82	137.00	5BY4U	Cable Repair
Coastal Vanguard	32.27	PCFH	AHT
Voë Vanguard	33.18	MBEN	AHT
Lingestroom	34.75	PICW	AHT

The cable repair vessel '**BOKA BARGE 82**' will be secured south of the TSS using an eight point anchor spread.

The operation will have guard vessels '**COASTAL VANGUARD**', '**VOE VANGUARD**', and '**LINGESTROOM**' marking the limits of the operational area. These vessels will be transmitting regular broadcasts to vessels on VHF channel 16.

The vessels listed above will liaise closely with VTS Humber during the campaign, advising when vessels intend to move and any operations that are ongoing. They will exhibit the lights and shapes prescribed by the International Regulations for Preventing Collisions at Sea and will maintain a listening watch on VHF Channels 16 and 14.

MARINERS ARE REQUESTED that due to the limited manoeuvrability of the cable repair vessel and the extension of the anchor spread, vessels should give as wide a berth as possible. Additionally, mariners are advised to pass at a reduced speed to avoid creating a wash.

The anchor positions are detailed below and will be marked with lit pendant buoys in the following positions.

ANCHOR ID	LATITUDE	LONGITUDE
1	53° 32.019 N	0° 12.162 E
2-1	53° 32.168 N	0° 12.100 E
2	53° 32.218 N	0° 12.121 E
3	53° 32.274 N	0° 12.289 E
4	53° 32.275 N	0° 12.373 E
5	53° 32.197 N	0° 13.035 E
6A	53° 32.167 N	0° 13.120 E
6B	53° 32.074 N	0° 13.193 E
7	53° 31.485 N	0° 12.579 E
8	53° 31.537 N	0° 12.468 E

MARINERS ARE ADVISED that anchors 3 and 4 encroach the south side of the outbound TSS lane by up to 100 metres.

**CAPT. A FIRMAN
HARBOUR MASTER, HUMBER**

18th March 2021

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com