

---

# NOTICE TO MARINERS

---

No. H. 55/2024

## U P P E R H U M B E R

### SHOAL WATER

**MARINERS ARE WARNED** that a survey carried out on the 13<sup>th</sup> May 2024 shows the following: -

- 1) A least depth of 2.0 metres **ABOVE** Chart Datum exists North of the ships course 340 metres downstream of the Lower Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

- 2) Depths of between 0 metres at Chart Datum to 0.3 metres **ABOVE** Chart Datum exists North of the ships course from 70 metres upstream of the No.32A Light Float to 230 metres downstream of the No. 31 Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 3) A least depth of 1.1 metres **ABOVE** Chart Datum exists North of the ships course 320 metres upstream of the No. 33 Light Float.

Deeper water exists on the ships course in this vicinity.

- 4) Depths of between 0 metres at Chart Datum to 0.4 metres **ABOVE** Chart Datum exists North of the ships course from 340 metres upstream of the No.32C Light Buoy to 450 metres downstream of the No.34 Light Buoy.

Deeper water exists on the ships course in this vicinity.

**MARINERS ARE ADVISED** that 0 metres at Chart Datum should be used for passage planning purposes and that the shoal water referred to in Notice to Mariners No. H. 48/2024 is no longer valid.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

13<sup>th</sup> May 2024