

NOTICE TO MARINERS

No. H. 115/2020

HUMBER APPROACHES

WRECKS

MARINERS ARE WARNED that multibeam surveys carried out during 2020 have found the following:

1. A wreck with a least depth of 10.3 metres below Chart Datum exists 431 metres South West of the Bull Light Float, in Anchor location "K":

Latitude 53° 33.351' N Longitude 000° 5.465' E (WGS 84)

2. A wreck with a least depth of 16.8 metres below Chart Datum exists 842 metres South East of the Delta Light Buoy, in the outward bound traffic separation lane:

Latitude 53° 33.277' N Longitude 000° 7.750' E (WGS 84)

MARINERS ARE ADVISED to navigate with caution in this area.

CAPT. A. FIRMAN HARBOUR MASTER, HUMBER

14th August 2020

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.