

---

# NOTICE TO MARINERS

---

No. H. 132/2020

## U P P E R H U M B E R

### SHOAL WATER

**MARINERS ARE WARNED** that a survey carried out on the 21<sup>st</sup> September 2020 show the following: -

- 1) A least depth of 0.5 metres **ABOVE** Chart Datum exists North of the ships course 345 metres downstream of the Lower Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

- 2) A least depth of 0.3 metres **ABOVE** Chart Datum exists South of the ships course from the Upper Whitton Light Float to the No. 32C Light Float.

Deeper water exists on and to the North of the ships course in this vicinity.

- 3) A least depth of 0.9 metres **ABOVE** Chart Datum exists South of the ships course 210 metres upstream of the No. 32C Light Buoy.

Deeper water exists on and to the North of the ships course in this vicinity.

**MARINERS ARE ADVISED** that 0 metres at Chart Datum should be used for passage planning purposes and Notice to Mariners No. H.128/2020 is hereby cancelled.

**CAPT. A. FIRMAN**  
**HARBOUR MASTER, HUMBER**

21<sup>st</sup> September 2020

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)