
NOTICE TO MARINERS

No. H. 142/2020

HUMBER APPROACHES

NORTH BINKS BUOY – RETURNED TO STATION

MARINERS ARE ADVISED that the North Binks Buoy has been returned to station in its original charted position:

Latitude: 53° 36.017' N Longitude: 0° 18.295' E

Characteristics: Fl.G.4s

MARINERS ARE FURTHER ADVISED that Notice to Mariners No. H. 135/2020 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

10th October 2020

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com