
NOTICE TO MARINERS

No. H. 131/2022

HUMBER APPROACHES

MID NEW SAND BUOY – PERMANENT REPLACEMENT

MARINERS ARE ADVISED that with immediate effect, the Mid New Sand West Cardinal Buoy has been permanently replaced with a Port Hand Lateral Mark in its charted position as follows: -

- Red Can Buoy
- Light Characteristic – Q.R
- Position – 53° 36.720'N, 0° 21.201'E (WGS84)

MARINERS ARE FURTHER ADVISED that Notice to Mariners No. H. 67/2020 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

13th September 2022

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com