
NOTICE TO MARINERS

No. H. 166/2020

R I V E R H U M B E R

HULL – KING GEORGE – EASTERN APPROACH JETTY REPAIR WORKS

MARINERS ARE WARNED that due to necessary repair works **THE EASTERN APPROACH JETTY TO KING GEORGE DOCK SHOULD NOT BE USED** until further notice.

MARINERS ARE REQUESTED to contact the Assistant Dock Master on VHF CH11 prior to transiting the lock and to make any approach to King George Dock via the Western Approach Jetty.

Small craft wishing to use Fell's Landing for boarding and landing should seek the permission of the Assistant Dock master in advance.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

3rd December 2020

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com