
NOTICE TO MARINERS

No. H. 17/2025

RIVER HUMBER

BULL CHANNEL - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 29th January 2025 shows the following:-

- 1) Depths of between 3.3 metres and 5.5 metres below Chart Datum have encroached up to 370 metres into the Southern edge of the channel, from 1020 metres upstream of the Bull Light Float (North Cardinal) to 355 metres downstream of the Bull Sand Light Buoy.

Deeper water exists to the North in this vicinity.

- 2) A shoal with depths of between 3.3 metres and 5.5 metres below Chart Datum extends from 1020metres upstream of the Bull Light Float (North Cardinal) to 230 metres upstream of the Bull Sand Light Buoy.

MARINERS ARE ADVISED that Notice to Mariners No. H. 118/2024 is hereby cancelled.

**CAPT. A. FIRMAN.
HARBOUR MASTER, HUMBER**

30th January 2025

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com