
NOTICE TO MARINERS

No. H. 24/2021

RIVER OUSE


GOOLE DOCKS – SOUTH DOCK SUBMERGED
OBSTRUCTIONS

MARINERS ARE WARNED that submerged and partially submerged obstructions exist as the result of a recently collapsed dock wall in South Dock, Goole. The area of obstruction extends out into the dock approximately five metres from the original wall face for a length of 40 metres.

The obstruction consists of large baulks of timber protruding vertically from the riverbed, which were previously the foundations of the wall, and as such could pose a significant hazard to any vessel navigating in the area. The obstructions will be marked as soon as possible with yellow unlit buoys.

MARINERS ARE REQUESTED to remain to the south of the dock wall and marker buoys (once in position) and to pass the area at slow speed giving a wide berth.

MARINERS ARE ADVISED that works to repair the wall and remove the obstructions will be carried out as soon as is practicable.



CAPT. A FIRMAN HARBOUR MASTER, HUMBER

12th February 2021

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com