

---

# NOTICE TO MARINERS

---

No. H. 28/2025

## RIVER HUMBER

### HALTON MIDDLE - SHOAL WATER

**MARINERS ARE WARNED** that surveys carried out between the 26<sup>th</sup> and 27<sup>th</sup> February 2025 show the following: -

- 1) Depths of between 5.1 metres and 5.5 metres below Chart Datum have encroached up to 105 metres into the Eastern edge of the channel from 498 metres downstream to 672 metres upstream of the No. 15A Light Buoy.  
Deeper water exists to the West in this vicinity.
- 2) Depths of between 5.2 metres and 5.5 metres below Chart Datum have encroached up to 30 metres into the Western edge of the channel from 836 metres upstream to 228 metres downstream of the No. 14 Skitter Haven Light Buoy.  
Deeper water exists to the East in this vicinity.

**MARINERS ARE ADVISED** that 5.5 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 140/2024 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

28<sup>th</sup> February 2025

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)