

---

# NOTICE TO MARINERS

---

**No. H. 29/2025**

**RIVER HUMBER**  
**GRIMSBY MIDDLE - SHOAL WATER**

**MARINERS ARE WARNED** that a survey carried out on the 28<sup>th</sup> February 2025 shows the following: -

- 1) Depths of less than 6.4 metres below Chart Datum have encroached up to 60 metres into the Northern edge of the navigation channel from the No. 5A Light Buoy to 215 metres upstream of the No. 5A Light Buoy.

Deeper water exists to the South in this vicinity.

- 2) Depths of less than 6.4 metres below Chart Datum have encroached up to 65 metres into the Southern edge of the navigation channel from 400 metres upstream of the No. 4A Clee Ness Light Float to 350 metres downstream of the No. 4B Light Buoy.

Deeper water exists to the North in this vicinity.

- 3) Depths of less than 6.4 metres below Chart Datum have encroached up to 85 metres into the Southern edge of the navigation channel from 60 metres upstream of the No. 6 Lower Burcom Light Float to 920 metres downstream of the Pyewipe Outfall Light Buoy.

Deeper water exists to the North in this vicinity.

- 4) Depths of less than 6.4 metres below Chart Datum have encroached up to 55 metres into the Southern edge of the navigation channel from 470 metres to 700 metres upstream of the Pyewipe Outfall Light Buoy.

Deeper water exists to the North in this vicinity.

**MARINERS ARE ADVISED** that Notice to Mariners No. H. 112/2024 is hereby cancelled.

**CAPT. A. FIRMAN**  
**HARBOUR MASTER, HUMBER**

3<sup>rd</sup> March 2025

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)