

---

# NOTICE TO MARINERS

---

No. H. 36/2025

## RIVER HUMBER

### HUMBER LIGHT FLOAT TEMPORARY REPLACEMENT

**MARINERS ARE ADVISED** that the Humber Light Float has been replaced with a temporary floating mark, until further notice. A Green conical buoy is being used as a temporary replacement in its original charted position as follows

- Position – 53° 38.700' N 0° 21.240' E
- Light Characteristic – LFl.G.10s
- Green conical buoy (lateral)

**MARINERS ARE FURTHER ADVISED** that Notice to Mariners No. H.32/2025 is hereby cancelled

**CAPT. A. FIRMAN**  
**HARBOUR MASTER, HUMBER**

16<sup>th</sup> March 2025

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.  
[www.humber.com](http://www.humber.com)