

NOTICE TO MARINERS

No. H. 67/2025

R I V E R H U M B E R

SKITTER CHANNEL

SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 20th and 22nd May 2025 shows the following: -

- 1) A least depth of 1.8 metres below chart datum exists close South of the ships course 365 metres upstream of the No. 20A Light Buoy.

Deeper water exists on the ships course in this vicinity.

- 2) A least depth of 1.7 metres below chart datum exists South of the ships course 460 metres upstream of the No. 21B Light Buoy.

Deeper water exists on the South of ships course in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 20/2025 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

22nd May 2025

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com