
NOTICE TO MARINERS

No. H. 90/2022

RIVER HUMBER

FOUL HOLME CHANNEL - SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 27th to 28th April and 10th June 2022 show the following: -

A least depth of 0.9 metres below Chart Datum exists on the Eastern edge of the channel 230 metres upstream of the FH3 Light Buoy.

Deeper water exists to the West in this vicinity.

MARINERS ARE ADVISED that 0.5 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 60/2022 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

10th June 2022

LOCAL NOTICE TO MARINERS FOR 2019, 2020, 2021 & 2022 CURRENTLY IN FORCE:

H. 27/2019, H. 43/2020, H. 67/2020, H. 68/2020, H. 160/2020, H. 02/2021, H. 07/2021, H. 24/2021, H. 43/2021, H. 64/2021, H. 92/2021, H. 109/2021, H. 133/2021, H. 178/2021, H. 179/2021, H. 08/2022, H. 12/2022, H. 19/2022, H. 22/2022, H. 27/2022, H. 28/2022, H. 37/2022, H. 43/2022, H. 50/2022, H. 52/2022, H. 54/2022, H. 59/2022, H. 64/2022, H. 65/2022, H. 67/2022, H. 68/2022, H. 71/2022, H. 75/2022, H. 76/2022, H. 79/2022, H. 80/2022, H. 82/2022, H. 83/2022, H. 84/2022, H. 87/2022, H. 88/2022, H. 89/2022, H. 90/2022.

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com