

# NOTICE TO MARINERS

---

No. H. 38/2026

## RIVER HUMBER

### SKITTER CHANNEL

### SHOAL WATER

**MARINERS ARE WARNED** that surveys carried out on the 13<sup>th</sup> and 16<sup>th</sup> March 2026 show the following: -

- 1) A Least depth of 1.2 metres below chart datum exists South of the ships course from 1040 metres to 1150 metres downstream of the Hull Middle Light Buoy.

Deeper water exists on the ships course in this vicinity.

- 2) A least depth of 1.2 metres below chart datum exists South of the ships course 470 metres upstream of the No. 21B Light Buoy.

Deeper water exists on the ships course in this vicinity.

- 3) A least depth of 1.5 metres below chart datum exists South of the ships course 1090 metres upstream of the No. 21B Light Buoy.

Deeper water exists on the ships course in this vicinity.

**MARINERS ARE ADVISED** that Notice to Mariners No. H. 170/2025 is hereby cancelled.

**CAPT. A. FIRMAN**  
**HARBOUR MASTER, HUMBER**

16<sup>th</sup> March 2026

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.  
[www.humber.com](http://www.humber.com)