

NOTICE TO MARINERS

No. H. 20/2025

RIVER HUMBER

SKITTER CHANNEL

SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 7th February 2025 shows the following: -

1) A least depth of 1.3 metres below chart datum exists South of the ships course 460 metres upstream of the No. 21B Light Buoy.

Deeper water exists on the ships course in this vicinity.

2) A least depth of 0.1 metres **ABOVE** chart datum exists North of the ships course 700 metres upstream of the No. 21B Light Buoy.

Deeper water exists on and to the South of ships course in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 132/2024 is hereby cancelled.

CAPT. A. FIRMAN HARBOUR MASTER, HUMBER

10th February 2025

LOCAL NOTICE TO MARINERS FOR 2021, 2022, 2023, 2024 & 2025 CURRENTLY IN FORCE:

H. 07/2021, H. 43/2021, H. 92/2021, H. 109/2021, H. 28/2022, H. 131/2022, H. 52/2023, H. 104/2023, H. 112/2023, H. 17/2024, H. 20/2024, H. 48/2024, H. 63/2024, H.72/2024, H.76/2024, H.83/2024, H. 86/2024, H.91/2024, H.108/2024, H.109/2024, H.110/2024, H. 112/2024, H. 117/2024, H. 130/2024, H. 136/2024, H. 140/2024, H. 148/2024, H. 149/2024, H. 151/2024, H. 01/2025, H. 02/2025, H. 05/2025, H. 06/2025, H. 07/2025, H. 09/2025, H. 10/2025, H. 11/2025, H. 12/2025, H. 14/2025, H. 15/2025, H. 17/2025, H. 18/2025, H. 19/2025 and H. 20/2025.

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com