

---

# NOTICE TO MARINERS

---

**No. H. 42/2021**

## R I V E R H U M B E R

### HAWKE LIGHT FLOAT REPLACEMENT – SIGNIFICANT CHANGE OF CHARACTERISTICS

**NOTICE IS HEREBY GIVEN** that on Wednesday 17<sup>th</sup> March, or as soon after as circumstances permit, the Hawke Light Float will be permanently replaced with a significant change of characteristics in the same charted position as the original float as follows:

Latitude: 53° 34.549' ' N    Longitude: 0° 05.545' E

New Characteristics:    FI G (2+1) 6s  
                                  Light Float GRG  
                                  Preferred channel to port

The following characteristics of the Hawke Light Float are discontinued:

Previous Characteristics: V Q (3) 5s  
                                  Lt Float BYB  
                                  Cardinal E

**MARINERS ARE ADVISED** that Notice to Mariners No. H. 25/2021 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

17<sup>th</sup> March 2021

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.