
NOTICE TO MARINERS

No. H. 83/2024

RIVER HUMBER

**GRIMSBY MIDDLE DEPOSIT
SHOAL WATER**

MARINERS ARE WARNED that surveys carried out on the 2nd & 3rd July 2024 show the following: -

A shoal with a least depth of 1.2 metres below Chart Datum exists in the South-East corner of the Grimsby Middle deposit spoil ground, from 300 metres upstream of the P6 Light Buoy to 450 metres upstream of the P7 Light Buoy.

MARINERS ARE ADVISED that depths within spoil grounds are inevitably subject to change and should therefore proceed with caution in these areas. In addition, Notice to Mariners No. H. 31/2024 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

5th July 2024

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com