
NOTICE TO MARINERS

No. H. 09/2025

R I V E R H U M B E R

NEW HOLLAND DOCK ENTRANCE - REMOVAL OF EASTERN BULLNOSE AND RELOCATION OF NAVIGATION LIGHTS

MARINERS ARE ADVISED that following removal of the eastern bullnose at the entrance to New Holland Dock as outlined in Notice to Mariners No. 28/2024, the navigation lights at the eastern entrance to the Dock have been relocated with the same characteristics as follows:

Old Position

Latitude 53° 42.337 N Longitude 0° 21.720 W
2F.R (vert)(occas)

New Position

Latitude 53° 42.339' N Longitude 0° 21.717' W
2F.R(vert)(occas)

MARINERS ARE FURTHER ADVISED That Notice to Mariners No. 28/2024 is hereby cancelled.

**CAPT. A. FIRMAN.
HARBOUR MASTER, HUMBER**

13th January 2025

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com