

## **NOTICE TO MARINERS**

No. H. 186/2022

## RIVER HUMBER BURCOM DEPOSIT - SHOAL WATER

**MARINERS ARE WARNED** that a survey carried out on the 22<sup>nd</sup> December 2022 shows the following: -

Depths of between 2.1 metres and 5.5 metres below Chart Datum have encroached up to 50 metres into the Southern edge of the channel from 350 metres to 570 metres downstream of the No. 8 Middle Burcom Light buoy.

Deeper water exists to the North in this vicinity.

**MARINERS ARE ADVISED** that Notice to Mariners No. H. 145/2022 is hereby cancelled.

CAPT. A. FIRMAN HARBOUR MASTER, HUMBER

22<sup>nd</sup> December 2022

## THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.