
NOTICE TO MARINERS

No. H. 23/2021

RIVER TRENT

OBSTRUCTION

MARINERS ARE WARNED that an obstruction has been identified in the River Trent downstream of Susworth, roughly one quarter of the way into the river from the East bank in approximate position: -

- 53° 31.182 N, 00° 44.349 W (WGS84) See also attached chartlet.

The obstruction appears to be a large baulk of timber wedged on-end into the river bed and as such could pose a significant hazard to any vessel navigating in the area. With a height of approximately 3.5 metres **ABOVE** chart datum the obstruction could either be exposed or beneath the water line depending on the state of tide.

MARINERS ARE ADVISED that Deeper water exists to the Western side of the river in this vicinity, however, extreme care and cation should be observed whilst navigating in this area.

MARINERS ARE FURTHER ADVISED that works to remove the obstruction will be carried out as soon as is practicable.

**CAPT. A FIRMAN
HARBOUR MASTER, HUMBER**

10th February 2021

