

NOTICE TO MARINERS

No. H. 31/2021

RIVER HUMBER

HESSLE SAND - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 2nd March 2021 shows the following: -

- 1) A least depth of 0.3 metres below Chart Datum exists on the ships course from 700 metres to 750 metres upstream of the No. 28 Light Buoy.

Deeper water exists to the South of the ships course in this vicinity.

- 2) A least depth of 0.2 metres below Chart Datum exists close North of the ships course from 300 metres to 450 metres downstream of the No. 23 Light Buoy.

Deeper water exists on and to the South of the ships course in this vicinity.

- 3) Depths of between 0 metres at Chart Datum and 0.6 metres **ABOVE** Chart Datum exist North of the ships course from 550 metres downstream to 160 metres upstream of the No. 23 Light Buoy.

Deeper water exists on and to the South of the ships course in this vicinity.

MARINERS ARE ADVISED that 0.6 metres **ABOVE** Chart Datum should be used for passage planning purposes and Notices to Mariners H. 170/2020 is hereby cancelled.

CAPT. A FIRMAN
HARBOUR MASTER, HUMBER

2nd March 2021

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com