

---

# **NOTICE TO MARINERS**

---

**No. H.32/2021**

## **RIVER HUMBER**

### **BULL CHANNEL - SHOAL WATER**

**MARINERS ARE WARNED** that a survey carried out on the 4<sup>th</sup> March 2021 shows the following:-

A shoal of between 2.4 metres and 5.5 metres below Chart Datum extends from 840 metres downstream to 1920 metres upstream of the North Fort Cardinal Buoy.

**MARINERS ARE ADVISED** that Notice to Mariners No. H. 123/2020 is hereby cancelled.

**CAPT. A. FIRMAN.  
HARBOUR MASTER, HUMBER**

4<sup>th</sup> March 2021

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)