

---

# **NOTICE TO MARINERS**

---

**No. H. 35/2025**

## **RIVER HUMBER**

### **HULL ROADS – EAST MIDDLE - SHOAL WATER**

**MARINERS ARE WARNED** that a survey carried out on the 14<sup>th</sup> March 2025 shows the following: -

- 1) Depths of between 4 metres and 5.5 metres below Chart Datum have encroached up to 25 metres into the Northern edge of the channel from 150 metres downstream to 405 metres upstream of the No. 21 Hebbles Light Buoy.

Deeper water exists to the South in this vicinity.

- 2) Depths of between 4.9 metres and 5.5 metres below Chart Datum have encroached up to 55 metres into the Southern edge of the channel from 100 metres downstream to 455 metres upstream of the East Middle Light Buoy.

Deeper water exists to the North in this vicinity.

- 3) Depths of between 4.3 metres and 5.5 metres below Chart Datum have encroached up to 130 metres into the Southern edge of the channel from 570 metres upstream of the No. 22 Hook Light Buoy to 80 metres upstream of the No. 24 Lower West Middle Light Buoy.

Deeper water exists to the North in this vicinity.

**MARINERS ARE ADVISED** that Notice to Mariners No. H. 11/2025 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

14<sup>th</sup> March 2025

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)