
NOTICE TO MARINERS

No. H. 52/2024

RIVER HUMBER

FOUL HOLME CHANNEL - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 7th May 2024 shows the following: -

- 1) Depths of less than 1.9 metres below Chart Datum have encroached up to 95 metres into the Eastern edge of the channel from 100 metres to 210 metres upstream of the FH3 Light Buoy.

Deeper water exists to the West in this vicinity.

- 2) A least depth of 2 metres below Chart Datum exists on the Eastern edge of the channel 700 metres downstream of the FH5 Light Buoy.

Deeper water exists to the West in this vicinity.

- 3) Depths of less than 1.9 metres below Chart Datum exists on the Eastern edge of the channel from 230 metres to 480 metres upstream of the FH7 Light Buoy.

Deeper water exists to the West in this vicinity.

MARINERS ARE ADVISED that 1.5 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 19/2024 is hereby cancelled.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

9th May 2024

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com