
NOTICE TO MARINERS

No. H. 59/2021

RIVER HUMBER

HULL ROADS – EAST MIDDLE - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 6th April 2021 shows the following: -

- 1) Depths of between 4.8 metres and 5.5 metres below Chart Datum have encroached up to 38 metres into the Southern edge of the channel from 50 metres to 505 metres upstream of the East Middle Light Buoy.

Deeper water exists to the North in this vicinity.

- 2) Depths of between 4.4 metres and 5.5 metres below Chart Datum have encroached up to 80 metres into the Southern edge of the channel from 370 metres upstream of the No. 22 Hook Light Buoy to the No. 24 Lower West Middle Light Buoy.

Deeper water exists to the North in this vicinity.

- 3) Depths of between 4.9 metres and 5.5 metres below Chart Datum have encroached up to 5 metres into the Northern edge of the channel from the No. 21 Hebbles Light Buoy to 120 metres downstream of the No. 21 Hebbles Light Buoy.

Deeper water exists to the South in this vicinity

MARINERS ARE ADVISED that Notice to Mariners No. H. 09/2021 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

7th April 2021

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com