

NOTICE TO MARINERS

No. H. 62/2021

RIVER HUMBER

FOUL HOLME CHANNEL - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 7th and 8th April 2021 shows the following: -

A least depth of 0.8 metres below Chart Datum exists on the Eastern edge of the channel 365 metres upstream of the FH3 Light Buoy.

Deeper water exists to the West in this vicinity.

MARINERS ARE ADVISED that 0.5 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 168/2020 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

8th April 2021

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com