
NOTICE TO MARINERS

No. H. 71/2025

RIVER HUMBER

HULL ROADS – EAST MIDDLE - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 2nd June 2025 shows the following: -

- 1) Depths of between 3.8 metres and 5.5 metres below Chart Datum have encroached up to 30 metres into the Northern edge of the channel from 390 metres downstream to 425 metres upstream of the No. 21 Hebbles Light Buoy.

Deeper water exists to the South in this vicinity.

- 2) Depths of between 4.9 metres and 5.5 metres below Chart Datum have encroached up to 56 metres into the Southern edge of the channel from 95 metres downstream to 480 metres upstream of the East Middle Light Buoy.

Deeper water exists to the North in this vicinity.

- 3) Depths of between 4.1 metres and 5.5 metres below Chart Datum have encroached up to 133 metres into the Southern edge of the channel from 711 metres upstream of the No. 22 Hook Light Buoy to 410 metres upstream of the No. 24 Lower West Middle Light Buoy.

Deeper water exists to the North in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 35/2025 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

3rd June 2025

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com