

NOTICE TO MARINERS

No. H. 87/2024

RIVER HUMBER

SKITTER CHANNEL

SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 15th and 16th July 2024 show the following: -

- 1) A least depth of 1.5 metres below chart datum exists South of the ships course from 450 metres upstream of the No. 21B Light Buoy to 630 metres Downstream of the No. 22A Light Buoy.

Deeper water exists on the ships course in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 54/2024 is hereby cancelled.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

17th July 2024

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com