

# **NOTICE TO MARINERS**

---

**No. H. 27/2026**

## **RIVER HUMBER**

### **FOUL HOLME CHANNEL - SHOAL WATER**

**MARINERS ARE WARNED** that a survey carried out on the 17<sup>th</sup> and 19<sup>th</sup> February shows the following: -

- 1) Depths of between 1.9 metres and 2.0 metres below Chart Datum exist on the Eastern edge of the channel from 25 metres to 210 metres downstream of the FH3 Light Buoy.

Deeper water exists to the West in this vicinity.

- 2) Depths of between 1.6 metres and 2.0 metres below Chart Datum exist on the Eastern edge of the channel from 100 metres downstream of the FH7 Light Buoy to 25 metres downstream of the of the FH9 Light Buoy.

Deeper water exists to the West in this vicinity.

**MARINERS ARE ADVISED** that 1.5 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 141/2025 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

20<sup>th</sup> February 2026

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)